

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 07 Jan 2020

## **Preliminary Advice**

Vehicle No	: SJC2123G	Accident Date	: 04/01/2020
Make	: AUDI Q7	Policy No.	: 999994048/100878162-00009
Assignment Date	: 07/01/2020	Excess	: S\$0.00
Date of Inspection	: 07/01/2020	Est. Duration of Repair	: 7 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,201.00
Revised Amount	:S\$	6,835.00
Check Items (Estimated)	:S\$	453.00
Total	:S\$	7,288.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	244,000.00
COE / PARF Rebate	:S\$	97,807.00
Salvage Value	:S\$	
Margin for Repair	:S\$	146,193.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :