

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25291

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0014/2020/NS
Date : 07-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Premium Automobiles Pte Ltd
Address : 55 Ubi Road 1
Singapore 408699
Telephone : HP +65 66900293
Type of Claim : Own Damage Claims
Policy No. : 999994048/100878162-00009
Vehicle No : **SJC 2123 G**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Aug-19
Engine No : CYR 090196
Chassis No : WAUZZZ4M2KD030897
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 04-Jan-20
Place of Accident : Victoria Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJC 2123 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle front bumper and renew rhs front fender. Re-organise front crash management components. Reinstall all parts removed. <i>500</i>	\$ 2,400.00 <i>1000</i>	
3	To dismantle rhs front door panel trims, renew rhs front door glass and wing mirror assy.	S/N \$ 800.00 /	500 ✓
4	To respray front bumper, rhs front fender, rhs front door, wing mirror cover and wheel arch trims. <i>550x2</i>	\$ 3,800.00 <i>1500</i>	
SUB TOTAL LABOUR CHARGES		: \$ 7,480.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJC 2123 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To renew rhs front door glass solar film.	S/N Tbc	X no solar film
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	/
7	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 7,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJC 2123 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH / <i>OK</i>	\$ 1,481.00	1124.80
2	FRONT FENDER ATTACHMENT PARTS <i>OK</i> <i>OK</i> X NN	\$ 69.00	
3	FRONT FENDER BRACKET - RH <i>8</i> NN	\$ 59.00	
4	FRONT FENDER BRACE - RH <i>8</i> NN	\$ 94.00	
5	FRONT WHEEL HOUSING LINER - RH X NN	\$ 223.00	
6	WHEEL HOUSING LINER ATTACHMENT PARTS X NN	\$ 50.00	
7	FRONT WHEEL COVER - LH / RH / <i>OK</i>	2 \$ 1,044.00	835.20
8	EXTERIOR MIRROR MOUNTING - RH / <i>OK</i>	\$ 1,380.00	1104.00
9	MIRROR CAP - RH X NN	\$ 160.00	
10	TURN SIGNAL INDICATOR - RH / <i>OK</i>	\$ 149.00	119.20
11	FRONT DOOR WINDOW - RH / <i>OK</i>	\$ 309.00	247.20
12	WINDOW GUIDE - RH / <i>BT</i>	\$ 461.00	368.80
13	FRONT COVER TRIM - RH / <i>OK</i>	\$ 354.00	283.20
14	FRONT ALUMINIUM RIM - RH / <i>OK</i>	\$ 1,116.00	892.80
15	SUNDRIES <i>OK</i> NEC	\$ 300.00	256.
TOTAL SPARE PARTS CHARGES		: \$ 7,249.00	
TOTAL LABOUR CHARGES		: \$ 7,952.00	
GRAND TOTAL		: \$ 15,201.00	

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

7/1/29, 3:29pm
: Steve (LKK) OD - Not Auth'd (Revert)
: 7 days
: P/P
: R/L BL SM
:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant