

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CC3/FCl20000416/Kea3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 13-08-2020 Code: FCI2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7448K	Veh. Inspected	SHC 5903B	
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
	Claim No.	D20000213MFSH	Excess (\$)	0.00	
	Assign From		Assign Date	06/01/2020	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	VF1ABL15AUC281409	Colour	METALLIC WHITE / RED	
	Odometer	468398	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16		8 mm	
	L/H Front Tyre	215/60 R16		8 mm	
	R/H Rear Tyre	215/60 R16		6 mm	
	L/H Rear Tyre	215/60 R16		6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/12/2019	Inspection Date	06/01/2020	
	Survey held at TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				