

ASS. REC. BY:

REF: CSI INC 20000506/Uqf3

Special instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Theresa Kimala

of

INC

Date/Time: 8. Jan. 2020 10:20 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: **GBA 8436U**

Insured:

GBE 5086U

at Workshop m/s Think One Autocars

Tel:

91288488

of 18 Detu Avenue 2

Policy No:

Claim No: MT / 1078963-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 8. Jan. 2020 11.15 a.m

Person Contacted:

Michael

Vehicle IN/OUT

[illegible]

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LTA 15468 we 29-1-2023

net 3532

conf. insd 4/5 @ 3150 with M. White. (Red 6735.79, 6870)

RECEIVED 10 JAN 2020

Veh No: GBA84364 Yr Regn: 1 of

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan urvan

c.c 2953

Colour:

Grey/white

A/C: Insured / Std / NI / NA

Sp. Reading

363816

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1MG4E2520780541

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M/C/S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GST

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

4/1/20

D.O.I.

8/1/20

Survey held at

1143AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 10/01 finish

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

7p

Lump Sum / I.B.I. (\$

3150

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

290

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Thursday, 9 January 2020 9:05 AM
To: Nivitha (LKK Auto); 'assignments'
Cc: 'SUR'
Subject: RE: TP CASES FARMED OUT TO LKK ON 8/1/2020

Details of OIC etc...

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 8 January 2020 5:09 PM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 8/1/2020

Dear Sir/Mdm,

Kindly assist to provide us the completed details.

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Wednesday, 8 January 2020 10:20 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 8/1/2020

Hi LKK, please assist to survey these vehicles, Thank you.


SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	DOA	OI VEH	Additional Remarks
1	RAJESWARY	MT/1073837-002	8/1/2020	SKA816C	TAN CHONG MOTOR SALES PTE LTD	17 LORONG 8 TOA PAYOH AUTO WORLD BUILDING SINGAPORE 319254	Mr Aishah / 67038012	13:00-15:00	29/11	SKA816C	
2	DAVID PHUA	MT/1079034-001	8/1/2020	GBH7086R	JOO HAK KEE AUTO PTE LTD	BLK 3007 #01-406 UBI ROAD 1	shimin / 67431913		4/1/	GBF6885T	

3	HELENA	MT/1078836-002	8/1/2020	SKG2923G	MY CAR CONSULTANT PTE LTD	SINGAPORE 408701							
						53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832					SMP8191R	
4	SEREME	MT/1078976-001	8/1/2020	SME9797P	PREMIUM AUTOMOBILES PTE LTD	55 UBI ROAD 1 SINGAPORE 408699	/ 6388 2323	10:00-12:00			7/1/2020	SL56871X	Owner waiting
5	CHARLOTTE	MT/1078868-002	8/1/2020	SLG5080G	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01-45/46 UBI ROAD 1 SINGAPORE 408716					7/1/2020	SKS247A	
6	CHRYLLIS	MT/1078034-002	8/1/2020	GX2385S	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151	14:00-16:00			31/12/2019	EQ1221Z	owner waiting
7	DAVID	MT/1078116-002	8/1/2020	SMM68131	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151				31/12/2019	SKD7824S	
8	HELENA	MT/1078980-001	8/1/2020	SMP3605Y	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	Caymen / 6858 5151	11:00-16:00			5/1/2020	SLZ4828Z	
9	HELENA	MT/1078963-001	8/1/2020	GBA8436U	THINK ONE AUTOCARE PTE LTD	18 DEFU AVENUE 2 DEFU INDUSTRIAL ESTATE	Michael Ng / 91288488				4/1/2020	GBE5086U	
10	SERENE	MT/1077717-002	8/1/2020	SLE8868S	TRANS EUROKARS PTE LTD	5 UBI CLOSE	Ronald Yap / 9127 7928	10:00-12:00			27/12/2019	GBH5990T	6395 8899

Theresa Vimala
 Senior Administrator
 Operations, Motor & Personal Lines (PL)
 T +65 6430 7898
www.income.com.sg

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 609M

Vehicle Details

Vehicle No.: GBA8436U

Vehicle to be Exported: No

Intended Deregistration Date: 08 Jan 2020

Vehicle Make: NISSAN

Vehicle Model: URVAN PANEL LWB 3.0 5DR 5MT
AIRBAG 2WD

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: ZD30154808K

Chassis No.: JN1MG4E25Z0780541

Maximum Power Output: -

Open Market Value: \$25,572.00

Original Registration Date: 30 Jan 2008

First Registration Date: 30 Jan 2008

Transfer Count: 5

Actual ARF Paid: \$1,279.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Jan 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$25,304.00

COE Rebate Amount: \$15,468.00

Total Rebate Amount: \$15,468.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 08 Jan 2020

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

nissan urvanPrice Range▼Depreciation▼> 10 year:▼Vehicle Type▼SubmitAdvanced Search

Home » Used Cars » Net Link Partners Pte Ltd » Nissan Urvan (COE till 03/2022)

Nissan Urvan (COE till 03/2022)

OverviewFinancialAccessoriesSimilarResearchPhotosMap

NETLINK*Your Commercial Specialist*

Specialized in New & Used Commercial Vehicles. Insurance. Hire Purchase. Scrap/Export

Price	\$21,800	Lifespan	20-Dec-2022
Depreciation	\$9,790 /yr	Reg Date	21-Dec-2002 (2yrs 2mths 23days COE left)
Mileage	N.A.	Manufactured	2002
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$5,434 as of today (change)	OMV	\$21,403
COE	\$24,394	ARF	\$1,071
Engine Cap	2,953 cc	No. of Owners	2
Curb Weight	1,500 kg		
Type of Vehicle	Van		

Features

Highly Reliable Large Van For Sale! Powerful, Versatile And Can Carry Heavy Loads! Serviced And Ready To Go! Only 2 Previous Owner! View specs of the Nissan Urvan (2008-2009)

Description

Negotiable! Loan Available, Low Interest! Can Deliver Within 3 Days Upon Loan Approval! Call Fast For An No Obligations Discussion! Door Step Viewing Possible! \$5k Cash Rebate!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



ShortlistCompareAdd note
Report ErrorMore Actions

Seller Information

Net Link Partners Pte Ltd

110 vehicles for sale. 68 sold in past 3 mths

71 Woodlands Industrial Park E9 #07-01, #08-08
Wave9
Tel: 67531661
Search cars nearby

Peter	84898866
Teo	92967266
Jeremy	83215291

Posted on: 18-Dec-2019 | Last Updated on: 07-Jan-2020

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/01/2020 11:11
Date Of Accident	04/01/2020 09:15
Exact Location Of Accident	ALONG TPE FILTER LANE TAMPINES ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA8436U
Insured/Policyholder	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	2XXXXX509M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-2.7 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5107784426-000001
Cover Note Number	

Driver

Name of Driver	DING SIEW YIN
NRIC No	SXXXX567I
Date Of Birth	28/08/1958
Occupation	OUTDOOR
Date Of Driving Pass	25/04/1991
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92235266
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 32 CHAI CHEE AVENUE #04-196
Postcode	461032
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 4.1.2020 AT ABOUT 9:15HRS I WAS WAITING IN THE FILTER LANE OF TAMPINES ROAD AND KPE TO GIVE WAY TO MY RIGHT VEHICLE SUDDENLY BEHIND ME A VEHICLE BEARING NUMBER GBE5086U BANG ON TO MY VEHICLE NUMBER GBA8436U CAUSE DAMAGED TO THE REAR PORTION OF VEHICLE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE5086U
Vehicle Make/Model/Colour	NISSAN URVAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Not Allowed
8/1/20
Whip Wh. Atty.
Hdy.

1/5 \$3150

GBA8436U NISSAN URVAN

DATE 6.1.2020

DESCRIPTION	(LIST ITEMS)	AMOUNT S\$
1	1 TAIL GATE	1,459.40
2	1 TAIL GATE INNER LOCK	320.80
3	1 TAIL GATE INNER LOCK CATCH	57.90
4	1 TAIL GATE WEATHERSTRIP	219.30
5	1 TAIL GATE LOGO	145.60
6	1 REAR BUMPER	644.90
7	2 REAR BUMPER SIDE RETAINER	130.40
8	1 REAR END PANEL INNER	544.20
9	1 REAR END PANEL OUTER	548.90
10	1 REAR FLOOR PANEL	1,455.30
11	1 REAR TYRE CARRIER	542.00
		\$ 6,068.70
LESS 30%		\$ 1,820.61
		\$ 4,248.09

DESCRIPTION	(NETT ITEMS)	AMOUNT S\$
1	1 TAIL LAMP RH	287.40
2	1 TAIL GATE LOGO	112.00
3	1 REAR NUMBER LAMP	50.00
4	1 TAIL WIPER MOTOR	854.30
5	1 EXHUAUST TAIL PIPE	650.00
6	1 FLOOR PANEL RUBBER MAT GARNISH	320.00
7	1 TAIL GATE INNER TRIM BOARD	280.00
		\$ 2,553.70

DESCRIPTION	(SPECAIL NETT ITEMS)	AMOUNT S\$
1	1 REVERSE SENSOR	250.00
2	1 REAR NUMBER PLATE	35.00
3	4 REAR BUMPER SIDE CLIP	9.00
4	8 REAR END PANEL GARNISH CLIP	40.00
5	1 70KM/H STICKER	25.00
6	1 REAR WINDSCREEN GLASS SEALANT	90.00
7	8 TAIL GATE TRIM BOARD CLIP	65.00
8	1 JOINT SEALANT	240.00
		\$ 754.00

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged body panels with all necessary components/attach-ments apply hot-works where necessary straighten floor panel repair/reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments	1,000.00
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	850.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000506/Uqf3e2
73 BRAS BASAH ROAD Date: 13-01-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: HELENA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 5086U	Veh. Inspected	GBA 8436U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078963-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/01/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JN1MG4E25Z0780541	Colour	GREY / WHITE
Odometer	363856 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	GST	6 mm
L/H Front Tyre	195 R15	GST	6 mm
R/H Rear Tyre	195 R15	GST	6 mm
L/H Rear Tyre	195 R15	GST	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/01/2020	Inspect Date / Time	08/01/2020 (11:53 AM)
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 8436U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BADLY DENTED	1,459.40	1,459.40
1	TAIL GATE INNER LOCK	DENTED / JAMMED	320.80	320.80
1	TAIL GATE INNER LOCK CATCH	NOT NECESSARY	57.90	-
1	TAIL GATE WEATHERSTRIP (TORN)	NOT CONSISTENT WITH THE IMPACT	219.30	-
1	TAIL GATE LOGO	NECESSARY	145.60	45.00
1	REAR BUMPER	DENTED / DEFORMED	644.90	617.00
2	REAR BUMPER SIDE RETAINER @\$65.20	NOT NECESSARY	130.40	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	544.20	-
1	REAR END PANEL OUTER	BADLY DENTED	548.90	548.90
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,455.30	-
1	REAR TYRE CARRIER	NOT NECESSARY	542.00	-
	LESS 30% DISCOUNT		-1,820.61	-
	LESS 50% DISCOUNT		-	-1,495.55
			4,248.09	1,495.55
<u>SPECIAL NETT ITEMS</u>				
1	TAIL LAMP RH (SN)	NOT NECESSARY	287.40	-
1	TAIL GATE LOGO (SN)	REPEATED	112.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	TAIL WIPER MOTOR (SN)	NOT NECESSARY	854.30	-
1	EXHAUST TAIL PIPE (SN)	NOT NECESSARY	650.00	-
1	FLOOR PANEL RUBBER MAT GARNISH (SN)	NOT NECESSARY	320.00	-
1	TAIL GATE INNER TRIM BOARD (SN)	NOT NECESSARY	280.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
4	REAR BUMPER SIDE CLIP (SN)	NECESSARY	9.00	9.00
8	REAR END PANEL GARNISH CLIP @\$5.00 (SN)	NOT NECESSARY	40.00	-
1	70KM/H STICKER (SN)	NECESSARY	25.00	10.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	90.00	40.00

Report Ref No. CS/INC20000506/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	TAIL GATE TRIM BOARD CLIP (SN)	NOT NECESSARY	65.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	240.00	-
			3,307.70	259.00
	LABOUR			
	TO REMOVE DAMAGED BODY PANELS WITH ALL NECESSARY COMPONENTS/ATTACH-MENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FLOOR PANEL REPAIR/RESHAPE DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS,REPLACE NEW PARTS REFIT ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER AND REAR FLOOR PANEL.		1,000.00	600.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		850.00	600.00
	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS.		100.00	50.00
	TO REMOVE,REFIT REAR WINDSCREEN GLASS AND WATER TEST.		150.00	120.00
	TO REMOVE,REPLACE REAR WINDSCREEN GLASS AND WATER TEST.	NOT NECESSARY	150.00	-
	TO INSTALL REVERSE SENSOR.		80.00	40.00
			2,330.00	1,410.00
GRAND TOTAL			9,885.79	3,164.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,150.00

Report Ref No. CS/INC20000506/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.