




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC6/QBE20000508/Uda3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 11-05-2020		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 4374A	Veh. Inspected	SJL 6848A	
Policy No.	8-V0024132-MVA	Coverage (\$)	0.00	
Claim No.	VC013351	Excess (\$)	0.00	
Assign From		Assign Date	08/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CROSSROAD (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RT11008006	Colour	BLACK	
Odometer	263672	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	MICHELIN	6 mm	
L/H Front Tyre	225/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/01/2020	Inspection Date	08/01/2020	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		