

22/03/2021

ASS. REC. BY:

Surveyor: AdrianREF: es/INC20000521/Ayd3n2 Special Instruction:ASSIGNMENT (Office)From (Person): Theresa Vimala of INC Date/Time: 10:20am @ 8/1/2020

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMF9797P Insured: _____at Workshop m/s premium Tel: G7689911of 55 ubi Road 1Policy No: _____ Claim No: MT/1078976-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10:38am @ 8/1/2020 Person Contacted: Kalvin H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Johny /</u>
	<u>SMF9797P-X</u>

ASSIGNMENT

Form: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03/8/88 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMF9797P Date: 2018 August.
 Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Private Mover /
 Truck / Trailer or
 Make: Audi A6 Year: 1798.
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 25892 T/Ratio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: WAUZZZ460JN064386.
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: 225/55R17.
 R: 225/55R17.
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A.: _____ D.O.L: 08/01/20
 Survey held at: Premium 10:44am
 Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TP INC.
	PIP \$5291-90 (Red \$7277-10, 57%)
	MV:
	PV:
	Nett:
	RECEIVED 24 FEB 2020

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Date/Time, File Return to? 24/2/20 Typist

Add Fee: ☐ : Site Insp. 10
☐ : Interview 10
☐ : Tech. Insp. 10
☐ : Workshop 10

Survey Fee:	
Transportation:	
2-PS:	
Deep:	
Other:	
	250

Report Format: _____
 Temp. Sum / L/Bal: _____
 PIP \$5291-90

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Wednesday, 8 January 2020 10:20 AM
To: 'assignments'
Cc: Thio Tse Kiat; Theresa Vimala D/O Balagangadharan
Subject: TP CASES FARMED OUT TO LKK ON 8/1/2020

Hi LKK, please assist to survey these vehicles, Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	DOA	OI VEH	Additional Remarks
1		MT/1073837-002	8/1/2020	SKA816C	TAN CHONG MOTOR SALES PTE LTD	17 LORONG 8 TOA PAYOH AUTO WORLD BUILDING SINGAPORE 319254	Mr Aishah / 67038012	13:00-15:00			
2		MT/1079034-001	8/1/2020	GBH7086R	JOO HAK KEE AUTO PTE LTD	BLK 3007 #01-406 UBI ROAD 1 SINGAPORE 408701	shimin / 67431913				
3		MT/1078836-002	8/1/2020	SKG2923G	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832				
4	SEIENE	MT/1078976-001	8/1/2020	SMF9797P	PREMIUM AUTOMOBILES PTE LTD	55 UBI ROAD 1 SINGAPORE 408699	/ 6388 2323	10:00-12:00			Owner waiting
5		MT/1078868-002	8/1/2020	SLG5080G	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01-45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336				
6		MT/1078034-002	8/1/2020	GX2385S	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151	14:00-16:00			owner waiting
7		MT/1078116-002	8/1/2020	SMM6813J	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	William / 6858 5151				
8		MT/1078980-001	8/1/2020	SMP3605Y	TAN LIM MOTOR PTE LTD	1 DEFU LANE 6 SINGAPORE 539365	Caymen / 6858 5151	11:00-16:00			
9		MT/1078963-001	8/1/2020	GBA8436U	THINK ONE AUTOCARE PTE LTD	18 DEFU AVENUE 2 DEFU INDUSTRIAL ESTATE	Michael Ng / 91288488				
10		MT/1077717-002	8/1/2020	SLE8868S	TRANS EUOKARS PTE LTD	5 UBI CLOSE	Ronald Yap / 9127 7928	10:00-12:00			6395 8899

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2020 11:11
Date Of Accident	07/01/2020 09:35
Exact Location Of Accident	CTE EXIT AVE 5 TOWARD AMK INDUSTRIAL PARK 24
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF9797P
Insured/Policyholder	
Name Of Registered Owner	NEO GEK BENG
NRIC No	SXXXX426Z
Email Address	WILNEO@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-87236849
Alternative Phone No	OFFICE-87236849

Vehicle Particulars

Manufacturer	AUDI
Model	A6 1.8 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800107159
Cover Note Number	

Driver

Name of Driver	NEO GEK BENG
NRIC No	SXXXX426Z
Date Of Birth	15/01/1972
Occupation	INDOOR
Date Of Driving Pass	26/11/1993
Driving Experience	26 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87236849
Fax Number	
Contact Number	OFFICE-87236849
Email Address	WILNEO@SINGNET.COM.SG

Address	788 YISHUN AVE 2 #03-1491
Postcode	760788
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHEN I WAS TRAVELLING FROM CTE EXIT ANG MO KIO AVE 5 TOWARD MY OFFICE, AT THE GIVE WAY EXIT A SLOW DOWN, THE REAR VEHICLE SLS 6871 X JUST HIT ONTO MY REAR BOOTS. TIME AROUND 0930AM 7 JAN 2020

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS6871X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOONG CHI LEONG
NRIC/Passport Number	
Contact Number	9222 3910
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Wahin Wong*
NRIC/FIN No.: *G8467988*

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I was travelling from CTE Exit 2 off the Kio Ave R5 toward my office, at the side way Exit I slow down, the rear vehicle SLS 6871X just hit onto my rear boots. Time around 0930am 7 July 2016.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Helen White
NRIC/FIN No: 68765901

GLA 5142 Sketch Plan Form 1/16

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25392

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0017/2020/NS
Date : 7-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLS 6871 X

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr Neo Gek Beng
Address : 788 Yishun Avenue 2
#03-1491
Singapore 760788
Telephone : HP +65 87236849
Type of Claim : Third Party Claims
Policy No. : 1800107159
Vehicle No : **SMF 9797 P**
Model Code : A6 1.8 TFSI S TRONIC
Model / Year : Aug-18
Engine No : CYG 025123
Chassis No : WAUZZZ4G0JN064386
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Jul-20
Place of Accident : CTE Exit Ave 5 Toward Amk Industrial Park 24

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 9797 P

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00 ✓	\$360.00
2	To dismantle and renew rear bumper. To repair rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	2,000.00 800 ✓	\$2,000.00 \$800.00
3	To respray rear bumper, rhs rear fender and rear lid.	\$	3,000.00 800 ✓	\$3,000.00 \$800.00
4	To carry out diagnostic check.	S/N \$	192.00 ✓	\$192.00
TOTAL LABOUR CHARGES		:	\$ 5,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 9797 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Delid</i>	\$ 2,676.00	<i>✓</i> \$2676.00
2	REAR BUMPER FIXING PARTS <i>Neu</i>	\$ 247.00	<i>+</i>
3	REAR BUMPER SPOILER <i>Delid</i>	\$ 437.00	<i>✓</i> \$437.00
4	REAR BUMPER SECURING STRIP <i>Neu Neu.</i>	\$ 203.00	<i>?</i>
5	REAR BUMPER CLOSING ELEMENT - RH <i>Neu</i>	\$ 73.00	<i>+</i>
6	EXHAUST TAIL PIPE TRIM - RH <i>Neu</i>	\$ 517.00	<i>+</i>
7	REAR BUMPER CARRIER <i>Neu Neu.</i>	\$ 887.00	<i>?</i>
8	REAR BUMPER SEAL - LH / RH <i>Neu</i>	2 \$ 26.00	<i>+</i>
9	REAR BUMPER GUIDE SECTION - LH / RH <i>?</i>	2 \$ 60.00	<i>+</i>
10	REAR BUMPER GUIDE SECTION - RH	\$ 48.00	<i>+</i>
11	REAR BUMPER CONNECTING PIPE	2 \$ 22.00	<i>+</i>
12	REAR BUMPER GUIDE PROFILE - LH / RH	2 \$ 120.00	<i>+</i>
13	REAR BUMPER HOLDING STRAP - LH / RH <i>Neu</i>	2 \$ 116.00	<i>+</i>
14	REAR BUMPER COVER - RH	\$ 105.00	<i>+</i>
15	REAR BUMPER GUIDE SECTION - CENTRE	\$ 96.00	<i>+</i>
16	REAR PARKING AID SENSOR	2 \$ 462.00	<i>+</i>
17	LID DECORATIVE TRIM <i>Neu</i>	\$ 335.00	<i>+</i>
18	AUDI EMBLEM <i>?</i>	\$ 113.00	<i>+</i>
19	A6 INSCRIPTION <i>Neu</i>	\$ 87.00	<i>+</i>
20	TFSI INSCRIPTION	\$ 87.00	<i>+</i>
21	SUNDRIES <i>Neu</i>	\$ 300.00	<i>?</i> \$26.90
TOTAL SPARE PARTS CHARGES		: \$ 7,017.00	
TOTAL LABOUR CHARGES		: \$ 5,552.00	
GRAND TOTAL		: \$ 12,569.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian Ling
08/01/20

Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25392

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0017/2020/NS
Date : 07-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLS 6871 X

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Hi Adrian,

3 days - ok - Jy - 31 Jan 2020

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr Neo Gek Beng
Address : 788 Yishun Avenue 2
#03-1491
Singapore 760788
Telephone : HP +65 87236849
Type of Claim : Third Party Claims
Policy No. : 1800107159
Vehicle No : **SMF 9797 P**
Model Code : A6 1.8 TFSI S TRONIC
Model / Year : Aug-18
Engine No : CYG 025123
Chassis No : WAUZZZ4G0JN064386
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 07-Jul-20
Place of Accident : CTE Exit Ave 5 Toward Amk Industrial Park 24

Premium Automobiles

0

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMF 9797 P

S/n	Nature of Jobs		Estimated Charges	Surveyor's ecommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew rear bumper. To repair rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	2,000.00	\$ 800.00
3	To respray rear bumper, rhs rear fender and rear lid.	\$	3,000.00	\$ 800.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,552.00</u>	<u>\$ 2,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 9797 P

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,676.00	\$ 2,676.00
2	REAR BUMPER FIXING PARTS	\$ 247.00	
3	REAR BUMPER SPOILER	\$ 437.00	\$ 437.00
4	REAR BUMPER SECURING STRIP	\$ 203.00	
5	REAR BUMPER CLOSING ELEMENT - RH	\$ 73.00	
6	EXHAUST TAIL PIPE TRIM - RH	\$ 517.00	
7	REAR BUMPER CARRIER	\$ 887.00	
8	REAR BUMPER SEAL - LH / RH	2 \$ 26.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 60.00	
10	REAR BUMPER GUIDE SECTION - RH	\$ 48.00	
11	REAR BUMPER CONNECTING PIPE	2 \$ 22.00	
12	REAR BUMPER GUIDE PROFILE - LH / RH	2 \$ 120.00	
13	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 116.00	
14	REAR BUMPER COVER - RH	\$ 105.00	
15	REAR BUMPER GUIDE SECTION - CENTRE	\$ 96.00	
16	REAR PARKING AID SENSOR	2 \$ 462.00	
17	LID DECORATIVE TRIM	\$ 335.00	
18	AUDI EMBLEM	\$ 113.00	
19	A6 INSCRIPTION	\$ 87.00	
20	TFSI INSCRIPTION	\$ 87.00	
21	SUNDRIES	\$ 300.00	\$ 26.90
TOTAL SPARE PARTS CHARGES		: \$ 7,017.00	\$ 3,139.90
TOTAL LABOUR CHARGES		: \$ 5,552.00	\$ 2,152.00
GRAND TOTAL		: \$ 12,569.00	\$ 5,291.90

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000521/Ayd3n2
73 BRAS BASAH ROAD Date: 25-02-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: SERENE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 6871X	Veh. Inspected	SMF 9797P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078976-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/01/2020

2. Vehicle Particulars & Condition

Make & Model	AUDI A6	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZ4G0JN064386	Colour	GREEN
Odometer	25892 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	MICHELIN	6 mm
L/H Front Tyre	225/55 R17	MICHELIN	6 mm
R/H Rear Tyre	225/55 R17	MICHELIN	6 mm
L/H Rear Tyre	225/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/01/2020	Inspect Date / Time	08/01/2020 (10:44 AM)
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 9797P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	2,676.00	2,676.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	247.00	-
1	REAR BUMPER SPOILER (SN)	DEFORMED	437.00	437.00
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	203.00	-
1	REAR BUMPER CLOSING ELEMENT-RH (SN)	NOT NECESSARY	73.00	-
1	EXHAUST TAIL PIPE TRIM-RH (SN)	NOT NECESSARY	517.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	887.00	-
2	REAR BUMPER SEAL-LH/RH (SN)	NOT NECESSARY	26.00	-
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	60.00	-
1	REAR BUMPER GUIDE SECTION-RH (SN)	NOT NECESSARY	48.00	-
2	REAR BUMPER CONNECTING PIPE (SN)	NOT NECESSARY	22.00	-
2	REAR BUMPER GUIDE PROFILE-LH/RH (SN)	NOT NECESSARY	120.00	-
2	REAR BUMPER HOLDING STRAP-LH/RH (SN)	NOT NECESSARY	116.00	-
1	REAR BUMPER COVER-RH (SN)	NOT NECESSARY	105.00	-
1	REAR BUMPER GUIDE SECTION-CENTRE (SN)	NOT NECESSARY	96.00	-
2	REAR PARKING AID SENSOR (SN)	NOT NECESSARY	462.00	-
1	LID DECORATIVE TRIM (SN)	NOT NECESSARY	335.00	-
1	AUDI EMBLEM (SN)	NOT NECESSARY	113.00	-
1	A6 INSCRIPTION (SN)	NOT NECESSARY	87.00	-
1	TFSI INSCRIPTION (SN)	NOT NECESSARY	87.00	-
1	SUNDRIES (SN)	NECESSARY	300.00	26.90
			7,017.00	3,139.90
LABOUR				
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.			360.00	360.00
TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR RHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.			2,000.00	800.00
TO RESPRAY REAR BUMPER,RHS REAR FENDER AND REAR LID.			3,000.00	800.00

Report Ref No. CS/INC20000521/Ayd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			5,552.00	2,152.00
GRAND TOTAL			12,569.00	5,291.90
RECOMMENDED COST OF REPAIRS (CONFIRMED)				5,291.90

Report Ref No. CS/INC20000521/Ayd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.