

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. LIM WEI HONG
BLK 416 YISHUN AVENUE 11 #07-365
SINGAPORE 760416

Contact : 97680728

TP FWD.

Xiao Tong

ESTIMATE

Repair Code : CLM14826

Date in : 07/01/2020

Vehicle Num. : SJL8135K

Model : TOYOTA MARX X 2.5 A

Chassis/Eng# : GRX1203048590/4GR0402725

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>to r</i>	1	1210.10	869 1,210.10
FRONT BUMPER SIDE RETAINER L/R <i>LH Na</i>	2	131.20	131.20 262.40
FRONT LH DOOR <i>Dented.</i>	1	1294.70	✓ 1,294.70
FRONT LH DOOR UPPER MOULDING RIVET <i>3 riv</i>	8	8.00	X 64.00
FRONT LH DOOR VERTICAL GARNISH <i>1 riv</i>	1	122.70	X 122.70
FRONT LH FENDER <i>Dented</i>	1	672.40	✓ 672.40
FRONT LH FENDER INNER SHIELD <i>to r</i>	1	236.40	✓ 236.40
FRONT LH HEADLAMP <i>cauled.</i>	1	1417.70	✓ 1,417.70
FRONT LH KNUCKLE ARM <i>Dented</i>	1	600.80	✓ 600.80
FRONT LH KNUCKLE ARM BEARING <i>2 pc</i>	1	765.10	628 765.10
FRONT LH LINKAGE <i>NN</i>	1	135.50	X 135.50
FRONT LH LOWER ARM <i>Bent</i>	1	879.50	526 879.50
FRONT LH LOWER ARM BALL JOINT <i>Bent</i>	1	296.30	✓ 296.30
FRONT LH STEERING TIE ROD END <i>NN</i>	1	271.90	X 271.90
FRONT LH UPPER ARM <i>Bent</i>	1	598.00	322 598.00
LH SIDE SKIRT GARNISH <i>Deformed</i>	1	928.20	851 928.20
PETROL LID COVER RIVET <i>NN</i>	2	9.00	X 18.00
REAR LH DOOR <i>Dented</i>	1	1271.90	✓ 1,271.90

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM WEI HONG
BLK 416 YISHUN AVENUE 11 #07-365
SINGAPORE 760416

Contact : 97680728

ESTIMATE

Repair Code : CLM14826

Date in : 07/01/2020

Vehicle Num. : SJL8135K

Model : TOYOTA MARX X 2.5 A

Chassis/Eng# : GRX1203048590/4GR0402725

REAR LH DOOR UPPER MOULDING RIVET	8	8.00	X	64.00
REAR LH DOOR VERTICAL GARNISH	1	122.70	X	122.70
REAR LH FENDER	1	1211.00	X	1,211.00
REAR LH KNUCKLE ARM	1	561.20	X	561.20
REAR LH KNUCKLE ARM BEARING	1	539.30	X	539.30
REAR LH LOWER ARM	1	527.20	X	527.20
REAR LH STAY ARM	1	271.80	X	271.80
REAR LH TORSION ARM	1	211.30	X	211.30
REAR WINDSCREEN GLASS MOULDING	1	98.60	X	98.60

Subtotal before discount

14,652.70

Percentage discount 25%

3,663.18

Sub-total 1

10,989.53

FRONT BUMPER CLIPS - SET	1	50.00	30	50.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	30	50.00
FRONT LH HEADLAMP CLIPS	1	20.00	✓	20.00
FRONT LH SHOCK ABSORBER	1	1800.00	750	1,800.00
FRONT LH SPORT RIM	1	1200.00	750	1,200.00
FRONT LH TYRE	1	600.00	X	600.00

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LIM WEI HONG
BLK 416 YISHUN AVENUE 11 #07-365
SINGAPORE 760416

Contact : 97680728

ESTIMATE

Repair Code : CLM14826
Date in : 07/01/2020
Vehicle Num. : SJL8135K
Model : TOYOTA MARX X 2.5 A
Chassis/Eng# : GRX1203048590/4GR0402725

LH SIDE SKIRT GARNISH CLIPS - SET <i>new</i>	1	80.00	<i>30</i> 80.00
REAR LH SHOCK ABSORBER <i>new</i>	1	1800.00	<i>X</i> 1,800.00
REAR LH SPORT RIM <i>new</i>	<i>2360</i> 1	1200.00	<i>750</i> 1,200.00
REAR LH TYRE <i>new</i>	1	600.00	<i>X</i> 600.00
REAR WINDSCREEN GLASS SEALANT <i>new</i>	1	80.00	<i>X</i> 80.00
Subtotal before discount			7,480.00
Percentage discount 0%			0.00
Sub-total 2			7,480.00
Parts-total			18,469.53

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove and refit rear windscreen(to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

30 ~~60.00~~
X 150.00
220 ~~250.00~~
X 250.00
80 ~~100.00~~
X 80.00
50 ~~150.00~~
160 ~~200.00~~
1300 ~~1,500.00~~

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR. LIM WEI HONG
BLK 416 YISHUN AVENUE 11 #07-365
SINGAPORE 760416

Contact : 97680728

ESTIMATE

Repair Code : CLM14826

Date in : 07/01/2020

Vehicle Num. : SJL8135K

Model : TOYOTA MARX X 2.5 A

Chassis/Eng# : GRX1203048590/4GR0402725

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	800	1,200.00
	2690	20 120.00
Labour Total		4,060.00
Parts & Labour Total		22,529.53

*** This is a computer-generated document which requires no signature.***

page 4

total 11888.05
1/5 9.5K
08 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: