

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2020 Edit Reg		08 Jan 2020 00:00 Edit Adj Rpt	S\$3,788.40 Edit Estimates	S\$3,788.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	RADHA EXPORTS PTE. LTD., Co. Reg. No.: -								
Main Claimant:	PHOON GRACE								
Vehicle Reg. No.:	SJC2880D	Date of Loss:	06/01/2020 00:00 - :59 [23 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4134661386SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SMM4416K	Policy No. (Claimant):	PNPV2019-00001149						
		Excess:							
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (22/04/2020): Alert - Adj Mandate Approved (S\$4415.59) - SJC2880D - Claim Handler: Loh, Chee-H... - AIG_SG (09/01/2020): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJC2880D (4134661386SG)
[SMM4416K]
TP
PHOON GRACE
Jan 6 2020 12:00AM
[RADHA EXPORTS PTE. LTD.]
Vin's Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences 1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images 3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/03/20 10:06	General View	1	Load JPG	☒
2	26/03/20 10:06	General View	1	Load JPG	☒
3	26/03/20 10:06	General View	1	Load JPG	☒
4	26/03/20 10:06	General View	1	Load JPG	☒
5	26/03/20 10:06	General View	1	Load JPG	☒
6	26/03/20 10:06	General View	1	Load JPG	☒
7	26/03/20 10:06	General View	1	Load JPG	☒
8	26/03/20 10:06	General View	1	Load JPG	☒
9	26/03/20 10:06	General View	1	Load JPG	☒
10	26/03/20 10:06	General View	1	Load JPG	☒
11	26/03/20 10:06	General View	1	Load JPG	☒
12	26/03/20 10:06	General View	1	Load JPG	☒
13	26/03/20 10:06	General View	1	Load JPG	☒
14	26/03/20 10:06	General View	1	Load JPG	☒
15	26/03/20 10:06	General View	1	Load JPG	☒
16	26/03/20 10:06	General View	1	Load JPG	☒
17	26/03/20 10:06	General View	1	Load JPG	☒
18	26/03/20 10:06	General View	1	Load JPG	☒
19	26/03/20 10:06	General View	1	Load JPG	☒
20	26/03/20 10:06	General View	1	Load JPG	☒
21	26/03/20 10:06	General View	1	Load JPG	☒
22	26/03/20 10:06	General View	1	Load JPG	☒
23	26/03/20 10:06	General View	1	Load JPG	☒
24	26/03/20 10:06	General View	1	Load JPG	☒
25	26/03/20 10:06	General View	1	Load JPG	☒
26	26/03/20 10:06	General View	1	Load JPG	☒
27	26/03/20 10:06	General View	1	Load JPG	☒
28	26/03/20 10:06	General View	1	Load JPG	☒
29	26/03/20 10:06	General View	1	Load JPG	☒
30	26/03/20 10:06	General View	1	Load JPG	☒
31	26/03/20 10:06	General View	1	Load JPG	☒
32	26/03/20 10:06	General View	1	Load JPG	☒
33	26/03/20 10:06	General View	1	Load JPG	☒
34	26/03/20 10:06	General View	1	Load JPG	☒
35	26/03/20 10:06	General View	1	Load JPG	☒
36	26/03/20 10:06	General View	1	Load JPG	☒
37	26/03/20 10:06	General View	1	Load JPG	☒

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	26/03/20 10:06	General View		Load JPG	☒
39	26/03/20 10:06	General View		Load JPG	☒
40	26/03/20 10:06	General View		Load JPG	☒
41	26/03/20 10:06	General View		Load JPG	☒
42	26/03/20 10:06	General View		Load JPG	☒
43	26/03/20 10:06	General View		Load JPG	☒
44	26/03/20 10:06	General View		Load JPG	☒
45	26/03/20 10:06	General View		Load JPG	☒
46	26/03/20 10:06	General View		Load JPG	☒
47	26/03/20 10:06	General View		Load JPG	☒
48	26/03/20 10:06	General View		Load JPG	☒
49	26/03/20 10:06	General View		Load JPG	☒
50	26/03/20 10:06	General View		Load JPG	☒
51	26/03/20 10:06	General View		Load JPG	☒
52	26/03/20 10:06	General View		Load JPG	☒
53	26/03/20 10:06	General View		Load JPG	☒
54	26/03/20 10:06	General View		Load JPG	☒
55	26/03/20 10:06	Odometer Reading		Load JPG	☒
56	26/03/20 10:07	Reinspection Photo		Load JPG	☒
57	26/03/20 10:07	Reinspection Photo		Load JPG	☒
58	26/03/20 10:07	Reinspection Photo		Load JPG	☒
59	26/03/20 10:07	Reinspection Photo		Load JPG	☒
60	26/03/20 10:07	Reinspection Photo		Load JPG	☒
61	26/03/20 10:07	Reinspection Photo		Load JPG	☒
62	26/03/20 10:07	Reinspection Photo		Load JPG	☒
63	26/03/20 10:07	Reinspection Photo		Load JPG	☒
64	26/03/20 10:07	Reinspection Photo		Load JPG	☒
65	26/03/20 10:07	Reinspection Photo		Load JPG	☒
66	26/03/20 10:07	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/01/20 20:46	ACKNOWLEDGEMENT EMAIL TO AIG DD 08.01.2020		Load PDF	
2	08/01/20 20:46	EMAIL FROM AIG DD 08.01.2020		Load PDF	
3	19/01/20 00:50	TP ESTIMATE - MARKED		Load PDF	
4	19/01/20 00:50	TP GIA REPORT		Load PDF	
5	21/04/20 10:53	GIA SEARCH		Load PDF	
6	21/04/20 10:53	LOD		Load PDF	
7	08/05/20 12:01	Authorisation to Act		Load PDF	
8	08/05/20 12:01	LETTER TO OI		Load PDF	
9	08/05/20 12:01	Release Voucher		Load PDF	
10	08/05/20 12:01	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/01/20 16:31	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMM4416K (Insd veh)	Model:	MITSUBISHI ATTRAGE 1.2 CVT
	SJC2880D (TP veh)		(A)
Date of Accident:	06/01/2020		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				5,826.36
Final Repair Cost	:	\$				4,053.59
Loss of Use	:	\$				360.00
Rental (if any)	:	\$				6.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$				2.00
Others:	:	\$				0.00
	:	\$				
Final Settlement Sum	:	\$				4,415.59
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)						
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____						
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)						
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>						
Remarks _____ _____ _____						

Payment Instruction: Payee's Breakdown			
1)	Vin's Motor Pte Ltd	: \$	4,415.59
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

08 May
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000565/GDA3S2**Date:** 08/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJC2880D**Insured Vehicle No :** SMM4416K

Date of Loss: 06/01/2020

Nature of Claim: TP

Claim No: 4134661386SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJC2880D**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UGN2938

Reg. Date: 23/01/2018 (Man. Year: 2017)

Chassis No: MMBSTA13AJH000781

Colour: Black

Odometer: 26822 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,785.20	2,588.40	1,196.80	31.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,200.00	460.00	27.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,445.20	3,788.40	1,656.80	30.43
+ GST 7.00/7.00% (S\$)	381.16	265.19	115.97	30.43
Nett Amount (S\$)	5,826.36	4,053.59	1,772.77	30.43
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,415.59		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 10/01/2020 Inspected At:

Vin's Motor Pte Ltd

Sin Ming AutoCity,, 160 Sin Ming Drive #03-03

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** CHAN JIA LE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	765.00 FL	*765.00 FL
2	1		*REAR BOOT LID TOP SPOILER	Deformed	512.00 FL	*512.00 FL
3	1		*REAR BOOTLID EMBLEM	Necessary	41.00 FL	*41.00 FL
4	1		*REAR BOOTLID C&C EMBLEM	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BOOTLID ATTRAGE EMBLEM	Necessary	20.00 FL	*20.00 FL
6	1		*REAR BOOTLID MIVEC EMBLEM	Necessary	70.50 FL	*70.50 FL
7	1		*REAR BOOTLID OUTER CHROME MOULDING	Not Necessary	318.00 FL	*- FL
8	2		*REAR BOOTLID HINGES	Not Necessary	370.00 FL	*- FL
9	1		*REAR BOOTLID LOCK	Cut	198.00 FL	*198.00 FL
10	1		*REAR BOOTLID RUBBER	Twisted	143.00 FL	*143.00 FL
11	1		*REAR TAILLAMP	N/s Cracked/O/s Not Necessary	532.00 FL	*266.00 FL
12	1		*REAR BUMPER	Deformed	659.00 FL	*659.00 FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	40.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Deformed	22.00 FL	*22.00 FL
15	1		*REAR END PANEL	Repair	402.00 FL	*- FL
16	1		*REAR END PANEL TOP TRIM	Cut	62.00 FL	*62.00 FL
17	1		*SET REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS
18	1		*SPARE PANEL BOARD	Cut	177.00 FL	*177.00 FL
					Sub Total (\$\$)	4,661.50 3,185.50
					- List Item Discount on L Items 20.00/20.00% (\$\$)	876.30 597.10
					Total Parts (\$\$)	3,785.20 2,588.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR DAMAGE.	New	780.00	500.00
2	TO SPRAY PAINTING.	New	880.00	700.00
Gross Labour Cost (S\$)			1,660.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >