

Vin's

Our Ref : TP/012020/4220
Accident date : 6/1/2020
Your Ref : SMM4416K
AUTOMOTIVE GROUP

Invoice No.:
A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
Date : 10/1/2020
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

4 Days.
part by part.
before paint photos.
Gino Qianf - 82880282
10/01/2020.

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SJC2880D
Model : MITSUBISHI ATTRAGE-1.2 (A)

1	pc	Rear boot lid / Blue	\$ 765.00
1	pc	Rear boot lid top spoiler ?	\$ 512.00
1	pc	Rear bootlid emblem	\$ 41.00
1	pc	Rear bootlid 'C & C' emblem	\$ 50.00
1	pc	Rear bootlid 'Attrage' emblem	\$ 20.00
1	pc	Rear bootlid 'Mivec' emblem	\$ 70.50
1	pc	Rear bootlid outer chrome moulding	\$ 318.00
2	pcs	Rear bootlid hinge @ \$185.00	\$ 370.00
1	pc	Rear bootlid lock - cut	\$ 198.00
1	pc	Rear bootlid rubber - two: cut - OA	\$ 143.00
2	pcs	Rear taillamp @ \$266.00	\$ 532.00
1	pc	Rear bumper / Re	\$ 659.00
2	pcs	Rear bumper reflector @ \$20.00	\$ 40.00
2	pcs	Rear bumper side retainer @ \$22.00	\$ 22.00
1	pc	Rear end panel	\$ 402.00
1	pc	Rear end panel top trim	\$ 62.00
		Spare panel Board cut - \$177.00	\$ 4,204.50
		Less 20%	\$ (840.90)
			\$ 3,363.60

1 set Rear bumper parking sensor / PM.

\$ 280.00 N 200.

To repair rear damage
To spray painting

\$ 780.00 (400 (600))
\$ 880.00 (600 (700))
\$ 5,303.60

VIN'S MOTOR PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: