

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date: 08/01/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLQ3194Y

CHASSIS NO : RU31214754

MAKE / MODEL : Honda Vezel Hybrid 1.5X Auto

DATE OF ACCIDENT : 04/01/2020

YOUR INSURED VEHICLE NUMBER : SJC2123G

MILEAGE : 168500 Km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION

	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Front bumper ✓ CR4	1PC	\$955.00	\$955.00 800
2 F/L headlamp (LHD) ? ✓ CRA	1PC	\$2,100.00	\$2,100.00 1,250
3 F/L fender ✓ CR4	1 PC	\$600.00	\$600.00 ✓
4 F/L fender wheel arch moulding ✓ SCH	1PC	\$300.00	\$300.00 250
LIST TOTAL S\$:			\$3,955.00 2,900
20.00% DISCOUNT S\$:			\$791.00 -20%
			\$3,164.00 2,320

SPECIAL NETT

1 Bumper and end panel clips ✓ NEC	1 SET	\$200.00	30
Special Nett Total S\$:		\$200.00	30

LABOUR CHARGES

1 To labour charge for removing front bumper and F/L fender out to facilitate repairs and replacement of damaged parts.	\$750.00	400
2 To respray front bumper, F/R fender and F/L fender wheel arch moulding	\$700.00	600
3, wheel Alignment \$60 ✓		
LABOUR TOTAL S\$:		\$1,450.00 1,160
TOTAL S\$:		\$4,814.00
7% GST		\$336.98
GRAND TOTAL S\$:		<u>\$5,150.98</u>

Repair day - 3 days.

P/P Repair.

before spray photo.

Supp S/Nett
 wheel Cover \$120 ✓ /SCR
 wheel Rim \$200 170 ✓ BT
290

P = 2,320
 N = 320
 L = 1,160
3,800

Sun Pin (LKK)

08/01/2020

TP without prejudice.

P/P
\$3,800
 3 days