LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 10 Jan 2020

Preliminary Advice

Vehicle No : XD6545A Accident Date : 07/01/2020

: DMCVSN1900161900 Make : VOLVO FMX420 Policy No.

Assignment Date : 08/01/2020 **Excess** : S\$1,500.00 Date of Inspection : 09/01/2020 Est. Duration of Repair : 30 days

Inspection At : Vfix Auto Service Pte Ltd (HQ)

26 Chia Ping Road

Singapore 619977

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	152,413.30
Revised Amount	:S\$	56,619.00
Check Items (Estimated)	:S\$	84,125.70
Total	:S\$	140,744.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 79,000.00 COE / PARF Rebate 18,264.00 :S\$

Salvage Value :S\$

Margin for Repair 60,736.00 :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
Х)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :