

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Cince Teo of SMO Date/Time: 9/11/2020 @ 10:42am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 7047T Insured: YP731T

at Workshop n/s Vision Autowork Tel: 98564815

of 2 kaki Bukit Ave #08-09 premier

Policy No: Claim No: CMTD2000147/APL

Sum Insured: Excess:

Make of Veh: D.O.A. 07/10/2020 (Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 11:12am @ 9/1/2020 Person Contacted: Michelle Vehicle: IN/OUT

Date/Time	Action/Instruction	John/MT ✓
	GBJ7047T-x	
	YP731T-x	
15/1/20	Pending Estimate from workshop	
16/1/20	Sent Preli by email	
17/1 3.25pm	Spoken to Michelle, agreed to repair the vehicle at Lump Sum not more than \$27,500.	



## Celine Fong (LKKAuto)

---

**From:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>  
**Sent:** Monday, 20 January 2020 8:53 AM  
**To:** Vision Autowork  
**Cc:** Celine Fong (LKKAuto); Yvonne Wong (LKK Auto); Bryan Ang (LKKAuto); SUR  
**Subject:** Direct Settle ; RE: Pls fwd repair estimate ; RE: Accident involving GBJ7047T and YP731T on 07.01.20 (Your Ref:CMTD2000147/GPL)

Dear Michelle,

Thank you for your email below and as above, we would like to Direct Settle and please liaise with agreed SJE, M/s LKK AUTO for survey / finalisation at agreed \$ 27,500 for cost of repair.

By copy to M/s LKK AUTO,

Please assist above, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

<sup>1</sup>For Travel, Personal Accident & Home Insurance | <sup>2</sup>For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Vision Autowork <visionautowork@gmail.com>

**Sent:** Monday, 20 January, 2020 8:20 AM

**To:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

**Subject:** Re: Pls fwd repair estimate ; RE: Accident involving GBJ7047T and YP731T on 07.01.20 (Your Ref:CMTD2000147/GPL)

Dear Pau Loong,

Any update from your Manager regarding the GBJ7047T liability??

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,  
#08-09, Premier @ Kaki Bukit,  
Singapore 415875  
Tel: 6341 6789  
Fax: 6341 6778

## Celine Fong (LKKAuto)

---

**From:** Celine Fong (LKKAuto)  
**Sent:** Friday, 17 January 2020 9:51 AM  
**To:** Gnoh, Pau Loong  
**Cc:** Han, Bernard; Yvonne Wong (LKK Auto); Bryan Ang (LKKAuto)  
**Subject:** RE: Pls advise economical to repair ? ; RE: Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20

Dear Mr Gnoh,

We have checked and revised the margin for repair for third party vehicle is as below:

Market Value : \$58,000.00 (Est)  
LTA Rebate : \$30,443.00  
NETT Value : \$27,557.00

According to our surveyor, the repairer has agreed to repair at Lump Sum not more than \$27,500.00.

Apologise for the inconvenience caused.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>  
**Sent:** Thursday, 16 January 2020 5:11 PM  
**To:** Celine Fong (LKKAuto) <[celinefong@lkkauto.com](mailto:celinefong@lkkauto.com)>  
**Cc:** Han, Bernard <[Bernard.han@sompo.com.sg](mailto:Bernard.han@sompo.com.sg)>; Yvonne Wong (LKK Auto) <[yvonne Wong@lkkauto.com](mailto:yvonne Wong@lkkauto.com)>; Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>  
**Subject:** RE: Pls advise economical to repair ? ; RE: Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20  
**Importance:** High

Dear Celine,

With reference to the email trail below and as just spoken, we would appreciate your assistance as we require our management mandate, thank you

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



**SOMPO**  
INSURANCE

**A Century of Trust**

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, January 16, 2020 10:59 AM  
**To:** Gnoh, Pau Loong  
**Cc:** Han, Bernard  
**Subject:** RE: Pls advise economical to repair ? ; RE: Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20

Morning Pau Loong

Market value : \$58,000.00 (Est)  
LTA rebate : \$25,600.00  
NETT value : \$32,400.00

The vehicle is economical repair in lump sum basis and within nett value.

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]  
**Sent:** Thursday, January 16, 2020 10:22 AM  
**To:** Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; Han, Bernard <Bernard.han@sompo.com.sg>  
**Subject:** Pls advise economical to repair ? ; RE: Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20  
**Importance:** High

Dear Yvonne,

With reference above, please advise if third party vehicle is economical for repair ?

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



**SOMPO**  
INSURANCE

**A Century of Trust**

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, January 16, 2020 10:16 AM  
**To:** Gnoh, Pau Loong  
**Cc:** SUR; Han, Bernard  
**Subject:** RE: Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20  
**Attachments:** GBJ7047T PRELI ADVISE.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle GBJ7047T  
Date of survey : 09/01/2020  
Number of days : 21 days  
Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonnewong@lkkauto.com](mailto:yvonnewong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]  
**Sent:** Wednesday, January 15, 2020 10:16 AM  
**To:** Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; Han, Bernard <Bernard.han@sompo.com.sg>  
**Subject:** Urgent : Pls advise prelim report for GBJ7047T ; RE: CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20  
**Importance:** High

Dear Yvonne,

With reference above and as spoken yesterday, we would appreciate your advise for third party prelim repair for GBJ7047T, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Thursday, 9 January 2020 10:42 AM  
**To:** Vision Autowork; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James; nsg5vincent@gmail.com; 'khowyong@yahoo.com.sg'  
**Subject:** CMTD2000147/GPL - LKK/ YP731T & GBJ7047T ACC ON 07.01.20  
**Attachments:** 08012020174422.pdf

Our Reference: CMTD2000147/GPL  
Your Reference: GBJ7047T

**Without Prejudice**  
EMAIL ONLY

Date: 09/01/2020

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**  
**M/S VISION AUTOWORK PTE LTD**

Dear Michelle,

### **ACCIDENT INVOLVING YP731T & GBJ7047T ON 07.01.2020**

We refer to our tele-conversation and will re-assign **LKK Auto** to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **GBJ7047T** on a without prejudice basis and revert with your report upon completion of survey to my colleague, **Mr. Pau Loong**.

Thank you.

Aside to Vincent,

Kindly cancel the assignment.

Please note our office will be closed on 24<sup>th</sup> January 2020 (Friday). Business will resume on 28<sup>th</sup> January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Teo, Grace

**Sent:** Thursday, January 9, 2020 10:28 AM

**To:** 'Vision Autowork' <visionautowork@gmail.com>; 'nsg5vincent@gmail.com' <nsg5vincent@gmail.com>

**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; 'khowyong@yahoo.com.sg' <khowyong@yahoo.com.sg>

**Subject:** CMTD2000147/GPL - RS/ YP731T & GBJ7047T ACC ON 07.01.20

Our Reference: CMTD2000147/GPL

Your Reference: GBJ7047T

**Without Prejudice**

**EMAIL ONLY**

Date: 09/01/2020

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**

**M/S VISION AUTOWORK PTE LTD**

Dear Michelle,

**ACCIDENT INVOLVING YP731T & GBJ7047T ON 07.01.2020**

We refer to your email reply of today.

We will appoint **Raleigh Services** to conduct the survey.

Hi Raleigh Services,

Please make the arrangement to survey for GBJ7047T on a without prejudice basis and revert with your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Please note our office will be closed on 24<sup>th</sup> January 2020 (Friday). Business will resume on 28<sup>th</sup> January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)>

**Sent:** Thursday, January 9, 2020 10:24 AM

**To:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** Re: CMTD2000147/GPL - PRI(LIA)/ YP731T & GBJ7047T ACC ON 07.01.20

Dear All,

Thanks for reply.

Please arrange **Raleigh Services** to survey the above vehicle.

**\*\* Please advise liability after your study the case \*\***

Thank You

Yours faithfully,

Michelle  
Hp: 9856 4815

8 Kaki Bukit Avenue 4,  
#08-09, Premier @ Kaki Bukit,  
Singapore 415875  
Tel: 6341 6789  
Fax: 6341 6778

On Thu, Jan 9, 2020 at 10:12 AM Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference: CMTD2000147/GPL

Your Reference: GBJ7047T

**Without Prejudice**

Date: 09/01/2020

EMAIL ONLY

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**

**M/S VISION AUTOWORK PTE LTD**

Dear Michelle,

**ACCIDENT INVOLVING YP731T & GBJ7047T ON 07.01.2020**

We refer to your Notice of Accident dated 08/01/2020.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/  
[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg) .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey			Selection (Indicate as tick)
	Motor Surveyor	Surveyor	
1	Raleigh Services	Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Aside to Pau Loong,

Please assist on the liability request from **VISION AUTOWORK PTE LTD.**

Please note our office will be closed on 24<sup>th</sup> January 2020 (Friday). Business will resume on 28<sup>th</sup> January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)




**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)>  
**Sent:** Thursday, January 9, 2020 9:52 AM  
**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>  
**Subject:** Re: GBJ7047T (Pre-inspection) / Your vehicle : YP731T

Dear Person In Charge,

Appreciate your can arrange pre-inspection soonest

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,

#08-09,Premier @ Kaki Bukit,

Singapore 415875

Tel: 6341 6789

Fax: 6341 6778

On Wed, Jan 8, 2020 at 5:46 PM Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)> wrote:

Dear Person In Charge,

Attach GIA report for your record

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,

#08-09, Premier @ Kaki Bukit,

Singapore 415875

Tel: 6341 6789

Fax: 6341 6778

On Wed, Jan 8, 2020 at 2:57 PM Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)> wrote:

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**\*\* PLEASE ADVISE LIABILITY\*\***

**\*\* GIA REPORT WILL EMAIL TO YOUR ONCE RECEIVE FROM MY CLIENT \*\***

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,

#08-09, Premier @ Kaki Bukit,

Singapore 415875

Tel: 6341 6789

Fax: 6341 6778

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	138K
Vehicle Details	
Vehicle No.:	GBJ7047T
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KD2859524
Chassis No.:	JTFAT35Y10K213613
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	22 Jul 2019
First Registration Date:	22 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$30,443.00
<b>Total Rebate Amount:</b>	<b>\$30,443.00</b>

The information contained herein is correct as at 16 Jan 2020

OK

> Back to OneMotoring



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Details

Owner ID Type:	Company
Owner ID:	138K

### Vehicle Details

Vehicle No.:	GBJ7047T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KD2859524
Chassis No.:	JTFAT35Y10K213613
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	22 Jul 2019
First Registration Date:	22 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	21 Jul 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$25,600.00
<b>Total Rebate Amount:</b>	<b>\$25,600.00</b>

The information contained herein is correct as at 09 Jan 2020

OK

## RENTAL CAR DEALS



**2014 Mazda 3**  
\$380/week Be it leasing for entirely new vehicles, or long term lease for used vehicle, we are able to assist you. Call us now~!

FIND OUT MORE

Home » Used Cars » ABWIN Bus Pte Ltd » Toyota Dyna 150 3.0M

### Toyota Dyna 150 3.0M

Overview Financial Accessories Similar Research Photos Map



<b>Price</b>	\$59,800	<b>Lifespan</b>	29-May-2039
<b>Depreciation</b> ⓘ	\$6,380 /yr <small>View models with similar depre</small>	<b>Reg Date</b>	30-May-2019 <small>(9yrs 4mths 13days COE left)</small>
<b>Mileage</b>	N.A.	<b>Manufactured</b> ⓘ	2019
<b>Road Tax</b> ⓘ	N.A.	<b>Transmission</b>	Manual
<b>Dereg Value</b> ⓘ	\$22,060 as of today (change)	<b>OMV</b> ⓘ	\$27,082
<b>COE</b> ⓘ	\$23,537	<b>ARF</b> ⓘ	\$1,355
<b>Engine Cap</b>	2,982 cc	<b>No. of Owners</b> ⓘ	1
<b>Curb Weight</b> ⓘ	1,720 kg		
<b>Type of Vehicle</b>	Truck		

**Features**

View specs of the Toyota Dyna 150 (2014)

**Accessories**

New Front Recording Camera, Pioneer Audio System.

**Description**

Take And Go, Still Under Warranty. Don't Worry About Loan As We Provide Flexible In House Loan With Over Trade, Over Loan Available. Call Now.

**Category**

Almost New Car, Premium Ad Car

**Status**

Available

**Resources**



**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more



**Car Valuation - Free**


Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary



Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add note](#)  
[Report Error](#)
[More Actions](#)

Seller Information

**ABWIN Bus Pte Ltd**

162 vehicles for sale. 129 sold in past 3 mths

172 Sin Ming Drive  
 Tel: 69339414  
 Search cars nearby

Dan 83213033  
 MJ 91647884

Posted on: 15-Jan-2020 | Last Updated on: 15-Jan-2020

Upfront Payment

- more Financial info

Tr: Compare

# Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop

to

Advanced Search

Home » New Cars » Toyota Dyna 150 Search Results

## Toyota Dyna 150 Search Results (1 vehicles)

Sort by

results/page

Car Model	Price	Dealer	Built in	User Rating
<b>Toyota Dyna 150</b>		Parallel Importers	<b>Japan</b>	<input type="button" value="Rate it"/>
 3.0 (M)	<b>\$69,000</b> \$8,000 /yr	• 10.3km/l   142bhp   5-speed (M)		
3.0 (M) <input type="button" value="FACTORY"/>	<b>\$70,000</b>	• 10.3km/l   142bhp   5-speed (M)		
3.0 (A)	<b>\$73,000</b>	• 10.3km/l   142bhp   5-speed (A)		

Car Model Price Dealer Built in User Rating

results/page

1 result(s) for **Toyota Dyna 150** models no longer being sold by local distributors  
View all [past Toyota cars](#)



Toyota Dyna 150 (2008-2009)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

## WorldUniExpo@Suntec Fri 10 Jan

Bring your results for Application Fee waivers. Speak to Uni Staff & our Senior counsellor OverseasEducation.sg

**SEARCH**  
 Min Price  to No Max  
 Depreciation  
 Vehicle Type  
 Category

Home » New Cars » toyota dyna Search Results

### toyota dyna Search Results (1 vehicles)

Sort by Most Popular  15 results/page

Car Model	Price	Dealer	Built In	User Rating
<b>Toyota Dyna 150</b>		Parallel Importers	Japan	No Ratings yet
<input type="checkbox"/> 3.0 (M)	<b>\$69,000</b> <small>\$8,000 /yr</small>	• 10.3km/l   142bhp   5-speed (M)		<input type="button" value="Rate It"/>
<input type="checkbox"/> 3.0 (M) <small>FACILITY</small>	<b>\$70,000</b>	• 10.3km/l   142bhp   5-speed (M)		
<input type="checkbox"/> 3.0 (A)	<b>\$73,000</b>	• 10.3km/l   142bhp   5-speed (A)		

Car Model	Price	Dealer	Built In	User Rating

15 results/page

1 result(s) for **toyota dyna** models no longer being sold by local distributors  
View all [past Toyota cars](#)



Toyota Dyna 150 (2008-2009)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000147/GPL

Date: 16 Jan 2020

Our Ref: CS/SMO20000583/Ayd3

The Motor Claims Department  
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. GBJ7047T .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/01/2020 at the premises of M/s VISION AUTOWORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>65,612.85</u> .
Revised Estimate Amount	: S\$ <u>19,089.57</u> .
"Check" Items Amount	: S\$ <u>15,477.62</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Adrian Ling  
Licensed Appraiser

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/01/2020 13:13
Date Of Accident	07/01/2020 14:10
Exact Location Of Accident	BKE>WDLANDS(AFTER BUKIT PANJANG RD EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ7047T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOPMAST ENGINEERING PTE LTD
Co Reg No	2XXXXX138K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62580352

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111176361
Cover Note Number	PREFERRED WORKSHOP PLAN

### Driver

Name of Driver	MOHAMMED RAFIT BIN KARIM
NRIC No	SXXXX165E
Date Of Birth	31/07/1969
Occupation	OUTDOOR
Date Of Driving Pass	26/04/2008
Driving Experience	11 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93635154
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	15 YISHUN INDUSTRIAL STREET 1 #03-17
Postcode	768091
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP731T
Vehicle Make/Model/Colour	MITSUBISHI / FUSO FM65FM2RDEB
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	MOHAMMED RAFIT BIN KARIM
Approximate Age	
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	GBJ7047T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	15 YISHUN INDUSTRIAL STREET 1 #03-17
Postcode	730012

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Name:  
NRIC/  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to attached*

DECLARATION

(We declare the above particulars are true in every respect.)



Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

## Accident Sketch Plan

On 07.01.20 at about 14:10 hours along BKE towards Woodlands (After Bukit Panjang Road Exit). I was travelling straight on lane 2, suddenly vehicle (B) cut into my lane from my left without checking the oncoming traffic and collided onto front left hand side of my vehicle (A).

Vehicle (A): GBJ 7047T

Vehicle (B): YP 731T



# Vision Autowork Pte.Ltd.

( ROC / GST Reg. No. 201500371E)  
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
 Singapore 415875  
 Tel : 6341 6789 Fax: 6341 6778  
 E-mail:visionautowork@gmail.com

DATE : 07.01.20

TO : SOMPO MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBJ7047T  
 MODEL : TOYOTA DYNA  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER <i>2 yrs</i>	1	\$ 727.10	\$ 727.10	+
2	FRONT BUMPER BRACKET LH <i>2 yrs</i>	1	\$ 253.30	\$ 253.30	+
3	FRONT BUMPER FOGLAMP LH	1	\$ 439.40	\$ 439.40	+
4	FRONT GRILLE <i>Cracked</i>	1	\$ 795.20	\$ 795.20	✓
5	FRONT GRILLE LOGO <i>for</i>	1	\$ 88.10	\$ 88.10	✓
6	FRONT PANEL <i>Disbled</i>	1	\$ 1,156.70	\$ 1,156.70	✓
7	FRONT PANEL EMBLEM 'DYNA' <i>new</i>	1	\$ 96.20	\$ 96.20	✓
8	FRONT WINDSCREEN RUBBER <i>new</i>	1	\$ 363.50	\$ 363.50	✓
9	FRONT WINDSCREEN GLASS <i>Shattered</i>	1	\$ 1,532.70	\$ 1,532.70	✓
10	FRONT WIPER PANEL (OUTER) <i>Disbled</i>	1	\$ 476.20	\$ 476.20	✓
11	FRONT WIPER PANEL (INNER) <i>Disbled</i>	1	\$ 798.30	\$ 798.30	✓
12	FRONT WIPER PANEL SIDE SUPPORT BRACKET LH <i>Best</i>	1	\$ 64.20	\$ 64.20	✓
13	FRONT WIPER BLADE <i>lot</i>	2	\$ 72.60	\$ 145.20	✓
14	FRONT WIPER ARM <i>LH Best</i>	2	\$ 179.80	\$ 359.60	179.80
15	FRONT WIPER LINKAGE <i>?</i>	1	\$ 293.40	\$ 293.40	?
16	FRONT WIPER LINKAGE MOTOR <i>?</i>	1	\$ 678.80	\$ 678.80	?
17	FRONT NOZZLE LH <i>new</i>	1	\$ 47.40	\$ 47.40	+
18	HEAD LAMP <i>++ cruld</i>	2	\$ 981.30	\$ 1,962.60	✓
19	HEAD LAMP LOWER RUBBER <i>New</i>	2	\$ 47.20	\$ 94.40	✓
20	FRONT CORNER PANEL <i>RH Disbled</i>	2	\$ 329.80	\$ 659.60	529.80
21	FRONT CORNER TOP JOINT GARNISH LH <i>cruld</i>	1	\$ 26.40	\$ 26.40	✓
22	FRONT CORNER SUPPORT PANEL BRACKET LH <i>Best</i>	1	\$ 75.30	\$ 75.30	✓
23	SIDE MIRROR LH <i>lot</i>	1	\$ 588.50	\$ 588.50	✓
24	SIDE MIRROR STAND LH (AUTO) <i>Best</i>	1	\$ 678.40	\$ 678.40	✓
25	SIDE MIRROR TOP COVER LH <i>lot</i>	1	\$ 32.60	\$ 32.60	✓
26	SIDE MIRROR ROUND LH <i>Ne new</i>	1	\$ 185.40	\$ 185.40	X

TO : SOMPO MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBJ7047T  
 MODEL : TOYOTA DYNA  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

27	FRONT DOOR PILLAR (INNER) LH	<del>Repl</del> ?	1	\$ 894.50	\$ 894.50	?
28	FRONT DOOR PILLAR (OUTER) LH	Distorted	1	\$ 894.30	\$ 894.30	✓
29	FRONT DOOR PILLAR INNER GARNISH LH	Cracked	1	\$ 247.10	\$ 247.10	✓
30	FRONT PILLAR SUPPORT BAR	?	1	\$ 946.30	\$ 946.30	?
31	FRONT STEP PANEL GARNISH LH	new	1	\$ 318.90	\$ 318.90	x
32	FRONT DOOR LH	Distorted	2	\$ 1,769.70	\$ 3,539.40	1769.70
33	FRONT DOOR FRAME RUBBER LH	new	1	\$ 236.10	\$ 236.10	+
34	FRONT DOOR INNER RUBBER LH	lt	1	\$ 201.40	\$ 201.40	✓
35	FRONT DOOR OUTER MOULDING LH	Distorted	1	\$ 191.10	\$ 191.10	✓
36	FRONT DOOR HINGE LH	Best	2	\$ 78.90	\$ 157.80	✓
37	FRONT DOOR CHECKER LH	Best	1	\$ 149.50	\$ 149.50	✓
38	FRONT DOOR WEATHER STRIP LH	lt	1	\$ 195.60	\$ 195.60	✓
39	FRONT DOOR ARCH RUBBER LH	Distorted	1	\$ 264.60	\$ 264.60	✓
40	FRONT DOOR GLASS CHANNEL LH	?	1	\$ 198.10	\$ 198.10	?
41	FRONT DOOR INNER LOCK LH	2nd	1	\$ 306.40	\$ 306.40	✓
42	FRONT DOOR LOCK INNER HANDLE LH	new	1	\$ 327.70	\$ 327.70	x
43	FRONT DOOR LOCK CATCH LH	new	1	\$ 42.10	\$ 42.10	+
44	FRONT DOOR POWER SWITCH CONTROL C/W PANEL	new	2	\$ 545.40	\$ 1,090.80	x
45	FRONT DOOR STOPPER LH	new	2	\$ 19.80	\$ 39.60	+
46	FRONT DOOR INNER HOLDER	new	2	\$ 64.10	\$ 128.20	+
47	FRONT DOOR INNER TRIM BOARD	LT Cracked	2	\$ 942.60	\$ 1,885.20	942.60
48	FRONT DOOR GLASS LH	Shattered	1	\$ 725.90	\$ 725.90	✓
49	FRONT DOOR GLASS SIDE GARNISH LH	new	1	\$ 96.40	\$ 96.40	x
50	FRONT DOOR POWER WINDOW MOTOR LH	new	1	\$ 596.30	\$ 596.30	+
51	FRONT DOOR REGULATOR LH	?	1	\$ 436.60	\$ 436.60	?
52	FRONT DOOR WIRE HARNESS LH	new	1	\$ 769.40	\$ 769.40	+
53	FRONT DOOR SPEAKER LH	new	1	\$ 348.10	\$ 348.10	x
54	FRONT WHEEL ARCH PANEL LH	Repair	1	\$ 649.90	\$ 649.90	+
55	FRONT WHEEL ARCH RUBBER LH	Distorted	1	\$ 365.40	\$ 365.40	+
56	FRONT FLOOR PANEL SIDE GARNISH LH	Distorted	1	\$ 343.10	\$ 343.10	✓
57	FRONT DASHBOARD	Distorted	1	\$ 1,250.40	\$ 1,250.40	✓
58	FRONT DASHBOARD GLOVE COMPARTMENT C/W AIRBAG	?	1	\$ 3,878.20	\$ 3,878.20	?
59	FRONT DASHBOARD CENTER LOWER COVER GARNISH	?	1	\$ 396.40	\$ 396.40	?
60	FRONT DASHBOARD SWITCH CONTROL PANEL	?	1	\$ 764.30	\$ 764.30	?
61	FRONT SPEEDOMETER	?	1	\$ 1,151.70	\$ 1,151.70	?

TO : SOMPO MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBJ7047T  
 MODEL : TOYOTA DYNA  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

62	FRONT SPEEDOMETER COVER ?	1	\$ 346.30	\$ 346.30	?
63	AIR BAG CONTROL UNIT ?	1	\$ 782.20	\$ 782.20	?
64	FRONT ROOF LINING <i>Coupled</i>	1	\$ 1,388.90	\$ 1,388.90	-
65	CARBIN HINGE (FRONT) <i>new</i>	1	\$ 2,468.30	\$ 2,468.30	+
66	CABIN ROOF PANEL <i>Rejis</i>	1	\$ 1,758.10	\$ 1,758.10	+
67	CABIN ROOF SIDE PANEL (INNER) LH <i>Rejis</i>	1	\$ 285.70	\$ 285.70	+
68	CABIN ROOF SIDE PANEL (OUTER) LH <i>Rejis</i>	1	\$ 348.60	\$ 348.60	+
69	CABIN BACK PILLAR (OUTER) LH <i>Rejis</i>	1	\$ 469.90	\$ 469.90	+
70	CABIN BACK PILLAR (INNER) LH <i>Rejis</i>	1	\$ 327.80	\$ 327.80	+
71	CABIN BACK CHASSIS MEMBER LH <i>Rejis</i>	1	\$ 896.70	\$ 896.70	+
72	CABIN CHASSIS MEMBER COVER GARNISH LH <i>new</i>	1	\$ 87.40	\$ 87.40	+
73	CABIN LOCK SYSTEM <i>new</i>	1	\$ 983.10	\$ 983.10	+
74	CABIN FLOORPANEL <i>Rejis</i>	1	\$ 2,414.40	\$ 2,414.40	+
75	CABIN FLOOR MATT <i>new</i>	1	\$ 863.70	\$ 863.70	+
76	WASHER TANK ?	1	\$ 168.30	\$ 168.30	?
77	AIR CON CONDENSER ?	1	\$ 987.70	\$ 987.70	?
78	AIR CON CONDENSER SUPPORT BRACKET ?	1	\$ 236.30	\$ 236.30	?
79	AIR CON CONDENSER FAN MOTOR C/W COWLING ?	1	\$ 429.80	\$ 429.80	?
80	AIR CON BLOWER ?	1	\$ 1,758.60	\$ 1,758.60	?
81	AIR CON COOLING COIL ?	1	\$ 2,379.20	\$ 2,379.20	?
82	AIR CON HEATER ?	1	\$ 983.80	\$ 983.80	?
83	AIR CON PIPE ?	2	\$ 396.50	\$ 793.00	?
84	FRONT WIRE HARNESS <i>new</i>	1	\$ 7,200.70	\$ 7,200.70	+

TOTAL PRICE \$ 65,003.80  
 LESS 25% \$ 16,250.95  
 SUB TOTAL PRICE \$ 48,752.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	LED LIGHT (SPECIAL TYPE) (SET) <i>new</i>	1	\$ 480.00	\$ 480.00	+
3	FRONT WINDSCREEN GLASS SEALANT <i>Rejis</i>	1	\$ 80.00	\$ 80.00	40
4	FRONT WINDSCREEN GLASS INNER SEAL <i>Rejis</i>	1	\$ 60.00	\$ 60.00	40
5	FRONT ERP BRACKET <i>new</i>	1	\$ 40.00	\$ 40.00	26
6	FRONT DOOR PILLAR SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	X
7	FRONT DOOR LTA STICKER <i>new</i>	1	\$ 40.00	\$ 40.00	30
8	FRONT FLOOR PANEL SIDE GARNISH CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20

TO : SOMPO MOTOR CLAIMS DEPTS  
 VEHICLE NO : GBJ7047T  
 MODEL : TOYOTA DYNA  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

9	FRONT DASHBOARD CLIP (SET) <i>Mc</i>	1	\$ 150.00	\$ 150.00	<i>50</i>
10	FRONT ROOF LINING CLIP (SET) <i>Mc</i>	1	\$ 150.00	\$ 150.00	<i>80</i>
11	CABIN ROOF SIDE PANEL (INNER) SEALANT LH <i>2 yr</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	CABIN ROOF SIDE PANEL (OUTER) SEALANT LH <i>Mc</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
13	CABIN CHASSIS MEMBER COVER GARNISH CLIP LH (SET) <i>Mc</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
14	RADIO <i>Mc</i>	1	\$ 1,200.00	\$ 1,200.00	<i>+</i>

TOTAL \$ 2,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 4,800.00	<i>2400</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 2,800.00	<i>1600</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>X</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 380.00	<i>200</i>
7	TRANSFER FRONT DOOR MECHANISM X2	\$ 180.00	<i>80</i>
8	REMOVE AND REFIX AND AUDIO SYSTEM	\$ 200.00	<i>120</i>
9	REMOVE AND REFIX AIR CON BLOWER AND AIR CON CENDENSER	\$ 400.00	<i>?</i>
10	REMOVE AND REFIX CABIN	\$ 1,200.00	<i>?</i>
11	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>X</i>
12	REMOVE AND REFIX DASHBOARD	\$ 650.00	<i>220</i>
13	REMOVE AND REFIX WIRE HARNESS	\$ 1,800.00	<i>X</i>
14	RESET AIR BAG SYSTEM	\$ 550.00	<i>X</i>
15	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	<i>✓</i>

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ7047T**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

16	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$	<del>350.00</del> 100
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00 x
<b>TOTAL</b>		<b>\$</b>	<b>14,180.00</b>

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 51,432.85  
 TOTAL LABOUR COST : \$ 14,180.00  
 TOTAL REPAIR COST : \$ 65,612.85

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

*ABBY*  
 SERVICE ADVISOR  
 ABBY (HP:9856 4815)

*Adrian Lij*  
 2/c 09/01/20.  
 21 Days.



TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ7047T**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

QTY	DESCRIPTION	UNIT	UNIT PRICE	TOTAL PRICE	REMARKS
27	FRONT DOOR PILLAR (INNER) LH <i>Replaced</i>	1	\$ 894.50	\$ 894.50	✓
28	FRONT DOOR PILLAR (OUTER) LH <i>Distorted</i>	1	\$ 894.30	\$ 894.30	✓
29	FRONT DOOR PILLAR INNER GARNISH LH <i>Cracked</i>	1	\$ 247.10	\$ 247.10	✓
30	FRONT PILLAR SUPPORT BAR <i>Best</i>	1	\$ 946.30	\$ 946.30	✓
31	FRONT STEP PANEL GARNISH LH <i>new</i>	1	\$ 318.90	\$ 318.90	+
32	FRONT DOOR LH <i>Distorted</i>	2	\$ 1,769.70	\$ 3,539.40	1769.70
33	FRONT DOOR FRAME RUBBER LH <i>new</i>	1	\$ 236.10	\$ 236.10	+
34	FRONT DOOR INNER RUBBER LH <i>ut</i>	1	\$ 201.40	\$ 201.40	✓
35	FRONT DOOR OUTER MOULDING LH <i>Distorted</i>	1	\$ 191.10	\$ 191.10	✓
36	FRONT DOOR HINGE LH <i>Best</i>	2	\$ 78.90	\$ 157.80	✓
37	FRONT DOOR CHECKER LH <i>Best</i>	1	\$ 149.50	\$ 149.50	✓
38	FRONT DOOR WEATHER STRIP LH <i>ut</i>	1	\$ 195.60	\$ 195.60	✓
39	FRONT DOOR ARCH RUBBER LH <i>Distorted</i>	1	\$ 264.60	\$ 264.60	✓
40	FRONT DOOR GLASS CHANNEL LH <i>Best</i>	1	\$ 198.10	\$ 198.10	✓
41	FRONT DOOR INNER LOCK LH <i>Distorted</i>	1	\$ 306.40	\$ 306.40	✓
42	FRONT DOOR LOCK INNER HANDLE LH <i>new</i>	1	\$ 327.70	\$ 327.70	+
43	FRONT DOOR LOCK CATCH LH <i>new</i>	1	\$ 42.10	\$ 42.10	+
44	FRONT DOOR POWER SWITCH CONTROL CW PANEL <i>new</i>	2	\$ 545.40	\$ 1,090.80	+
45	FRONT DOOR STOPPER LH <i>new</i>	2	\$ 19.80	\$ 39.60	+
46	FRONT DOOR INNER HOLDER <i>new</i>	2	\$ 64.10	\$ 128.20	+
47	FRONT DOOR INNER TRIM BOARD <i>LH Cracked</i>	2	\$ 942.60	\$ 1,885.20	942.60
48	FRONT DOOR GLASS LH <i>Shattered</i>	1	\$ 725.90	\$ 725.90	✓
49	FRONT DOOR GLASS SIDE GARNISH LH <i>new</i>	1	\$ 96.40	\$ 96.40	+
50	FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 596.30	\$ 596.30	+
51	FRONT DOOR REGULATOR LH <i>Distorted</i>	1	\$ 436.60	\$ 436.60	✓
52	FRONT DOOR WIRE HARNESS LH <i>new</i>	1	\$ 769.40	\$ 769.40	+
53	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 348.10	\$ 348.10	+
54	FRONT WHEEL ARCH PANEL LH <i>Repair</i>	1	\$ 649.90	\$ 649.90	+
55	FRONT WHEEL ARCH RUBBER LH <i>Distorted</i>	1	\$ 365.40	\$ 365.40	+
56	FRONT FLOOR PANEL SIDE GARNISH LH <i>Distorted</i>	1	\$ 343.10	\$ 343.10	✓
57	FRONT DASHBOARD <i>Distorted</i>	1	\$ 1,250.40	\$ 1,250.40	✓
58	FRONT DASHBOARD GLOVE COMPARTMENT CW AIRBAG <i>Distorted</i>	1	\$ 3,878.20	\$ 3,878.20	✓
59	FRONT DASHBOARD CENTER LOWER COVER GARNISH <i>Cracked</i>	1	\$ 396.40	\$ 396.40	✓
60	FRONT DASHBOARD SWITCH CONTROL PANEL <i>Cracked</i>	1	\$ 764.30	\$ 764.30	✓
61	FRONT SPEEDOMETER <i>Cracked</i>	1	\$ 1,151.70	\$ 1,151.70	✓

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ7047T**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

62	FRONT SPEEDOMETER COVER <i>could</i>	1	\$ 346.30	\$ 346.30	-
63	AIR BAG CONTROL UNIT <i>new</i>	1	\$ 782.20	\$ 782.20	+
64	FRONT ROOF LINING <i>could</i>	1	\$ 1,388.90	\$ 1,388.90	-
65	CARBIN HINGE (FRONT) <i>new</i>	1	\$ 2,468.30	\$ 2,468.30	+
66	CABIN ROOF PANEL <i>Revis</i>	1	\$ 1,758.10	\$ 1,758.10	+
67	CABIN ROOF SIDE PANEL (INNER) LH <i>Revis</i>	1	\$ 285.70	\$ 285.70	+
68	CABIN ROOF SIDE PANEL (OUTER) LH <i>Revis</i>	1	\$ 348.60	\$ 348.60	+
69	CABIN BACK PILLAR (OUTER) LH <i>Revis</i>	1	\$ 469.90	\$ 469.90	+
70	CABIN BACK PILLAR (INNER) LH <i>Revis</i>	1	\$ 327.80	\$ 327.80	+
71	CABIN BACK CHASSIS MEMBER LH <i>Revis</i>	1	\$ 896.70	\$ 896.70	+
72	CABIN CHASSIS MEMBER COVER GARNISH LH <i>new</i>	1	\$ 87.40	\$ 87.40	+
73	CABIN LOCK SYSTEM <i>new</i>	1	\$ 983.10	\$ 983.10	+
74	CABIN FLOORPANEL <i>Revis</i>	1	\$ 2,414.40	\$ 2,414.40	+
75	CABIN FLOOR MATT <i>new</i>	1	\$ 863.70	\$ 863.70	+
76	WASHER TANK <i>Detail</i>	1	\$ 168.30	\$ 168.30	✓
77	AIR CON CONDENSER <i>Detail</i>	1	\$ 987.70	\$ 987.70	✓
78	AIR CON CONDENSER SUPPORT BRACKET <i>Best</i>	1	\$ 236.30	\$ 236.30	✓
79	AIR CON CONDENSER FAN MOTOR C/W COWLING <i>could</i>	1	\$ 429.80	\$ 429.80	✓
80	AIR CON BLOWER <i>could</i>	1	\$ 1,758.60	\$ 1,758.60	✓
81	AIR CON COOLING COIL <i>could</i>	1	\$ 2,379.20	\$ 2,379.20	✓
82	AIR CON HEATER <i>new</i>	1	\$ 983.80	\$ 983.80	+
83	AIR CON PIPE <i>Best</i>	2	\$ 396.50	\$ 793.00	✓
84	FRONT WIRE HARNESS <i>new</i>	1	\$ 7,200.70	\$ 7,200.70	+

35341  
26505.75

TOTAL PRICE \$ 65,003.80  
 LESS 25% \$ 16,250.95  
 SUB TOTAL PRICE \$ 48,752.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	LED LIGHT (SPECIAL TYPE) (SET) <i>new</i>	1	\$ 480.00	\$ 480.00	+
3	FRONT WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
4	FRONT WINDSCREEN GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	40
5	FRONT ERP BRACKET <i>new</i>	1	\$ 40.00	\$ 40.00	26
6	FRONT DOOR PILLAR SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	FRONT DOOR LTA STICKER <i>new</i>	1	\$ 40.00	\$ 40.00	30
8	FRONT FLOOR PANEL SIDE GARNISH CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ7047T**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

9	FRONT DASHBOARD CLIP (SET) <i>MC</i>	1	\$ 150.00	\$ 150.00	<i>50</i>
10	FRONT ROOF LINING CLIP (SET) <i>MC</i>	1	\$ 150.00	\$ 150.00	<i>80</i>
11	CABIN ROOF SIDE PANEL (INNER) SEALANT LH <i>2</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	CABIN ROOF SIDE PANEL (OUTER) SEALANT LH <i>2</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
13	CABIN CHASSIS MEMBER COVER GARNISH CLIP LH (SET) <i>MC</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
14	RADIO <i>MC</i>	1	\$ 1,200.00	\$ 1,200.00	<i>+</i>
<i>286</i>			<b>TOTAL</b>	<b>\$ 2,680.00</b>	

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 4,800.00	<i>2400 2800</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 2,800.00	<i>1600</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 380.00	<i>200</i>
7	TRANSFER FRONT DOOR MECHANISM X2	\$ 180.00	<i>80</i>
8	REMOVE AND REFIX AND AUDIO SYSTEM	\$ 200.00	<i>120</i>
9	REMOVE AND REFIX AIR CON BLOWER AND AIR CON CENDENSER	\$ 400.00	<i>80</i>
10	REMOVE AND REFIX CABIN	\$ 1,200.00	<i>600</i>
11	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
12	REMOVE AND REFIX DASHBOARD	\$ 650.00	<i>220</i>
13	REMOVE AND REFIX WIRE HARNESS	\$ 1,800.00	<i>x</i>
14	RESET AIR BAG SYSTEM	\$ 550.00	<i>380</i>
15	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	<i>✓</i>

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ7047T**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 07.01.20  
 TIME OF ACCIDENT : 14:10HRS

16	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$ 350.00	100
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

**TOTAL \$ 14,180.00** 6450

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 51,432.85  
 TOTAL LABOUR COST : \$ 14,180.00  
 TOTAL REPAIR COST : \$ 65,612.85

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**ABBY**

SERVICE ADVISOR  
 ABBY (HP:9856 4815)

Adrian Lij  
 r/s 09/01/20.

28 Days.

total: 83241.75  
 L/S: 26.5K

26.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: