

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
Chang Hock Yan (Zhang Fuyan) Blk 688B Choa Chu Kang Drive #18-324 Singapore 682688 Contact No Mobile: 97715021	Cust No/Name	/Chang Hock Yan (Zhang Fuyan)
	Reg No/Reg Date	SGZ1789G / 28/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5745994
	Engine No	G4FGHH679729
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	07/01/2020/ 17:29	QUK	282 / Kevin Leong	64677		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPLACE REAR BUMPER, REAR BODY KIT & AFFECTED AREA TO REPAIR ON REAR LH FENDER, BOOT & END PANEL X							550.2200.00
E PNT98000 PAINT WORK ON REAR BUMPER, REAR LH FENDER, END PANEL & BOOT 420							1260 1680.00
E PNT88000 TO REMOVE & INSTALL REAR PARKING ASSIST							✓ 150.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA							nn X 80.00
M SUNDRY PERFORM RUST PREVENTION							nn X 160.00
A 54900099 CHECK ELECTRICAL SYSTEM							✓ 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							✓ 180.00
M SUNDRY TO SUPPLY C & C EMBLEM							nn X 50.00
M SUNDRY SUNDRIES							20 50.00
M	EMBLEM-CERATO			1.00	35.00	00.00	nn { +35.00
M	LOGO ASSY-KIA SUB			1.00	37.00	00.00	nn { +37.00
M	COVER-RR BUMPER,CTR			1.00	347.00	00.00	nn { 347.00
M	COVER-RR BUMPER			1.00	688.00	00.00	de ✓ 688.00
M	BRACKET-RR BEAM LWR MTG			2.00	5.00	00.00	nn ✓ 10.00
M	BRACKET-RR BEAM LWR,CTR			1.00	5.00	00.00	nn ✓ 5.00
M	BEAM-RR BUMPER			1.00	318.00	00.00	nn X 318.00
M	ANTENNA ASSY-SMARTKEY			1.00	69.00	00.00	nn X 69.00
M	BRACKET-RR BEAM UPR MTG			1.00	3.00	00.00	nn ✓ 3.00
M	BRACKET-RR BEAM UPR MTG,RH			1.00	3.00	00.00	X 3.00
M	STAY-RR BUMPER LH			1.00	120.00	00.00	X 120.00
M	STAY-RR BUMPER RH			1.00	120.00	00.00	X 120.00
M	BRACKET-RR BUMPER SIDE MTG,LH			1.00	29.00	00.00	nn ✓ 29.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : TAUFIKH LKK
Claim : TP MS FIRST CAPITA
DOA : 20.12.2019
Emailed : 14.02.2020, 9.30am
Date survey : 14.01.2020

VEHICLE NO : SGZ 1789 G
MODEL : KIA CERATO K3 1.6 A SX
WIP : 64677

Material	:	\$	<u>2,436.00</u>
Labour	:	\$	<u>2,240.00</u>
Sub-Total	:	\$	<u>4,676.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,676.00</u>
GST 7%	:	\$	<u>327.32</u>
Grand Total	:	\$	<u>5,003.32</u>
Finalise By/Date	:	<u>LOI / 14/02/2020</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 7


☒ TP claim SHC7545M

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited Motor Claims Department 36 Robinson Road #16-01 City House Singapore 068877 Contact No 14/01/2020	Cust No/Name	/Chang Hock Yan (Zhang Fuyan)
	Reg No/Reg Date	SGZ1789G / 28/09/2017
	Date In/Mileage	14/01/2020/ 45000
	Chassis/Package	KNAFZ411MJ5745994 /KC17P
	Engine No	G4FGHH679729
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	12/02/2020/ 15:16	TLK	260 / AiTing	64677

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR BODY KIT, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, LH REAR FENDER, REAR BODY KIT, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1260.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR				✓ 150.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 80.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 180.00
M SUNDRY SUNDRIES				✓ 20.00
X COVER-RR BUMPER,CTR	1.00	? 347.00	00.00	347.00
X COVER-RR BUMPER	1.00	✓ 688.00	00.00	688.00
X BRACKET-RR BEAM LWR MTG	2.00	✓ 5.00	00.00	10.00
X BRACKET-RR BEAM LWR,CTR	1.00	✓ 5.00	00.00	5.00
X BRACKET-RR BEAM UPR MTG	1.00	✓ 3.00	00.00	3.00
X BRACKET-RR BUMPER SIDE MTG,LH	1.00	✓ 29.00	00.00	29.00
X ULTRASONIC SENSOR ASSY-P.A.S	1.00	✓ 177.00	00.00	177.00
X BODY KITS	1.00	✓ 1177.00	00.00	1177.00
Z TEXT TP CLAIM MS FIRST CAPITAL SHC7545M DOA : 20.12.19 SURVEYOR TAUFIKH LKK 14.01.20 REPAIR 05 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,436.00	Nett	4,676.00
Labour	2,220.00	7% GST on	4676.00
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,003.32
Sundry/Others	20.00		
Total(w/o GST)	4,676.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.