

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SKH 2567 X**
Made : Volkswagen
Model : Scirocco 2010
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 1,957.30	\$ 1,957.30
2	Front bumper side retainer	2	\$ 65.30 325.10	\$ 130.60 650.20
3	Front bumper lower lip	1	\$ 386.40	\$ 386.40
4	Front bumper fog lamp LH	1	\$ 426.20	\$ 426.20
5	Front bumper signal lamp LH	1	\$ 378.60	\$ 378.60
6	Front bumper fog lamp garnish LH	1	\$ 421.50	\$ 421.50
7	Front fender LH	1	\$ 895.00 1,678.30	\$ 895.00 1,678.30
8	Front fender inner cowl LH	1	\$ 462.10	\$ 462.10
9	Headlamp LH	1	\$ 1,469.20	\$ 1,469.20
10	Headlamp lower bracket LH	1	\$ 412.60	\$ 412.60
11	Side skirt LH	1	\$ 413.60	\$ 413.60
12	Front door LH	1	\$ 1,953.80	\$ 1,953.80
13	Front door lock	1	\$ 786.30	\$ 786.30
14	Front door lock sticker	1	\$ 106.20	\$ 106.20
15	Front door inner trim board LH	1	\$ 789.60	\$ 789.60
16	Front door weatherstrip LH	1	\$ 387.20	\$ 387.20
17	Front door outer garnish LH	1	\$ 365.90	\$ 365.90
18	Front side mirror assy LH	1	\$ 985.20	\$ 985.20
19	Front lower arm LH	1	\$ 456.20	\$ 456.20
20	Front knuckle arm LH	1	\$ 523.10	\$ 523.10
21	Front knuckle arm bearing LH	1	\$ 459.30	\$ 459.30
			Parts Sub Total :	\$ 4359.55 15,468.80
			10% Discount	\$ 435.96 1,546.88
			PARTS TOTAL :	\$ 3923.59 13,921.92

CUTV ✓
NECV ✓
BRV ✓
NDX
NDX
DDV ✓
?BRV ✓
CUTV ✓
?NSPX
NDX
R-X
ND
NDX
CUTV ✓
?NDX
?SCR ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Front bumper clips	1	\$ 50.00	\$ 30.00 50.00	nec
3	Front bumper lower lip clips	1	\$ 50.00	\$ 30.00 50.00	nec
4	Front fender sealant	1	\$ 80.00	\$ 30.00 80.00	nec
5	Front fender inner cowling clips	1	\$ 50.00	\$ 50.00	?NEC✓
6	Side skirt clips	1	\$ 50.00	\$ 50.00	NNX
7	Front door sealant	1	\$ 80.00	\$ 80.00	NNX
8	Front door inner trim board clips	1	\$ 50.00	\$ 50.00	NNX
9	Front door outer garnish clips	1	\$ 50.00	\$ 50.00	NNX
10	Side mirror seal	1	\$ 80.00	\$ 80.00	NNX
11	Alloy rim LH <i>local repair</i> scr	1	\$ 850.00	\$ 300.00 850.00	R✓
12	Tyre LH	1	\$ 350.00	\$ 350.00	NDX
SPECIAL NETT TOTAL :				\$ 440.00 1,820.00	

Nos.	LABOUR	S\$	
1	R&R front door component	\$ 100.00	nn
2	Panel beating	\$ 800.00 1,200.00	
3	Spray painting	\$ 800.00 1,200.00	
4	R&R Front undercarriage	\$ 70.00 150.00	NNX
5	R&R front tyre and balancing	\$ 150.00	NNX
6	Conduct water leakage test	\$ 150.00	NNX
7	Diagnostic & reset fault code	\$ 300.00	NNX
8	Wiring / bulb checking	\$ 100.00	NNX
9	Wheel alignment	\$ 60.00 100.00	
LABOUR TOTAL :		\$ 1730.00 3,450.00	

Burvey 10/1/2020
1430 hrs

TGrim Lin
Lump sum

Resurvey on 13/1/2020
TGrim Lin

Repair days 5

PARTS TOTAL : \$ 8923.59 13,921.92
SPECIAL NETT TOTAL : \$ 440.00 1,820.00
LABOUR TOTAL : \$ 1730.00 3,450.00
GRAND TOTAL : \$ 19,191.92

@ 20%

6093.59
1218.72
4874.87

L/S 4850/2

TGrim Lin
21/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: