

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopi@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SJB 5317 A**

Make : Toyota

Model : Picnic

Chassis No :

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	BONNET	1	\$ 1,120.00	\$ 1,120.00
2	BONNET CHROME GRILLE	1	\$ 683.40	\$ 683.40
3	BONNET LOCK	1	\$ 134.00	\$ 134.00
4	BONNET LOCK STRICKER	1	\$ 86.00	\$ 86.00
5	FRONT GRILLE	1	\$ 543.80	\$ 543.80
6	FRONT GRILLE LOGO	1	\$ 106.40	\$ 106.40
7	HEADLAMP RH	1	\$ 1,047.00	\$ 1,047.00
8	HEADLAMP LH	1	\$ 1,047.00	\$ 1,047.00
9	HEADLAMP BRACKET RH	1	\$ 154.00	\$ 154.00
10	HEADLAMP BRACKET LH	1	\$ 154.00	\$ 154.00
11	FRONT BUMPER	1	\$ 1,096.00	\$ 1,096.00
12	FRONT BUMPER SIDE RETAINER	2	\$ 85.00	\$ 170.00
13	FRONT BUMPER CENTER GRILLE	1	\$ 236.80	\$ 236.80
14	FRONT BUMPER INNER SPOOGE	1	\$ 182.00	\$ 182.00
15	FRONT SUPPORT PANEL	1	\$ 658.30	\$ 658.30
16	FRONT FOG LAMP COVER	2	\$ 127.50	\$ 255.00
17	FRONT FOG LAMP	2	\$ 318.20	\$ 636.40
18	RADAIOR	1	\$ 954.70	\$ 954.70
19	AIR CON CONDENSER	1	\$ 862.40	\$ 862.40
20	AIR CON LOW PRESSURE PIPE	1	\$ 243.10	\$ 243.10
21	AIR CON HIGH PRESSURE PIPE	1	\$ 294.40	\$ 294.40
22	RADIATOR FAN COWLING	1	\$ 657.00	\$ 657.00
Parts Sub Total :			\$ 11,483.30	\$ 11,483.30
25% Discount			\$ 2,870.83	\$ 2,870.83
PARTS TOTAL :			\$ 8,612.48	\$ 8,612.48

DDV ✓
BRV ✓
DOV ✓
NDX
NSPX
BRV ✓
NNX
CUTV ✓
NECV ✓
NECV ✓
?BRV ✓
BT ✓
BRV ✓
?NDX
?BT ✓
BT ✓
?NDX
?NDX
7476.88
1869.22
5607.66

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	NUMBER PLATE WITH CASING	1	\$ 80.00	\$ 80.00
2	FRONT GRILLE CLIPS	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 50.00
4	BONNET INSULATOR CLIPS	1	\$ 50.00	\$ 50.00
5	FRONT FOG LAMP CAVER CLIPS	1	\$ 50.00	\$ 50.00
6	FRONT CENTER GRILLE CLIPS	1	\$ 50.00	\$ 50.00
7	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00
8	A/C FLUID	1	\$ 80.00	\$ 80.00
9	SUNDRIES	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :			\$ 570.00	\$ 570.00

NDX
NNX
NEC
NNX
NNX
NNX
?NNX
NECV ✓
NNX

Nos.	LABOUR		SS
1	FRONT PANEL BEATING	\$ 660.00	1,000.00
2	R&R RADIATOR	\$	150.00
3	R&R AIR CON CONDENSER	\$ 120.00	150.00
4	FRONT SPRAY PAINT	\$ 600.00	1,000.00
5	DIAGNOSTIC & RESET FAULT CODE	\$	150.00
6	ALIGNMENT CHASSIS	\$	200.00
7	CHECK WIRING	\$ 50.00	150.00
LABOUR TOTAL :		\$ 1370.00	2,900.00

Survey 10/1/2020

TGLim lin

1600 hrs

Lump sum repair

Resurvey 13/1/2020

TGLim lin

Repair days 5

PARTS TOTAL :	\$5094.36	8,612.48	5,607.66
SPECIAL NETT TOTAL :	\$ 110.00	570.00	110.00
LABOUR TOTAL :	\$1370.00	2,900.00	1370.00
GRAND TOTAL :	\$6574.36	12,082.48	7087.66
@ 20%	1314.87		1417.53
	5259.49		5670.13

L/S 5250/2

TGLim lin
17/1/2020

L/S 5650/2

TGLim lin
3/4/2020

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by:

Signature:

Date:

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: