

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 14 Sept 2018

ASSESSMENT FOR REPAIR: HONDA CBF190WH - FBN568G

Chassis No.: LWBMC4698J1307827

Engine No.: MC46E5064093

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$195.00 X SVL
1 pc	Front wheel axle	\$95.00 X SVL / SCE
1 pc	• R(6H) Left fork assembly	250 \$450.00 X SVL
1 pc	Front cover	\$125.00 / SCE
1 pc	• Headlamp bracket	\$195.00 / BT
1 pc	Front windshield	\$125.00 / SCE
1 pc	Front left signal	\$95.00 / SCE
1 pc	Left fairing assembly	\$215.00 / SCE
1 pc	Fairing ambler left	\$45.00 / N F/L
1 pc	Right fairing assembly	\$215.00 X N F/L
1 pc	Fairing ambler right	\$45.00 X N F/L
2 pcs	• Steering stem bearing @ \$45.00	\$90.00 X SVL
1 pc	- Steering fork bridge	\$280.00 X SVL
1 pc	• Steering stem underbracket	\$295.00 X SVL / DEF
1 pc	Handle bar left	\$175.00 / BT
1 pc	Left view mirror	\$75.00 / SCE
1 pc	Left handle balancer	\$48.00 / SCE
1 pc	Clutch lever	\$48.00 / SCE
1 pc	Left front footrest holder assembly	\$195.00 / DEF
1 pc	left front footrest	\$65.00 / SCE
1 pc	Gear pedal assy	\$105.00 / BT / SCE
1 pc	Side stand	\$95.00 X SVL
1 pc	Mainstand	\$220.00 / jammed
1 pc	Left rear footrest	\$65.00 / SCE
1 pc	Left rear footrest holder	\$185.00 X SVL
		1,791
		250
		90
		2,130
		1,917
	Less discount 10%	\$3,741.00
		\$374.10
		\$3,366.90
	Special nett items	
1 pc	Front sport rim	\$550.00 X SVL
1 pc	Box bracket	\$150.00 X SVL
1 pc	Top box	\$380.00 / SCE
1 pc	Front number plate	\$20.00 / N F/L
1)	Towing charges	\$80.00 /
2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00 300
3)	To knock, straighten chassis & body balancing	\$380.00 X NN
4)	• To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00 X SVL
5)	To remove/refit, replace (if damage) check and replace front sport rim	\$180.00 X NN
6)	Spray painting	\$300.00 100

Total Estimate

\$6,286.90

Note: The above estimate is subjected to the prevailing GST of 7%

NAZUK
16/1/2020 1630

LIS

2 DAYS

TRACK ITEM PHOTO

FREE PAWT PHOTO



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 17 Jan 2020


ASSESSMENT FOR REPAIR: HONDA CBF190WH - FBN568G

Chassis No.: LWBMC4698J1307827

Engine No.: MC46E5064093

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left inner cover	\$85.00 / CRK
1 pc	Meter	\$310.00 / SCR
1 pc	Tank top cover	\$65.00 / BDEF
1 pc	Front meter cover	\$55.00 / SCR
1 pc	Front mudguard	\$120.00 / SCR
1 pc	Right switch	\$145.00 / SCR
1 pc	Right mirror	\$75.00 / SCR
1 pc	Clutch holder	\$55.00 / SCR
		<hr/>
		\$910.00
	Less discount 10%	<hr/>
		\$91.00
		<hr/>
		\$819.00
	<u>Special nett items</u>	
1 pc	ERP IU	\$157.00 / SCR
		<hr/>
	Total Estimate	<hr/>
		\$976.00
		<hr/>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd