

Date: 24.12.2019
Vehicle No: SMR504P
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106695002 - 2017
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMD5205T
Date of Accident: 23.12.2019

*Not Authorised
Newm Bepaim
5day*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT FENDER RH	1	<i>Bj</i>	\$619.75
2	FRONT FENDER "HYBRID" EMBLEM RH	1	<i>M</i>	\$78.75
3	FRONT FENDER INNER LINER RH	1	<i>D.Y</i>	\$153.20
4	FRONT FENDER INNER LINER CLIPS RH	10	\$5.80 <i>M</i>	\$58.00
5	FRONT DOOR RH	1	<i>Bj</i>	\$1,005.90
6	FRONT DOOR FRAME PROTECTIVE STICKER RH	1	<i>M</i>	\$56.10
7	FRONT DOOR INNER TRIM CLIPS RH	10	\$6.20	\$62.00
8	REAR DOOR RH	1	<i>Bj</i>	\$902.30
9	REAR DOOR FRAME PROTECTIVE STICKER RH	1	<i>M</i>	\$56.10
10	REAR DOOR INNER TRIM CLIPS RH	8	\$6.20	\$49.60
11	RUNNING BOARD PANEL RH			REPAIR
12	REAR QUARTER PANEL RH			REPAIR
SUB TOTAL				\$3,041.70
LESS 25%				-\$760.43
PARTS TOTAL				\$2,281.28

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST SIDE ACCIDENT AREAS & ETC \$600.00 ✓

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC \$100.00 *bol*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC \$100.00 *bol*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR QUARTER PANEL RH, RUNNING BOARD PANEL RH & ETC \$1,250.00 *1000*

LABOUR CHARGES TO CHECK DOOR CENTRAL LOCKING & ELECTRICAL WIRING SYSTEMS & ETC \$100.00 *20*

TO TUFF KOTE & UNDERSEAL MATERIALS \$150.00 *90*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$2,300.00

ONG

TOTAL \$4,581.28

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

