FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Qty

Particular

List Item:

SLAT 270T

1PCS REAR WINDSCREEN MOULDING

1PCS TAILGATE

953.00

1PCS TAILGATE OUTER GARNISH

1PCS TAILGATE 'H' LOGO

1PCS TAILGATE 'VEZEL' EMBLEM

2PCS TAILGATE REFLECTORS @\$364.60

1PCS TAILGATE INNER LOCK

1PCS TAILGATE LOCK STRIKER

1PCS TAILGATE INNER TRIM BOARD

1PCS TAILGATE INNER HANDLE HOLDER

2PCS TAILGATE ABSORBERS @\$192.50

1PCS TAILGATE WEATHERSTRIP

1PCS REAR BUMPER

701.00

2PCS REAR BUMPER SIDES @\$295.80

2PCS REAR BUMPER REFLECTORS @\$151.00

1PCS REAR BUMPER CLIPS

1PCS REAR BUMPER UNDER COVER

1SET REAR BUMPER UNDER COVER CLIPS

2PCS REARBUMPER SIDE RETAINERS @\$35.50

1PCS REAR END PANEL

1PCS REAR END PANEL TOP GARNISH

1PCS REAR FLOOR PANEL

1PCS REAR FLOOR PANEL TOP BOARD

13/1/20 1/5 4 5800 1/5 4 5800

Amount S\$

ner \$50.20

\$1100.90

11 \$315.20

1 F \$32.50 X

M \$48.50 X

11 \$729.20 \$

TUI \$181.90 -

19 \$48.60 X

Defer \$368.20

11 \$30.50 X

11 \$385.00 X

1m \$135.20

\$863.50

MSCN \$302.00 PC

NU \$45.00

\$45.00

Nu \$158.40

17 \$71.00 X

m/ser \$514.00

1NI \$86.40 -

人 \$1330.20 人

70ra \$326.90

202

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Tax Reg No : 20-0006262-1)	
Qty <u>Particular</u>	Amount S\$
<u>List Item:</u>	
1PCS REAR FLOOR PANEL TOOLS SPONGE	7011 \$485.30
2PCS TAILLAMPS @\$386.20	ere \$772.40
1PCS REAR LOCK SENSOR	slight \$259.20
2PCS REAR FENDERS @\$891.10	
2PCS REAR FENDER INNER TRIMS @\$279.30	MG701 \$558.40 WC
1PCS REAR EXHAUST MUFFLER	U7 \$777.40 Q
2PCS REAR EXHAUST MUFFLER MOUNTINGS @\$34.90	17 \$69.80 K
1PCS REAR EXHAUST HEAT SHIELD	U7 \$166.50 X
1PCS CENTRE EXHAUST PIPE	1~ \$866.50 X
2PCS CENTRE EXHAUST PIPE MOUNTINGS @\$34.90	17 \$69.80 X
2PCS REAR FENDER OUTER PROTECTORS @\$172.40	of 7000 \$344.80
List Item Total:	\$13,912.20 6157
	202
Special Nett Item:	-4900,00
1PCS REAR WINDSCREEN SEALANT	M \$50.00 40
1PCS REAR END PANEL SEALANT	W. \$80.00 SV
1SET REAR BUMPER REVERSE SENSOR	Shul \$280.00 200
1PCS REAR LICENCE PLATE W/HOLDER	60e \$100.00 60
Special Nett Total:	\$510.00
Labour Charge:	
TO CHECK WIRING.	200 00 30
	\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.	\$100.00 10

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Qty Particular	Amount S\$
Labour Charge:	
TO DISMANTLE & REFIX REAR WINDSCREEN.	\$150.00 /20
TO DISMANTLE & REFIX TAILGATE COMPONENTS.	\$100.00 60
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	\$180.00 Ro
TO DISMANTLE & REPLACING REAR EXHAUST.	\$100.00 📈
TO DISMANTLE & REFIX PETROL TANK.	\$100.00 ×
TO SPRAY RUST PROOFING.	\$150.00 60
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN	
& REPLACING PARTS.	\$2500.00 600
TO PUTTY & SPRAY PAINTING.	\$2000.00 [000
CONDUCT CHASSIS ALIGNMENT.	\$380.00 ×
Labour Charge Total:	\$5840.00 742.8
	5817

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$20,262.20

LKK Auto Consultants hence notify the Repairer of the following:

- the Repairer of the following:

 To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: