

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:56

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85015086 Date : 21/04/2020 Order : SKJ7830S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKJ7830S (V 19247) Regn Date: 14/05/2013 Mileage: 64311 WIP No.: 25961

Model: A3 SPORTSBACK 1.4 TFSI 8PABBG Chassis: WAUZZZ8P7DA010766 Engine: CAX B61967 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT,HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REPAIR BONNET	250.00	1.00	250.00
S	BODYWORK	M: TO RESPRAY BONNET	550.00	1.00	550.00
X	A8P0807105F GRU	COVER Less 020%	1.00	1236.00	988.80
X	A8P0807681AAT94	(A) (SK) GRILL 15/1/20 Less 020%	1.00	233.00	186.40
X	A8P0821105G	(A) (SK) FENDER 15/1/2 Less 020%	1.00	692.00	553.60
X	AN 0161857	POP-RIVET Less 020%	6.00	3.00	14.40
X	A8P0821471	(A) (SK) BRACKET 15/1/ Less 020%	1.00	46.00	36.80
X	A8P0821135B	(A) (SK) SUPPORT 15/1/ Less 020%	1.00	49.00	39.20
X	A8P0853887B	(A) (SK) SPOILER 15/1/ Less 020%	1.00	51.00	40.80
X	A8P0941029BF	(A) (SK) HEADLAMP 15/1 Less 020%	1.00	1859.00	1,487.20
X	A8P0805607A	008027/ (V) (SK) MOUNTI Less 020%	1.00	111.50	89.20
X	A8P0807183B	008027/ (V) (SK) GUIDE Less 020%	1.00	35.80	28.64

Parts 3,465.04
Labour 0.00
Sublet 3,702.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,567.04

7% GST 459.69

Grand Total 7,026.73



Received by

For & on behalf of
Premium Automobiles Pte Ltd