

K/c

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

A/C
13/01/20
Monday
after 11am

07/01/2020

Owner: IGUA MOTORING PTE LTD

*Not withstanding
61 Day @ 1850h
Penny After Rain
3 days*

ESTIMATE TO REPAIR HONDA CIVIC - SJW5706A

2pcs	front headlamp @\$903.20	<i>o/s car</i>
2pcs	front headlamp lower bracket @\$58.85	
1pc	front centre grille base	
1pc	front centre grille chrome	
1pc	front centre grille "HONDA" logo	
1pc	front bumper	
10pcs	front bumper clip @\$3.70	
2pcs	front bumper side retainer @\$48.50	
1pc	front bumper grille	
1pc	front bumper RH side cover	
1pc	front bumper reinforcement	

\$	1,806.40	<i>LT</i>
<i>SL</i>	\$ 117.70	<i>X</i>
<i>mylms</i>	\$ 336.40	<i>~</i>
<i>SL</i>	\$ 282.50	<i>X</i>
<i>SL</i>	\$ 58.50	<i>X</i>
<i>Protem</i>	\$ 638.00	<i>—</i>
<i>m</i>	\$ 37.00	<i>—</i>
<i>o/s 7/1</i>	\$ 97.00	<i>LT</i>
<i>m</i>	\$ 125.50	<i>X</i>
<i>SL</i>	\$ 150.50	<i>X</i>
<i>SL</i>	\$ 328.40	<i>X</i>

less 20%
balance c/f

\$	3,977.90
\$	795.58
\$	3,182.32

1set front number plate & casing

s.nett \$ 50.00 *X*

towing
wiring
tuffkote
spray painting
labour charges
Total

\$	60.00	<i>501</i>
\$	80.00	<i>201</i>
<i>nn</i>	\$ 80.00	<i>X</i>
\$	600.00	<i>4001</i>
\$	800.00	<i>301</i>
\$	4,852.32	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: