

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date : 01/10/2020

To : AIG ASIA PACIFIC INSURANCE PTE LTD

Attn : Motor Claim Department

Owner : POH KIAN HUP

FWD

Acknowledged by Repairer

Signature:

Date:

Certificate Number : PNCV2019-00000580

Accident Date : 10/1/2020

Vehicle Number : SLQ3215X

Make & Model : TOYOTA C-HR 1.8

ESTIMATED REPAIR COST DETAILS

C/N	DESCRIPTION	QTY	REPAIR AMOUNT	SURVEYOR APP.
1	FRONT BUMPER ✓ <i>cut</i>	1	\$ 3,800.00	
2	FRONT BUMPER RETAINER RH <i>X (SVC)</i>	1	\$ 60.00	
3	FRONT BUMPER RETAINER LH <i>✓ CAR</i>	1	\$ 60.00	
4	FRONT BUMPER REINFORCEMENT <i>X (SVC)</i>	1	\$ 1,500.00	
5	FRONT BUMPER SPONGE <i>X (SVC)</i>	1	\$ 250.00	
6	FRONT BUMPER LOWER GARNISH CENTRE <i>X (SVC)</i>	1	\$ 550.00	
7	FRONT BUMPER LOWER GARNISH LH <i>CLIP ✓ CAR</i>	1	\$ 280.00	
8	FRONT BUMPER TOP GARNISH <i>X (SVC)</i>	1	\$ 250.00	
9	FRONT SUPPORT PANEL <i>X (R)</i>	1	\$ 1,600.00	
10	BONNET <i>X (R)</i>	1	\$ 2,500.00	
11	BONNET LOGO <i>✓</i> NN	1	\$ 185.00	
12	LH HEADLAMP <i>✓ CAR (950)</i>	1	\$ 3,800.00	
13	LH HEADLAMP ECU <i>✓</i> NN	1	\$ 1,800.00	
14	LH HEADLAMP PANEL <i>X (R)</i>	1	\$ 450.00	
15	LH FRONT FENDER <i>✓ BT</i>	1	\$ 1,800.00	
16	LH FRONT FENDER INNER SHIELD <i>X (SVC)</i>	1	\$ 455.00	
17	FRONT GRILLE & CHROME <i>X (SVC)</i>	1	\$ 1,900.00	
18	FRONT BUMPER DRY RUNNING LIGHT LH <i>✓ MIS</i>	1	\$ 450.00	
19	LH FRONT BUMPER SENSOR <i>✓</i>	1	\$ 650.00	
	<i>LH Front Fender whole garnish</i>			
	Sub Total		\$ 22,340.00	
	Discount 25% on Parts		\$ 5,585.00	
	Total		\$ 16,755.00	
Special Nett Item				
1	FRONT SUPPORT PANEL TOP GARNISH CLIP <i>✓</i>	10	\$ 100.00	
2	FRONT BUMPER CLIPS <i>✓</i>	10	\$ 100.00	
3	LH FRONT SPORT RIM <i>✓ SCR</i>	1	\$ 450.00	
	SUB TOTAL:		\$ 650.00	
Labour & Misc				
1	LABOUR TO FACILITATE REPAIR <i>✓</i>		\$ 2,500.00	
2	R & R REAR FRONT SUPPORT CAP COMPAREMENT <i>X</i>		\$ 250.00	
4	RUST PROOF ON AFFECTED AREAS <i>✓</i>		\$ 150.00	
5	TO SPRAY PAINT BONNET		\$ 250.00	
6	TO SPRAY PAINT FRONT BUMPER		\$ 250.00	
7	TO SPRAY PAINT FRONT FENDER LH <i>✓</i>		\$ 250.00	
8	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT <i>✓</i>		\$ 250.00	
9	TO SPRAY PAINT FRONT SUPPORT PANEL <i>✓</i>		\$ 200.00	
	Sub Total		\$ 4,100.00	
	Grand Total		\$ 21,505.00	

930.50 ✓

1955.20 ✓

600.50 ✓

230.50 ✓

100 ✓

155.70 ✓

20 ✓

25 ✓

400 ✓

700 ✓

30 ✓

700 ✓

parts 4312.40

parts less 25%

3234.30

spe nett 445

labour 1430

5109.30

45 less 20%

Total 4087.44

45 net
\$ 4100

L/S rpr
without prejudice
5 day
Resurvey within paint
Hock Ann
95311883
Hock Ann @ LKK Auto.com
10/1/20
3.15pm