

Vehicle No : SKB3227C

To remove all damaged parts with all necessary components/
 attachments. Straighten chassis member, repair/reshape dented
 body panel in accordance with factory specifications..
 Replace/reposition damaged parts, refit align into Refix all
 necessary components/attachment.

\$ 800.00

500

To transfer door mechanism

\$ 150.00

60

To spray portion

\$ 600.00

✓

To check wiring/proper function on light and etc.

\$ 50.00

20

Remove & refix rear wheelers include of
 Section

\$ 5,424.93

£ 200 — £ 160

Any other parts which necessitate repair or renewal will incur additional charged.
 Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
 EVELYN NG