

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2020 <a href="#">Edit Reg</a>		10 Jan 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	LIEW WEE AIK (LIAO WEIYI), Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	FBG4767J	Date of Loss:	20/12/2019 00:00 - :59 [88 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4211488661SG	Policy/Cover Note No.:	1800095288						
Vehicle Reg. No. (Insured):	SLB4678R	Policy No. (Claimant):							
		Excess:							
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/01/2020]								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>AIG_SG (14/01/2020): Request to upload TP GIA Report</li> <li>AIG_SG (14/01/2020): No OI GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBG4767J (4211488661SG)  
[SLB4678R]**

TP

-

**Dec 20 2019 12:00AM  
[LIEW WEE AIK (LIAO WEIYI)]  
Hua Chin (2000) Trading Motor Service Centre**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
2	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
3	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
4	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
5	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
6	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
7	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
8	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
9	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
10	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
11	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
12	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
13	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
14	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
15	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
16	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
17	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
18	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
19	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
20	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
21	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
22	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
23	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
24	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
25	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
26	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
27	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
28	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
29	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
30	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
31	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
32	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
33	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
34	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
35	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
36	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
37	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
38	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
39	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			
40	27/04/20 17:05	<b>General View</b>						 Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
61	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
62	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
63	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
64	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
65	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
66	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
67	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
68	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
69	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
70	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
71	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
72	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
73	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
74	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
75	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
76	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
77	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
78	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
79	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
80	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
81	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
82	27/04/20 17:05	General View	 Load JPG	<input checked="" type="checkbox"/>
83	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	27/04/20 17:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
147	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
148	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
149	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
150	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
151	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
152	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
153	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
154	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
155	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
156	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
157	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
158	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
159	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
160	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
161	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
162	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
163	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
164	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
165	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
166	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
167	27/04/20 17:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

  

<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/01/20 17:53	ACKNOWLEDGEMENT EMAIL TO AIG DD13012020	Load PDF	
2	13/01/20 17:53	EMAIL FROM AIG DD10012020	Load PDF	
3	10/06/20 12:44	Letter from SPF dd 050620	Load PDF	
4	10/06/20 12:44	PIR Search Fee invoice	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/AIG20000791/R1DS3S2  
**Date:** 04/08/2020

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800095288  
**Claimant Vehicle No :** FBG4767J **Insured Vehicle No :** SLB4678R  
Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: 4211488661SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBG4767J**  
Make & Model: PIAGGIO GILERA RUNNER, 198cc ST 200 Engine No: M464M0009138  
Reg. Date: 24/07/2012 (Man. Year: 2011) Chassis No: ZAPM4640100005690  
Colour: Black Odometer: 0 km  
Engine Capacity: 198 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 120/70-14 Rear Tyre Size: 130/70-13  
Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment: 10/01/2020  
Date Inspected: 13/01/2020 Inspected At: Hua Chin (2000) Trading Motor Service Centre (HQ)  
50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING  
Singapore 659578  
Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Repair	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
3	1		*FRONT BRAKE DISC	Scratched	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
6	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
7	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
8	1		*FRONT LH SIGNAL LAMP	Broken	0.00 F	*- F
9	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
10	1		*ERP UNIT	Cut	0.00 F	*- F
11	1		*HANDLE BAR COVER	Scratched	0.00 F	*- F
12	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
13	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
14	1		*SIDE FAIRING	Scratched	0.00 F	*- F
15	1		*FAIRING SHIELD	Broken	0.00 F	*- F
16	1		*RADIATOR TANK	Deformed	0.00 F	*- F
17	1		*FAIRING INNER	Cracked	0.00 F	*- F
18	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
19	1		*REAR LH SIGNAL LAMP	Scratched	0.00 F	*- F
20	1		*REAR RH SIGNAL LAMP	Cracked	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**
**0.00**
**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**