

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBE9263Z**Spare Parts**

No.	Qty	Nett Items	
1	1	Rear bumper	\$ Bu 758.00 ✓
2	1	Rear bumper RH side retainer	\$ Dis 35.20 ✓
3	1	Rear bumper RH reflector	\$ 47.90 ?
4	1	Rear bumper tow cover	\$ Su 30.00 X
5	1 set	Rear bumper clips	\$ M 30.00 ✓
6	1	Rear bumper inner foam	\$ 103.00 ?
7	1	RH taillamp	\$ CM 258.70 ✓
8	1	RH taillamp panel	\$ 415.80 ?
9	1	Rear RH tailgate	\$ B 1,753.70 ✓
10	1	Rear RH tailgate "Dcl" emblem	\$ M 38.00 ✓
11	1	Rear RH tailgate hinge (Top & bottom)	\$ B 396.40 ✓
12	1	Rear RH tailgate rubber	\$ Dis/wh 351.50 ✓
13	1	Rear RH tailgate lower lock	\$ 166.10 ?
14	1	Rear RH tailgate top lock	\$ K 186.10 X
15	1	Rear RH tailgate inner trim board	\$ 184.80 ?
16	1 set	Rear tailgate inner trim board clips	\$ 40.00 ?
17	1	Rear end panel	\$ B 385.00 ✓
18	1	Rear RH body panel	\$ Bu 1,976.50 ✓
19	1	Rear RH body panel inner panel	\$ K 1,209.60 X
			\$ 8,366.30
Less 10%			\$ 836.63
Total :			\$ 7,529.67

Special Nett Items

20	1 set	Reverse sensors	\$ 250.00 ?
21	1 set	Rear RH body panel window glass sealant	\$ M 50.00 401n
22	1 set	Rear RH tailgate windscreen sealant	\$ M 50.00 401n
Total :			\$ 350.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 1,400.00 1200l
2	To putty and spray Spray Paintings charges.	\$ 1,200.00 1000l
3	To remove, refit rear RH tailgate windscreen glass.	\$ 120.00 ✓
4	To remove, transfer rear RH tailgate fittings.	\$ 80.00 60l
5	To remove, refit rear RH body panel window glass.	\$ 120.00 60l
6	To remove, refit roof lining/upholstery and etc...	\$ 200.00 80l
7	To apply anti-rust treatment	\$ 100.00 90l
Total :		\$ 3,220.00

Total Parts and Labour : \$ 11,099.67

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: