

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 25 November 2020 11:47 am
To: Koh, Victor-CK
Cc: SUR; Lim, Kok-Chong
Subject: RE: SKE6183J
Attachments: SKE 6813J - Diagnostic report.pdf

Dear Victor,

Attached diagnostic report for your requested.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Wednesday, 18 November 2020 5:06 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Subject: RE: SKE6183J

From: Koh, Victor-CK
Sent: Wednesday, November 18, 2020 5:05 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: SUR
Subject: RE: SKE6183J

Hi,

Any diagnostic report on the DAY DRIVING LIGHTS POWER MODULE? I don't see any damage on the connector portion?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, September 25, 2020 11:34 AM
To: Koh, Victor-CK

Cc: SUR
Subject: [EXTERNAL] RE: SKE6183J

This message is from an external sender; be cautious with links and attachments.

Dear Victor,

According to our surveyor, please refer to the attached documents for radar sensor.

Damaged photos for DAY DRIVING LIGHTS POWER MODULE submitted, kindly refer to the photos no. 95 – 103 in Merimen.

For your approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Tuesday, 22 September 2020 12:54 pm
To: SUR <sur@lkkauto.com>
Subject: SKE6183J

Hi,

DAY DRIVING LIGHTS POWER MODULE – damage photos?
Labour 6 - this model has radar sensor? Part diagram/ damage photos?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is

accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.