



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19020893/R1qd3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date : 17-01-2020



ATTN: JULIANA LEE

Code : INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMN 787K	Veh. Inspected	SLS 6866L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1072594-002	Excess (\$)	0.00
Assign From	MOTOR INCOME INSURANCE	Assign Date	13/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	AUDI A3 SPORTBACK 1.0 TFSI	c.c	999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WAUZZZ8V0JA002924	Colour	RED
Odometer	26913	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	21/11/2019	Inspection Date	26/11/2019
Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------