



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

Estimate To Repair PC730X KING LONG XMQ6900K

Chassis No : LA6R1DSB5BB202954

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
1	1pc	Front bumper	\$ 2,113.79
2	1pc	Front body panel R/h	\$ 2,129.33
3	1pc	1st compartment side door R/h	\$ 1,274.74
			\$ 5,517.86
		Less 10%	\$ 551.79
			\$ 4,966.07
		<u>LABOUR & MISC CHARGE</u>	
1		Panel beating.	\$ 2,000.00
2		Putty and spray painting of the affected areas.	\$ 2,500.00
3		To remove and renew the above parts, adjust and realign the same.	\$ 550.00
4		Rust proof the affected areas.	\$ 380.00
			\$ 5,430.00
		Total	\$ 10,396.07