From (Person	theresa Vimala	ASSIGNMEN of 1	NC -	Date/Time:	14/01/2020@99	soan
Estimated Co	Electric Control of the Control of t		Bill to:		AV	
	S/TPRES/ODRES/ chicle No:	SIC 1173T		Insured:	FBJ 83269	
at Workshop	m/s	progressive Co	r .	Tel: 674	415336	
of	Blk 3022A ubi	Road 1 # 01.	45/46			
Policy No:			Claim No:	MT/107617	0-001	
Som Insured:			Excess:			
Make of Veh (Chent's Recor	See			D.O.A	16/12/2019	
CA / REV	/ REP. / REV 24 HR	3		H.O.D. E	ndorsement:	
CA / REV	/ REP. / REV 24 HRS 9'53amo 1411/20	3 2 Q erson Contacted:	pei wen	H.O.D. E	Name of the last o	a a
CA / REV Date/Time:	9.53amo 1411/20	Qerson Contacted:	pei wen	<i>a</i>	Name of the last o	Ti .
Date/Time:	Action/Instruction	Person Contacted:		Vehicl IN	OUT	n)
Date/Time;	Action/Instruction SJC 11737-CCA	Person Contacted:		Vehicl IN	Name of the last o	π
Date/Time;	Action/Instruction	Person Contacted:		Vehicl IN	OUT	ăi .
Date/Time:	Action/Instruction SJC 11737-CCA	Person Contacted:		Vehicl IN	OUT	TI.

Nivitha (LKK Auto)

From: Sent:

Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg> Fuesday, 14 January 2020 5:05 PM

Nivitha (LKK Auto); 'assignments'

RE: TP CASES FARMED OUT TO LKK ON 14/1/2020

OIC details

Subject:

ë ë

Theresa Vimala

Operations, Motor & Personal Lines (PL) Senior Administrator

T+65 6430 7898

www.income.com.sg



ĕø

innovation and impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sig/careers At Income, we are 'In with You' on Performance, Growth,



From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Tuesday, 14 January 2020 9:50 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 14/1/2020

Please assist to survey these vehicles. Thank you.

	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey	OI VEH	DOA	Additional Remarks
	Mt/1079851- 002	14/1/2020	SMD9738X	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	You Po Soon / 9678 6493		Slz6733a	12/1/2020	
	MT/1075799- 002	14/1/2020	SGP3076U	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 8866832		SLU1768J	14/12	Previously farmed out to LKK
	MT/1079811- 001	14/1/2020	SJB7262K	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832		SKJ139B	12/1/20	
CHESTER	MT/1076170- 001	14/1/2020 SJC1173T	SJC1173T	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01- 45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336	14:00-	FBJ8326G	16/12/19	

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg











At Income, we are in with You on Performance Growth, innovation and Impact. These attributes refres ahat we promise its an employer and what we want our people to exemplify. Find out more at income.com.sg/careers.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

- 1		
٥	ğ	
(a)		
≥		
9		
V		
S		
- =		
==		
E		
(0		
y AVG a		
A		
2	e de la companya della companya della companya de la companya della companya dell	
S		
e e		
Š		
- 5		
_		
5		
D		
3		
ec		
5		
_		
9		
pe		
S	El	
-C	0	
=	5.5	
n a	\leq	
en	6.7	
S	8	
=	3	
1	>1	
_		_

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	871A
Vehicle Details	
Vehicle No.:	SJC1173T
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8XE A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	1ZZ2975713
Chassis No.:	ZNE100383123
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,078.00
Original Registration Date:	09 Jan 2008
First Registration Date:	09 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$19,886.00
filtended PARF Rebate Dehalls	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	6 7 3
PARF Rebate Amount:	\$0.00
ntended COE Repate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	E - Open Category
COE Period(Years):	5
QP Paid:	\$25,084.00
OE Rebate Amount:	\$14,437.00
otal Rebate Amount:	\$14,437.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Jan 2020

MPA219165446 / Progressive Car Care Pte Ltd - HQ ENTRY DATE & TIME: 16/12/2019 16:38 SUBMITTED BY: Ng Pei Wen

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	16/12/2019 16:38
Date Of Accident	16/12/2019 08:00
Exact Location Of Accident	KJE SLIP ROAD TOWARDS CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJC1173T
Insured/Policyholder	
Name Of Registered Owner	CHAN WEE SENG
NRIC No	S7718871A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93875574
Alternative Phone No	OTHERS-93875574
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 X (A)
Exact Purpose for which vehicle was being used a time of accident	at
Are you claiming under your own insurance policy for repair to your vehicle?	/ NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00497547/01
Cover Note Number	

Driver

CHAN WEE SENG Name of Driver

S7718871A NRIC No 10/07/1977 Date Of Birth INDOOR Occupation 03/09/2001 Date Of Driving Pass

18 YEARS AND 3 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-93875574 Mobile Number

Fax Number

OTHERS-93875574 Contact Number

NOEMAIL EMail Address

Address

BLK 127 RIVERVALE STREET #03-836

SINGAPORE

Postcode

540127

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBJ8326G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM HOCK CHUAN

NRIC/Passport Number

S1131872Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (liii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time:

NRIC/FIN No.:

Reporting Centre Perso

Page 3 of 13

Sketch Plan #2

	Legend Notice Motore	26
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joing then the Chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	Legend Notice Motore	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joing then the Chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	Legend Notice Motore	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	cycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	rcycle
CRIBE CIRCUMSTANCES OF THE ACCIDENT I' was exiting from KJE towards then C I stopped at the slip soud to wait for Clear before joine choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.	vehicle Motoro	cycle
I was exiting from KJE towards then C I stopped at the slip sound to wait for Clear before joing chos chu Kang way. land bang was heard and a bang was to banged into my nelvicle.	vehicle Motoro	cycle
I was exiting from KJE towards choo c I stopped at the slip sound to wait for Clear before joing choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.		cycle
I was exiting from KJE towards then C I stopped at the slip sound to wait for Clear before joing chos chu Kang way. land bang was heard and a bang was to banged into my nelvicle.		eyche
I was exiting from KJE towards then C I stopped at the slip sound to wait for Clear before joing chos chu Kang way. land bang was heard and a bang was to banged into my nelvicle.		cycle
I was exiting from KJE towards choo c I stopped at the slip sound to wait for Clear before joing choo chu Kang way. I and bang was heard and a bang was to banged into my vehicle.		
I was exiting from KJE towards then C I stopped at the slip sound to wait for Clear before joing chos chu Kang way. land bang was heard and a bang was to banged into my nelvicle.	hu Kong way mis slip road. the oncoming vehicles to Out of suddan, a found lett. A motorcycle had	
barged into my newcle.	the king way mis slip road. the ancoming vehicles to Out of suddan, a found lett. A motorcycle had	
barged into my valuele.	the oncoming vehicles to Out of sudday, a found lett. A motorcycle had	
barged into my valuele.	Out of suddon, a found lett. A motorcycle had	
barged into my valuele.	Out of suddan, a found lett. A motorcuple had	
barged into my valuele.	lett. A motorciple had	
barged into my valuele.	all. I moivingse	
barged into my newcle.		
,		
A video from my in-uchicle cam is provide		
H vided from my in-venicle com is provid	lad	
<u>.</u>		
		_
		_
		_
		_
		_
CLARATION	0	
We declare the foregoing particulars are true in every respect. ase be advised that your insurer may have a fourteen (14) days clause whereby the claim a	rainst own policy must be made within the stigulated time!	efram
ase be advised that your insurer may have a fourteen (14) days clause whereby the durin a m the day of documence. Kindly check your policy for more details.	X.MAN -	
hil	/\NV-	
Reyholder's Signature , Driver's Signature	Reporting Centre Personne's Signature	e

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg GST:201006949C RCB NO:201006949C

CHAN WEE SENG (CHEN WEISHENG)

BLK 127 RIVERVALE STREET #03-836

SINGAPORE 540127

Date:

EST1505583

18 Dec 2019

Policy No:

MT/00497547/01

Veh Reg No:

Estimate No:

SJC1173T

Make/Model:

TOYOTA WISH 1.8XE A

Chassis No:

ZNE100383123

Engine No:

1ZZ2975713

Reg. Date:

09/01/2008

Accident Date: TP Veh Reg No: FBJ 8326 G

Your Ref No:

Claim Type:

ATTN: NTUC INCOME

16/12/2019

Third Party

TP 1219-5793

Estimate Repair Cost to Vehicle No :SJC1173T

	Description	U/Price	Quantity	Price	Amount
	en and all congress			<u>ss</u>	<u>SS</u>
	List Price			211-0000-0000-0000-0000-00	/
1	REAR BOOT / WC	1,080.40	1 PC	1,080.40	X
2	REAR BOOT RUBBER X (A/A /	260.80	1 PC	260.80	×
3	REAR BOOT TOP LOCK	290.70	1 PC	290.70	
1	REAR BOOT BOTTOM LOCK X	128.50	1 PC	128:50	X.
5	REAR BOOT TOYOTA LOGO	79.80	1 PC	79.80	0
5	X VV	290.60	1 PC	290:60	X
7	REAR BOOT GLASS MOULDING / AC.	260.50	1 SET	260.50	
,	REAR BUMPER / QC	419.70	1 PC	419.70	7
,	REAR BUMPER CLIPS / NC	5.50	10 PC	55.00	/
0	REAR BUMPER SIDE HOLDER - LH X	128.60	1 PC	128.60	(
1	REAR BUMPER SIDE HOLDER - RH X	128.60	1 PC	128.60	
2	REAR BUMPER REFLECTOR - LH X	68.90	1 PC	68:90 >	(
3	REAR BUMPER REFLECTOR - RH	68.90	1 PC	68.90	~ ¬
4	REAR PANEL & Buc.	601.70	1 PC	601.70	490.1
5		280.50	1 PC	280.50	X
6	REAR PANEL TOP GARNISH X REAR SPARE TYRE BOARD X	850.60	1 PC	850.60	X = = 0 /1
Ů.	REAR SI ARE THE BOARD			4,993.80	238101
			Less 25%	1,248.45	3,745.35
	: 400.000 QUANT				1789.51
	Special Net		2.00	40.00	
7	SEALANT /	20.0000	2 PC	40.00	/
8	SPONGE TAPE	20.0000	1 PC	20.00	y 12
9	REAR BUMPER SENSOR	220.0000	1 SET	220.00	\
0.0	REAR NUMBER PLATE WITH CASING X	35.0000		35.00	ζ,
1	REAR BOOT REVERSE CAMERA	350.0000	1 PC	350.00	Χ
	8.3			665.00	665.00
	Labour			60	/
	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE,	800,0000	1 JOB	800.00	600
	TO KNOCK OUT DENTS, CUT WELD REAR PAREL, REMOVE,	000.0000			1
22	DEDLACE ACCIDENT PARTS			900.00	600
	REPLACE ACCIDENT PARTS TO RESPRAY PAINT ON ACCIDENT PORTIONS	900,0000	1 JOB	900.00	
23	TO RESPRAY PAINT ON ACCIDENT PORTIONS	900,0000 20,0000		20.00	/
23 24	TO RESPRAY PAINT ON ACCIDENT PORTIONS TO CHECK WIRING		1 JOB		60
23 24 25	TO RESPRAY PAINT ON ACCIDENT PORTIONS TO CHECK WIRING TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS	20.0000	1 JOB 1 JOB	20.00	
23 24 25 26	TO RESPRAY PAINT ON ACCIDENT PORTIONS TO CHECK WIRING TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS TO TRANSFER REAR BUMPER SENSOR	20.0000 80.0000	1 JOB 1 JOB 1 JOB	20.00 80.00	40
23 24 25 26 27	TO RESPRAY PAINT ON ACCIDENT PORTIONS TO CHECK WIRING TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS TO TRANSFER REAR BUMPER SENSOR TO REMOVE, REPLACE REAR EXHAUST PIPE	20.0000 80.0000 100.0000 80.0000	1 JOB 1 JOB 1 JOB 1 JOB	20.00 80.00 100.00	40
23 24	TO RESPRAY PAINT ON ACCIDENT PORTIONS TO CHECK WIRING TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS TO TRANSFER REAR BUMPER SENSOR TO REMOVE, REPLACE REAR EXHAUST PIPE TO TUFF-KOTE	20.0000 80.0000 100.0000	1 JOB 1 JOB 1 JOB 1 JOB 1 JOB	20.00 80.00 100.00 89.00	40 X MV

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg GST:201006949C RCB NO:201006949C

M/S:

CHAN WEE SENG (CHEN WEISHENG)

BLK 127 RIVERVALE STREET #03-836

SINGAPORE 540127

Date:

EST1505583

18 Dec 2019

Policy No:

MT/00497547/01

Veh Reg No:

Estimate No:

SJC1173T

Make/Model:

TOYOTA WISH 1.8XE A

Chassis No:

ZNE100383123

Engine No:

1ZZ2975713

Reg. Date:

09/01/2008

Accident Date: TP Veh Reg No:

Your Ref No:

Claim Type:

ATTN: NTUC INCOME

16/12/2019 FBJ 8326 G

Third Party

TP 1219-5793

Estimate Repair Cost to Vehicle No :SJC1173T

Amoun	Price	Quantity	U/Price	Description
<u>S</u>	SS			2000
S\$ 6,570.3	Total			
459.9	Γ@ 7%	Add GST		
S\$ 7,030.2	Payable	Total Amount I		

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND THIRTY AND CENTS TWENTY SEVEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SDAMS. Whites

Lumpsum repour phosos.

After negar phosos.

Guo Qi T.

14/1/2020

3328.58 2%. 2650.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000907/Gsd3n2 Date: 11-03-2020

73 BRAS BASAH ROAD

Ref:	CS/INC20000907	
Date:	11-03-2020	

TTN-	CHESTER		Code: INC				
No.		Policy Particu	lars :- THIRD PARTY CLA	JM			
	nsured Veh.	FBJ 8326G	Veh. Inspected	SJC 1173T			
- 1	Policy No.		Coverage (\$)	0.00			
_	Claim No.	MT/1076170-001	Excess (\$)	0.00			
-	Assign From	THERESA VIMALA	Assign Date	14/01/2020			
2.	16 Salba 500	Vehicle	Particulars & Condition	MANUAL PROPERTY.			
	Make & Model	TOYOTA WISH 1.8	c.c	1794			
	Engine No.	HIDDEN	Year of Reg.	2008			
_	Chassis No.	ZNE100383123	Colour	BLACK			
	Odometer	258245 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Co	onditions of Tyres	NAME OF THE OWNER OF			
		Size	Make	Balance			
	R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm			
	L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm			
	R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm			
	L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm			
4.		Des	cription of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.						

5.	General Information					
	Accident Date	16/12/2019	Inspect Date / Time	14/01/2020 (04:00 PM)		
	Survey held at PROGRESSIVE CAR CARE PTE LTD					
		BLK 3022A UBI ROAD 1 #01-	45/46, SINGAPORE 048716			
ia.	Remarks					
	A)THE INSPECTION	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
335	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 1173T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
-	REPLACEMENT OF PARTS			
1	REAR BOOT	BUCKLED	1,080.40	1,080.40
1	REAR BOOT RUBBER	NOT NECESSARY	260.80	-
1	REAR BOOT TOP LOCK	NOT NECESSARY	290.70	-
	REAR BOOT BOTTOM LOCK	NOT NECESSARY	128.50	
1	REAR BOOT TOYOTA LOGO	NECESSARY	79.80	79.80
1	REAR BOOT OUTER CHROME	NOT NECESSARY	290.60	
1	SET REAR BOOT GLASS MOULDING	NECESSARY	260.50	260.50
1	REAR BUMPER	DEFORMED	419.70	419.70
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
	REAR BUMPER SIDE HOLDER-LH	NOT NECESSARY	128.60	
,	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	128.60	
- 1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	68.90	
1	REAR BUMPER REFLECTOR-RH	NOT NECESSARY	68.90	
1	REAR PANEL	BUCKLED	601.70	490.70
1	REAR PANEL TOP GARNISH	NOT NECESSARY	280.50	
,	REAR SPARE TYRE BOARD	NOT NECESSARY	850.60	
234	LESS 25% DISCOUNT		-1,248.45	-596.52
	LESS 25% DISCOST!		3,745.35	1,789.58
	SPECIAL NETT ITEMS	0.00	.0000	MONOGO DE
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER SENSOR (SN)	NOT NECESSARY	220.00)
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	35.00	
1	REAR BOOT REVERSE CAMERA (SN)	NOT NECESSARY	350.00	
	37 WARRING RESIDENCE OF THE SECOND STATE OF TH		665.00	60.00
	LABOUR		000000	
	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS.		800.00	600.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		900.00	600.00
	TO CHECK WIRING.		20.00	20.00

Report Ref No. CS/INC20000907/Gsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE, REFIX REAR GARNISH AND RELATED PARTS.	NOT NECESSARY	80.00	60.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	40.00
	TO REMOVE, REPLACE REAR EXHAUST PIPE.		80.00	
	TO TUFF-KOTE.		60.00	60.00
	TO REMOVE, REPLACE REAR BOOT GLASS.		120.00	100.00
			2,160.00	1,480.00
	GRAND TOTAL		6,570.35	3,329.58

RECOMMENDED COST OF LUMP SUM REPAIRS	2,650.00
(TO ITS PRE-ACCIDENT CONDITION)	
(CONFIRMED)	

Report Ref No. CS/INC20000907/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.