

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : PANG CHEE KEONG
630 JURONG WEST ST 65
#05-416
SINGAPORE 640630

Claim No: MC1900933
No: MF1901138
Date: 03 Jul 2020
Policy No: P10030710R02
Veh Reg No: SJH1419J
Make/Model: TOYOTA ALLION 1.5 A
Chassis No: NZT2603030248
TP Ins Co: SPF

ATTN:

Your Ref No: SJH1419J
Claim Type: Third Party
Accident Date: 31/12/2019
TP Veh Reg No: QX1022C

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJH1419J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
LABOUR			
1 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT BUMPER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	150.00	
2 TO SPRAY FRONT BUMPER.	1 PC	200.00	
		350.00	350.00
Total			S\$ 350.00
Add GST @ 7%			24.50
Total Amount Payable			S\$ 374.50

TOTAL: SINGAPORE DOLLAR THREE HUNDRED SEVENTY FOUR AND CENTS FIFTY ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 15/01/2020

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

0:12/16
SURVEYOR COPY

M/S : PANG CHEE KEONG
630 JURONG WEST ST 65
#05-416
SINGAPORE 640630

LKK
12 noon

Estimate No: MC1900933
Date: 03 Jan 2020
Policy No: P10030710R02
Veh Reg No: SJH1419J
Make/Model: TOYOTA ALLION 1.5 A

ATTN:

Your Ref No: SJH1419J
Claim Type: Third Party — SPF
Accident Date: 31/12/2019
TP Veh Reg No: QX1022C

Estimate Repair Cost to Vehicle No :SJH1419J

Description	Quantity	List Price S\$	Amount S\$
LABOUR			
1 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT BUMPER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	150
2 TO SPRAY FRONT BUMPER.	1 PC	300.00	200
		500.00	500.00
		Total	S\$ 500.00
		Add GST @ 7%	35.00
		Total Amount Payable	S\$ 535.00

TOTAL: SINGAPORE DOLLAR FIVE HUNDRED THIRTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

350

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

2 Days.

part by part.

After repair photos.

Gmo Qian
82880282

15/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

70.
2:10
Ah Lim motor company

11-06-20
In

PLS arrange vehicle for survey