

ASS. REC. BY:

REF:

08/00120000927/Avd302

Special Instruction:

✓

Manager: Adnan

ASSIGNMENT (Office)

From (Person): Josephine Wong of UOI Date/Time: 15/01/2020 @ 9:09am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDM 6288G Insured: _____at Workshop in/s: Vision Autoworks Tel: 9856 4815

8 Kaki Bukit Ave 4 # 08-09 premier

Policy No: Repairer: Dynamic AutoWork Claim No: M12D 12543001Sum Insured: _____ Excess: 500Make of Veh: _____ D.O.A. 11/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10:49am @ 15/1/2020 Person Contacted: Michelle Vehicle: INTL DUT

H.O.D. Endorsement:

Date/Time	Action/Instruction
	<u>Johnnie ✓</u>
	<u>SDM 6288G - NBA/00120000836/Y</u>
	<u>DoA: 11/01/2020</u>
<u>16/1/2020</u>	<u>@ 10:44am Adnan informed Michelle Max repair \$12,500/-</u>
<u>16/1/2020</u>	<u>Revert to Josephine by email</u>
<u>17/1/2020</u>	<u>Recd authorise repair from Josephine, ex \$500 by email</u>

ASSIGNMENT

Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / CO RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: SPM6288G. Reg: 2012 May
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 328i Yr: 1997
 Colour: Grey A/C: Insured / Std / Nil / NA
 Sp Reading: 99069 T/Ratio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WBA3A52040F253644
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/35 R 19
 R: 245/35 R 19
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: _____ D.O.I: 15/01/20
 Survey held at: Dynamic
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Front N/S, u/c.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD UOI
17/1/2000	Informed michelle c/a LS not exceeding \$12,500 ex \$500 by email
	MV: 561C
	PV: 43.1K
	Nett: 12.9K.
RECEIVED 27 MAR 2020	
27/3/20	Adrian confirmed LS \$12,000 (Recd 20,848.70, 639)
Date/Time, File Pass to:	<input type="checkbox"/> : Prel. Report
11	<input type="checkbox"/> : Final Report
Date/Time, File Return to:	Days Of Repair: <u>6</u>
30/3 - typist	Resurvey No. of Trip: <u>2</u>
30/3 - typist	Site Insp: <input type="checkbox"/> IS
30/3 - typist	Interview: <input type="checkbox"/> IS
30/3 - typist	Testimony: <input type="checkbox"/> IS
30/3 - typist	Witness: <input type="checkbox"/> IS
30/3 - typist	Other: <input type="checkbox"/> IS
30/3 - typist	LS \$12,000k

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 17 January 2020 12:00 PM
To: Dynamic Autowork; SUR
Subject: SDM 6288G-DOA: 11/1/2020 (UOI OD)
Attachments: OD Claim - DV (UOI).pdf

Dear Michelle,

As instructed by our client , please proceed to repair the **insured vehicle SDM 6288G, Not Exceeding Lump Sum Repair \$12,500/-or whichever lower, (Excess \$500).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>
Sent: Friday, 17 January 2020 11:16 AM
To: Veron Chen (LKKAUTO)
Cc: SUR; LEE KATIE
Subject: RE: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey Our ref: M12D12542001

Without Prejudice

Dear Veron

We refer to your email of 16 January 2020.

Kindly proceed to authorise repair at \$12,500.

Claim no: M12D12542001 AND Excess is \$500.0

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, January 16, 2020 12:09 PM
To: WONG JOSEPHINE <josephinewong@uoi.com.sg>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey

Dear Josephine,

Enclosed preliminary revised of vehicle SDM 6288G

Date of survey: 15/1/2020

Number of days (estimated) : 6 days

Repairer agree repair cost Not Exceeding \$12,500/-

We have Not authorise repair.

Kindly let us have your approval, provides claim number and policy excess

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Wednesday, 15 January 2020 10:52 AM

To: 'WONG JOSEPHINE' <josephinewong@uoi.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'LEE KATIE' <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: WONG JOSEPHINE [<mailto:josephinewong@uoi.com.sg>]

Sent: Wednesday, 15 January 2020 9:09 AM

To: visionautowork@gmail.com

Cc: LEE KATIE <katielee@uoi.com.sg>; assignments@lkkauto.com; sur@lkkauto.com

Subject: FW: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey

Without Prejudice

Dear Michelle

We refer to your email of 14 January 2020.

We will appoint LKK Auto Consultants for the survey.

Kindly forward us the estimate or give a copy to the surveyor.

LKK- Please attend to the survey .

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

=====

From: Vision Autowork [<mailto:visionautowork@gmail.com>]

Sent: Tuesday, 14 January, 2020 11:34 AM

To: LEE KATIE <katielee@uoi.com.sg>; LEE KATIE <katielee@uoi.com.sg>; LEW JENNY <jennylew@uoi.com.sg>

Subject: SDM6288G (OD CLAIM)

Dear Person In Charge,

Please arrange surveyor to survey the above OD CLAIM (SDM6288G)

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 16 January 2020 12:09 PM
To: 'WONG JOSEPHINE'; SUR
Cc: 'LEE KATIE'
Subject: RE: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey
Attachments: MARK EST.pdf; PRELI REVISED.pdf

Dear Josephine,

Enclosed preliminary revised of vehicle SDM 6288G
Date of survey: 15/1/2020
Number of days (estimated) : 6 days

Repairer agree repair cost Not Exceeding \$12,500/-

We have Not authorise repair.

Kindly let us have your approval, provides claim number and policy excess

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 15 January 2020 10:52 AM
To: 'WONG JOSEPHINE' <josephinewong@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'LEE KATIE' <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey

Dear Sir/Mdm,

Thank you for the assignment.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: WONG JOSEPHINE [mailto:josephinewong@uoi.com.sg]
Sent: Wednesday, 15 January 2020 9:09 AM
To: visionautowork@gmail.com
Cc: LEE KATIE <katielee@uoi.com.sg>; assignments@lkkauto.com; sur@lkkauto.com
Subject: FW: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey

Without Prejudice

Dear Michelle

We refer to your email of 14 January 2020.

We will appoint LKK Auto Consultants for the survey.

Kindly forward us the estimate or give a copy to the surveyor.

LKK- Please attend to the survey .

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

=====

From: Vision Autowork [mailto:visionautowork@gmail.com]

Sent: Tuesday, 14 January, 2020 11:34 AM

To: LEE KATIE <katielee@uoi.com.sg>; LEE KATIE <katielee@uoi.com.sg>; LEW JENNY <jennylew@uoi.com.sg>

Subject: SDM6288G (OD CLAIM)

Dear Person In Charge,

Please arrange surveyor to survey the above OD CLAIM (SDM6288G)

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CS/DOI20000927/Avd3

Date : 16/1/2020

The Motor Claims Department
UNITED OVERSEAS INSURANCE LTD

Dear Sir,

PRELIMINARY ADVICE OF VEHICLE NO. SDM 6288G


We thank you for your instruction on 15/1/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/1/2020 at the premises of M/s DYNAMIC AUTOWORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$32,848.70
Revised Estimate Amount	: S\$13,823.00
"Check" Items Amount	: S\$4,815.95
Total	: S\$18,638.95
Market Value	: S\$56,000.00
LTA Reimbursement Value	: S\$43,048.00
Nett Value	: S\$12,952.00

Description of Damage:

The vehicle sustained damages at the front n/s portion and undercarriage



Comments/Present Status:

Damages Consistent

Repair Cost Economical

Repairer agree repair cost Not Exceeding \$12,500/-

Yours faithfully,

Signature 16/1/2020

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Nivitha (LKK Auto)

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>
Sent: Wednesday, 15 January 2020 9:09 AM
To: visionautowork@gmail.com
Cc: LEE KATIE; assignments@lkkauto.com; sur@lkkauto.com
Subject: FW: SDM6288G (OD CLAIM) DOA: 11/01/2020 Conduct Survey
Attachments: OI - SDM6288G.zip

Without Prejudice

Dear Michelle

We refer to your email of 14 January 2020.

We will appoint LKK Auto Consultants for the survey.

Kindly forward us the estimate or give a copy to the surveyor.

LKK- Please attend to the survey .

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

=====

From: Vision Autowork [<mailto:visionautowork@gmail.com>]

Sent: Tuesday, 14 January, 2020 11:34 AM

To: LEE KATIE <katielee@uoi.com.sg>; LEE KATIE <katielee@uoi.com.sg>; LEW JENNY <jennylew@uoi.com.sg>

Subject: SDM6288G (OD CLAIM)

Dear Person In Charge,

Please arrange surveyor to survey the above OD CLAIM (SDM6288G)

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4201
Vehicle Details	
Vehicle No.:	SDM6288G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	328I 2.0 AT D/AB 4DR ABS HID DSC
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	A5360123N20B20A
Chassis No.:	WBA3A52040F253644
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$39,705.00
Original Registration Date:	04 May 2012
First Registration Date:	04 May 2012
Transfer Count:	1
Actual ARF Paid:	\$39,705.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 May 2022
PARF Rebate Amount:	\$23,823.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$84,590.00
COE Rebate Amount:	\$19,225.00
Total Rebate Amount:	\$43,048.00

The information contained herein is correct as at 16 Jan 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4201
Vehicle Details	
Vehicle No.:	SDM6288G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	328i 2.0 AT D/AB 4DR ABS HID DSC
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	A5360123N20B20A
Chassis No.:	WBA3A52040F253644
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$39,705.00
Original Registration Date:	04 May 2012
First Registration Date:	04 May 2012
Transfer Count:	1
Actual ARF Paid:	\$39,705.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 May 2022
PARF Rebate Amount:	\$23,823.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$84,590.00
COE Rebate Amount:	\$19,248.00
Total Rebate Amount:	\$43,071.00

The information contained herein is correct as at 15 Jan 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Singapore NRIC

4201

SDM6288G

No

13 Jan 2020

B.M.W.

328i 2.0 AT D/AB 4DR ABS HID DSC

Grey

2012

A5360123N20B20A

WBA3A52040F253644

180.0 kW (241 bhp)

\$39,705.00

04 May 2012

04 May 2012

1

\$39,705.00

Yes

03 May 2022

\$23,823.00

03 May 2022

E - Open Category

10

\$84,590.00

\$19,295.00

\$43,118.00

02/03/12



12682

The information contained herein is correct as at 13 Jan 2020

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SQUARESPACE

HELPING MILLIONS OF
ENTREPRENEURS SUCCEED ONLINE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal COE Toyota Wish 2.0A.



2.98% P.A. \$0 Admin, Monthly
From \$688, 2 Years Warranty
Engine/Gearbox.
GV Credit StarAd



* Free VICOM evaluation
* Free grooming and 6 months maintenance
* In-house workshop ensures quality service
* Member of SVTA and hire purchase association
* 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

8 vehicles

Search

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	bmw 328	Any	Any	Any	Any	Any	Any	Available
------------------	---------	-----	-----	-----	-----	-----	-----	-----------


☐ BMW 3 Series 328i

\$55,800

\$16,010 /yr

02-Mar-2012

1,997 cc

160,000 km

Luxury

Available

PML Unit! Sporty 3 Series Looking For Its Next Owner. Under Warranty By Optima Carz Pte Ltd Till 06/06/2022 Still Many Parts Replaced With Receipts. Air Con Compressor, Power Steering Racks, Absorbers, roof Lining Replaced Etc. Flexible Loan Options With High Trade In...

PREMIUM AD

Posted: 11-Jan-2020 Tags: 2012 BMW 328i, 2012 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW


☐ BMW 3 Series 328i Sport

\$70,000

\$19,910 /yr

12-Jun-2012

1,997 cc

133,100 km

Luxury

Available

1 Owner/PML Unit! Sportiest And Aggressive Snout Front Grill Stand Out From The Crowds. Bidded Double-Digit Plate Will Be Handed Over. Sublime Handling Makes Your Daily Drive Pleasurable. Well Maintain By Owner, Brake Rotors Replaced By PML Less Than 6 Month...

PREMIUM AD

Car Buyers Automotive Pte Ltd

Posted: 31-Dec-2019 Tags: 2012 BMW 328i, 2012 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW


☐ BMW 3 Series 328i M-Sport

\$65,800

\$18,300 /yr

15-Jun-2012

1,997 cc

89,292 km

Luxury

Available

Low Mileage Done At 89,292 Km Only! PML Unit! Full M-Series With M Body-Kit. 19" BMW Sport Staggered Rims With New Tires. Upgraded 6 Pot Forge -Disc Brakes. 100% Original Mineral White Paintwork With Dakota Black Leather Interior. Tastefully Done Up With No Illegal...

Posted: 10-Jul-2020 Tags: 2012 BMW 328i, 2012 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW


☐ BMW 3 Series 328i Sport

\$68,888

\$16,890 /yr

07-Nov-2012

1,997 cc

145,000 km

Luxury

Available

PML Unit. No Worries On Oil Leak. 100% Accident Free. Never Been To Track. View To Appreciate.

DIRECT OWNER

Posted: 22-Dec-2019 Tags: 2012 BMW 328i, 2012 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW



Mirage Motorwerkz Pte Ltd - Specialty Workshops

Mirage Motorwerkz Pte Ltd is a one-stop car workshop which to provide friendly, reliable and prices competitive motoring services.

More info about this shop


☐ BMW 3 Series 328i M-Sport

\$70,000

\$17,190 /yr

09-Nov-2012

1,997 cc

96,000 km

Luxury

Available

RARE Red Interior Unit! Sportiest M-Sport! Front Grill Stand Out From The Crowds. Sublime Handling Makes Your Daily Drive Pleasurable. Well Maintain By Owner, Zero Mishap! NO Repairs Needed! Superb Condition Unit! View To Believe! Whatsapp To View Now! By Appoint...

360 VR Cars

Posted: 13-Nov-2019 Tags: 2012 BMW 328i, 2012 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW


☐ BMW 3 Series 328i Gran Turismo

\$105,800

\$15,470 /yr

19-Nov-2014

1,997 cc

24,000 km

Luxury

Available

6 Months Warranty, Excellent Condition, Bank Loan/In House Loan Available, Trade In Welcome.

Posted: 11-Jan-2020 Tags: 2014 BMW 328i, 2014 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW


☐ BMW 3 Series 328i M-Sport

\$112,888

\$15,880 /yr

02-Apr-2015

1,997 cc

75,000 km

Luxury

Available

Viewing By Appointment Only. Flexible Loan/Trade In Available. Mint Condition! New Road Tax. Enthusiasts Be Thrilled! Elevating The Driving Experience To A Whole New Level With Its LTA Compliant Eisenmann Exo System, Hear It! Tastefully Done Up With Zero Expend...

PREMIUM AD

Posted: 02-Jan-2020 Tags: 2015 BMW 328i, 2015 bmw 328i, BMW 328i, bmw 328i, BMW, 328i, Used BMW

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2020 10:52
Date Of Accident	11/01/2020 01:35
Exact Location Of Accident	ALONG KEW DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM6288G
Insured/Policyholder	
Name Of Registered Owner	LEE LIAN YAP
NRIC No	SXXXX420I
Email Address	HAN-TAN88@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97386288
Alternative Phone No	OTHERS-98196288

Vehicle Particulars

Manufacturer	BMW
Model	328I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120037401800
Cover Note Number	

Driver

Name of Driver	TAN SOCK HAN (CHEN SHUHAN)
NRIC No	SXXXX942C
Date Of Birth	18/09/1988
Occupation	INDOOR
Date Of Driving Pass	29/10/2007
Driving Experience	12 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97386288
Fax Number	
Contact Number	OTHERS-98196288
Email Address	HAN-TAN88@HOTMAIL.COM

Address	19 PASIR RIS RISE #05-40
Postcode	518089
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV6931P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly, honestly and truthfully to the relevant authorities.
2. This form must be completed by the Pedestrian and/or the Author and Driver.
3. It is your responsibility to provide a truthful and accurate statement. Any false statement or omission may constitute an offence and may lead to criminal liability.
4. The false and/or false statement by you may constitute an offence under the relevant laws and may lead to criminal liability.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be made available to the relevant authorities for their use in the investigation of the accident and for the purpose of the investigation of the accident and for the purpose of the investigation of the accident.
7. By the submission of this report to the insurers, you hereby consent to the disclosure of the report to the insurers and to the insurers making the report being made available to the relevant authorities.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data, personal information set out in this form and any other personal information provided by me or generated by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (collectively the "Insurers"), the Insurers' lawyer/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claim including the settlement of the claim and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instruction and/or responding to enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, notices, reports or notices to me, which may include disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and/or packages); and/or
 - (v) complying with legislative law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firm may be deemed to collect, use, disclose and/or process my Personal Information for use in more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.
- (d) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.
- (e) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.
- (f) to all relevant third parties (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.
- (g) to all relevant third parties (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.
- (h) to all relevant third parties (including the Insurers' lawyer/law firm) who may be located outside of Singapore for use in more of the above Purposes.

Signature of Pedestrian
Date & Time

Signature of Author and Driver
Date & Time

Signature of Pedestrian
Date & Time
14/01/2020
Res 2

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Area for describing the circumstances of the accident, containing horizontal lines and a diagonal line from the bottom-left to the top-right.

Peter is attached

DECLARATION

We declare the foregoing to be true and correct.

Signature of Investigator
Date & Time

Signature of Driver
Date & Time

14/01/2020
Resd. 1000ARS

Sketch Plan #3

On 11.01.20 at about 01:35hrs, I was driving along Kew Heights on my way home, while driving on Kew Drive I accidentally bang into a stationary car parking at 112 Kew Drive. Immediately I came down to access the damage and notify the owner.

Vehicle (A) : SDM6288G

Vehicle (B) : SJV6931P

[Signature]
14/01/2020
Red Wolf

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 14.1.20

TO : UOI MOTOR CLAIMS DEPTS (OD CLAIM)

VEHICLE NO : SDM6288G

MODEL : BMW 328i

DATE OF ACCIDENT : 11.01.20

TIME OF ACCIDENT : 01:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,595.00	\$ 1,595.00
2	FRONT BUMPER SIDE AIR VENT LH ?	1	\$ 67.95	\$ 67.95
3	FRONT BUMPER FOGLAMP LH <i>new</i>	1	\$ 545.00	\$ 545.00
4	FRONT BUMPER FOGLAMP COVER LH <i>new</i>	1	\$ 105.00	\$ 105.00
5	FRONT BUMPER BOTTOM GARNISH LH ?	1	\$ 310.00	\$ 310.00
6	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 75.00	\$ 150.00
7	FRONT BUMPER PROTECTOR CHROME LH <i>new</i>	1	\$ 170.00	\$ 170.00
8	FRONT BUMPER CENTER GRILLE <i>new</i>	2	\$ 185.00	\$ 370.00
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 890.00	\$ 890.00
10	FRONT HEADLAMP (HID&LED) <i>H1 cut</i>	2	\$ 2,694.00	\$ 5,388.00
11	FRONT HEADLAMP LOWER BRACKET ?	2	\$ 125.00	\$ 250.00
12	FRONT HEADLAMP HID CONTROL UNIT <i>new</i>	2	\$ 945.00	\$ 1,890.00
13	FRONT HEADLAMP NOZZLE ?	2	\$ 435.00	\$ 870.00
14	FRONT HEADLAMP NOZZLE COVER <i>Missing</i>	2	\$ 140.00	\$ 280.00
15	FRONT NOZZLE TUBE <i>new</i>	2	\$ 120.00	\$ 240.00
16	FRONT FENDER LH <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00
17	FRONT FENDER INNER COWLING LH <i>ton</i>	1	\$ 295.00	\$ 295.00
18	FRONT WHEEL RIM LH <i>hit</i>	1	\$ 1,860.75	\$ 1,860.75
19	FRONT KNUCKLE LH ?	1	\$ 735.00	\$ 735.00
20	FRONT SHOCK ABSORBER LH ?	1	\$ 783.00	\$ 783.00
21	FRONT WHEEL HUP WITH BEARING LH ?	1	\$ 780.00	\$ 780.00
22	FRONT WHEEL ABS SENSOR LH <i>new</i>	1	\$ 365.00	\$ 365.00
23	FRONT STEERING RACK AND PINION <i>Bent</i>	1	\$ 3,879.00	\$ 3,879.00
24	FRONT LINKAGE LH <i>new</i>	1	\$ 195.00	\$ 195.00
25	FRONT LOWER ARM (STRAIGHT) <i>Bent</i>	1	\$ 790.00	\$ 790.00
26	FRONT LOWER ARM (BENT) ?	1	\$ 960.00	\$ 960.00

TOTAL PRICE \$ 25,008.70
LESS 0% \$ -
SUB TOTAL PRICE \$ 25,008.70

TO : UOI MOTOR CLAIMS DEPTS (OD CLAIM)
 VEHICLE NO : SDM6288G
 MODEL : BMW 328I
 DATE OF ACCIDENT : 11.01.20
 TIME OF ACCIDENT : 01:30HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PALTE <i>neu</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>neu</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER BOTTOM GARNISH CLIP LH (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00
4	FRONT FENDER INNER COWLING CLIP LH (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00
5	FRONT WHEEL TYRE LH <i>lot</i>	1	\$ 850.00	\$ 850.00
6	BRAKE OIL <i>neu</i>	1	\$ 40.00	\$ 40.00

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	600
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 150.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 1,200.00	280
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 650.00	150
8	FOUR WHEEL ALIGNMENT	\$ 180.00	80
9	RESET ABS LIGHT	\$ 650.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 750.00	120

TOTAL

\$6,710.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,138.70
 TOTAL LABOUR COST : \$ 6,710.00
 TOTAL REPAIR COST : \$ 32,848.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian Lj
H/S 15/01/20
Not Authorized
Exam: To be advised
06 Pays

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

Surveyer

DATE : 14.01.20

TO : UOI MOTOR CLAIMS DEPTS (OD CLAIM)

VEHICLE NO : SDM6288G

MODEL : BMW 328i

Veron

DATE OF ACCIDENT : 11.01.20

TIME OF ACCIDENT : 01:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,595.00	\$ 1,595.00
2	FRONT BUMPER SIDE AIR VENT LH <i>cracked</i>	1	\$ 67.95	\$ 67.95
3	FRONT BUMPER FOGLAMP LH <i>new</i>	1	\$ 545.00	\$ 545.00
4	FRONT BUMPER FOGLAMP COVER LH <i>new</i>	1	\$ 105.00	\$ 105.00
5	FRONT BUMPER BOTTOM GARNISH LH <i>cracked</i>	1	\$ 310.00	\$ 310.00
6	FRONT BUMPER SIDE RETAINER <i>2x new</i>	2	\$ 75.00	\$ 150.00
7	FRONT BUMPER PROTECTOR CHROME LH <i>new</i>	1	\$ 170.00	\$ 170.00
8	FRONT BUMPER CENTER GRILLE <i>new</i>	2	\$ 185.00	\$ 370.00
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 890.00	\$ 890.00
10	FRONT HEADLAMP (HID&LED) <i>Hit cut</i>	2	\$ 2,694.00	\$ 5,388.00
11	FRONT HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 125.00	\$ 250.00
12	FRONT HEADLAMP HID CONTROL UNIT <i>new</i>	2	\$ 945.00	\$ 1,890.00
13	FRONT HEADLAMP NOZZLE <i>uncracked</i>	2	\$ 435.00	\$ 870.00
14	FRONT HEADLAMP NOZZLE COVER <i>missing</i>	2	\$ 140.00	\$ 280.00
15	FRONT NOZZLE TUBE <i>new</i>	2	\$ 120.00	\$ 240.00
16	FRONT FENDER LH <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00
17	FRONT FENDER INNER COWLING LH <i>ton</i>	1	\$ 295.00	\$ 295.00
18	FRONT WHEEL RIM LH <i>hit</i>	1	\$ 1,860.75	\$ 1,860.75
19	FRONT KNUCKLE LH <i>Bad</i>	1	\$ 735.00	\$ 735.00
20	FRONT SHOCK ABSORBER LH <i>Best</i>	1	\$ 783.00	\$ 783.00
21	FRONT WHEEL HUP WITH BEARING LH <i>Bad</i>	1	\$ 780.00	\$ 780.00
22	FRONT WHEEL ABS SENSOR LH <i>new</i>	1	\$ 365.00	\$ 365.00
23	FRONT STEERING RACK AND PINION <i>Best</i>	1	\$ 3,879.00	\$ 3,879.00
24	FRONT LINKAGE LH <i>new</i>	1	\$ 195.00	\$ 195.00
25	FRONT LOWER ARM (STRAIGHT) <i>Best</i>	1	\$ 790.00	\$ 790.00
26	FRONT LOWER ARM (BENT) <i>Best</i>	1	\$ 960.00	\$ 960.00

13103.95

TOTAL PRICE \$ 25,008.70

LESS 0%

SUB TOTAL PRICE \$ 25,008.70

12448.75

S.N: 950

✓
✓
+
+
✓
75
+
+
+
2694
+
+
225
140
+
+
+
950 (sw)
2
2
2
+
+
380
2

TO : UOI MOTOR CLAIMS DEPTS (OD CLAIM)
 VEHICLE NO : SDM6288G
 MODEL : BMW 328I
 DATE OF ACCIDENT : 11.01.20
 TIME OF ACCIDENT : 01:30HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PALTE <i>neu</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>neu</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER BOTTOM GARNISH CLIP LH (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00
4	FRONT FENDER INNER COWLING CLIP LH (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00
5	FRONT WHEEL TYRE LH <i>lot</i>	1	\$ 850.00	\$ 850.00
6	BRAKE OIL <i>neu</i>	1	\$ 40.00	\$ 40.00

420

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	600
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 150.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 1,200.00	280
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 650.00	150
8	FOUR WHEEL ALIGNMNET	\$ 180.00	80
9	RESET ABS LIGHT	\$ 650.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 750.00	120

1760

TOTAL

\$6,710.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,138.70
 TOTAL LABOUR COST : \$ 6,710.00
 TOTAL REPAIR COST : \$ 32,848.70

• To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to change

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
 H/S 15/01/20
 Not Authorized

Exem: To be advised

06 Pays

total: 13578.75

H/S: 12K (Nett Value)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20000927/Avd3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 01-04-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDM 6288G
Policy No. DHOM120037401800	Coverage (\$)	0.00
Claim No. M12D12542001	Excess (\$)	500.00
Assign From JOSHEPHINE WONG	Assign Date	15/01/2020

2. Vehicle Particulars & Condition

Make & Model B.M.W. 328i	c.c	1997
Engine No. HIDDEN	Year of Reg.	2012
Chassis No. WBA3A52040F253644	Colour	GREY
Odometer 90069	Steering	IN ORDER
Brakes IN ORDER	Modification	SPORTS RIM
General GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35 R19	MICHELIN	6 mm
L/H Front Tyre	245/35 R19	MICHELIN	6 mm
R/H Rear Tyre	245/35 R19	MICHELIN	6 mm
L/H Rear Tyre	245/35 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND UNDERCARRIAGE PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date 11/01/2020	Inspection Date 15/01/2020
Survey held at 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT	
Repairer DYNAMIC AUTOWORK PTE LTD	

5a. Remarks

A)THE MARKET VALUE IS S\$56,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDM 6288G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,595.00	1,595.00
1	FRONT BUMPER SIDE AIR VENT LH	CRACKED	67.95	67.95
1	FRONT BUMPER FOGLAMP LH	NOT NECESSARY	545.00	-
1	FRONT BUMPER FOGLAMP COVER LH	NOT NECESSARY	105.00	-
1	FRONT BUMPER BOTTOM GARNISH LH	CRACKED	310.00	310.00
2	FRONT BUMPER SIDE RETAINER @\$75.00	N/S NECESSARY	150.00	75.00
1	FRONT BUMPER PROTECTOR CHROME LH	NOT NECESSARY	170.00	-
2	FRONT BUMPER CENTER GRILLE @\$185.00	NOT NECESSARY	370.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	890.00	-
2	FRONT HEADLAMP (HID&LED) @\$2694.00	N/S CUT	5,388.00	2,694.00
2	FRONT HEADLAMP LOWER BRACKET @\$125.00	NOT NECESSARY	250.00	-
2	FRONT HEADLAMP HID CONTROL UNIT @\$945.00	NOT NECESSARY	1,890.00	-
2	FRONT HEADLAMP NOZZLE @\$435.00	N/S CRACKED	870.00	125.00
2	FRONT HEADLAMP NOZZLE COVER @\$140.00	MISSING	280.00	140.00
2	FRONT NOZZLE TUBE @\$120.00	NOT NECESSARY	240.00	-
1	FRONT FENDER LH	DENTED	1,245.00	1,245.00
1	FRONT FENDER INNER COWLING LH	TORN	295.00	295.00
1	FRONT KNUCKLE LH	DAMAGED	735.00	735.00
1	FRONT SHOCK ABSORBER LH	BENT	783.00	783.00
1	FRONT WHEEL HUP WITH BEARING LH	DAMAGED	780.00	780.00
1	FRONT WHEEL ABS SENSOR LH	NOT NECESSARY	365.00	-
1	FRONT STEERING RACK AND PINION	BENT	3,879.00	3,879.00
1	FRONT LINKAGE LH	NOT NECESSARY	195.00	-
1	FRONT LOWER ARM (STRAIGHT)	BENT	790.00	380.00
1	FRONT LOWER ARM	BENT	960.00	960.00
	LESS 5% DISCOUNT		-	-703.20
			23,147.95	13,360.75
SPECIAL NETT ITEMS				
1	FRONT WHEEL RIM LH (SN)	CUT	1,860.75	950.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT BUMPER BOTTOM GARNISH CLIP LH (SN)	NECESSARY	60.00	20.00
1	SET FRONT FENDER INNER COWLING CLIP LH (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/UOI20000927/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL TYRE LH (SN)	CUT	850.00	300.00
1	BRAKE OIL (SN)	NECESSARY	40.00	40.00
			2,990.75	1,370.00
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,400.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	600.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		150.00	30.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE.		1,200.00	280.00
	REMOVE AND REFIX POWER STEERING RACK AND PINION.		650.00	150.00
	FOUR WHEEL ALIGNMENT.		180.00	80.00
	RESET ABS LIGHT.	NOT NECESSARY	650.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.		750.00	120.00
			6,710.00	1,760.00
GRAND TOTAL			32,848.70	16,490.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,000.00
LESS EXCESS				-500.00
NETT LIABILITY				11,500.00

Report Ref No. CS/UOI20000927/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.