

Surveyor

REF: CS1/LPC20000945/ Ksd302

Special Instruction:  
Part by part: \$15,121.61  
Third Parties:  
Claimant:  
Surveyor: CA APPRAISER  
Workshop: AE AUTO

From (Person): Gerald Poh of LPC Date/Time: 14/01/2020  
Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation  
To Inspect Vehicle No: SJX 5315P  
at Workshop m/s: AE Auto  
of: 160 Sin Ming Drive # 06-01

Insured: JMC 4009  
Tel:

Policy No: Claim No: 19/19/19/vp02/293060  
Sum Insured: Excess:  
Make of Veh: D.O.A. 26/08/2019  
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT  
Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)  
Date/Time: 30/01/20 Submit Final Fig \$7,800/- 06 days (Red \$ 7321.61 48%; Original 7 days)

Date/Time	Action/Instruction
	SJX5315P - X
	JMC 4009 - X
	- Market value of the vehicle at the material time of the accident.

RECEIVED 30 JAN 2020

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : \$ 30k  
Salvage Value :  
Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:

190
190

- 1) Date/Time File Pass to 2) Date/Time File Return to
- 3) Date/Time File Pass to 4) Date/Time File Return to
- 5) Date/Time File Pass to 6) Date/Time File Return to

## Nivitha (LKK Auto)

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Tuesday, 14 January 2020 9:28 AM  
**To:** assignments  
**Subject:** FW: Second opinion - SJX 5315 P; DOL : 26/08/2019; 19/19/19/VP02/293060 [External Confidential]  
**Attachments:** 293060-POLICE REPORT.pdf; 293060-RC.pdf; 293060-SJX5315P-ADJ RPT.pdf  
**Sensitivity:** Confidential

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---


**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 14 January 2020 8:32 AM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>; KO SIEW LING <slko@lonpac.com>  
**Subject:** FW: Second opinion - SJX 5315 P; DOL : 26/08/2019; 19/19/19/VP02/293060 [External Confidential]  
**Sensitivity:** Confidential

## Lonpac External - Confidential

Dear Densie,

Kindly assist and should you require further documents, kindly liaise with Ko Siew Ling.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



**From:** KO SIEW LING

**Sent:** Monday, 13 January 2020 5:43 pm

**To:** GERALD POH WEE BIN

**Subject:** Second opinion - SJX 5315 P; DOL : 26/08/2019; 19/19/19/VP02/293060 [External Confidential]

**Sensitivity:** Confidential

## Lonpac External - Confidential

Dear Gerald,

Would appreciate if you could help to get a second opinion from your panel adjusters on the reasonability of cost of repairs to the claimant's vehicle vis a vis the circumstances of accident as well as the **market value of the vehicle at the material time of accident.**

Attached please find the following:-

- 1) Claimant's survey report and photographs.
- 2) Vehicle registration details.
- 3) Police reports.

I will split into few emails as the size is too large.

Thanks and regards,  
Siew Ling

*Lonpac External - Confidential data is for use by authorised external parties only.*

*Lonpac External - Confidential data is for use by authorised external parties only.*

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	402D
Vehicle Details	
Vehicle No.:	SJX5315P
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT CC 1.8T AT 3572H7
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	LTA1401417
Chassis No.:	WVWZZZ3CZAE555185
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$30,830.00
Original Registration Date:	22 Jun 2010
First Registration Date:	22 Jun 2010
Transfer Count:	3
Actual ARF Paid:	\$30,830.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2020
PARF Rebate Amount:	\$15,415.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$23,889.00
COE Rebate Amount:	\$1,035.00
<b>Total Rebate Amount:</b>	<b>\$16,450.00</b>

The information contained herein is correct as at 15 Jan 2020

OK

## VEHICLE APPRAISAL REPORT

Our Reference: **TP19-088117**  
 Your Reference: -  
 Vehicle Number: **SJX5315P**

Date: 18-Oct-19

To: **MUHAMMAD ADIB BIN MOHAMED EUSOPE**  
 C/o AE Auto Pte Ltd,  
 160, Sin Ming Drive,  
 Sin Ming Auto City #06-01,  
 Singapore 575722

**Assessment of Vehicle No:** SJX5315P  
**Date of Accident:** 26-Aug-19  
**Date of Inspection:** 29-Aug-19

We have carried out a physical assessment of **SJX5315P** at M/s AE Auto Pte Ltd according to your instruction on **29-Aug-19** and are pleased to submit our report herewith.

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX5315P	Make:	VOLKSWAGEN
Reg date:	2010	Model:	PASSAT CC 1.8T AT
Colour:	Brown	Engine No:	-
Type:	-	Chassis No:	WVWZZZ3CZAE555185
Type of Claim:	-	Odometer No:	119170 km
Market Value:	-	Engine Cap.:	1798 cc

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

#### (STATIC ONLY)

<b>General Condition</b> : Good	<b>Steering</b> : Serviceable	<b>Engine Modification</b> : NA
<b>Paint work</b> : Good	<b>Handbrake</b> : Serviceable	<b>Pre-accident damage</b> : NA
	<b>Footbrake</b> : Serviceable	

### CONDITION OF TYRES

Front Left Size:	Michein 235/35 R19 70%	Front Right Size:	Michein 235/35 R19 70%
Rear Left Size:	Michein 235/35 R19 70%	Rear Right Size:	Michein 235/35 R19 70%

*The above percentages represent the remaining life of the tyre treads*

### COST OF REPAIRS

	Repairer's S\$	Adjuster's S\$	Difference S\$
Parts	11,917.86	11,411.61	506.25
Labour	4,450.00	3,710.00	740.00
<b>Calculated Cost (S\$) :</b>	<b>16,367.86</b>	<b>15,121.61</b>	<b>1,246.25</b>

**Calculated Cost (S\$) :**

**Estimated Repair Period:**

**Repair Status:**


**7 days**

Surveyed on a "Without Prejudice" basis.

Our Reference: **TP19-088117**  
Your Reference: -  
Vehicle Number: **SJX5315P**

**DESCRIPTION OF DAMAGE**


At the time of inspection, this vehicle sustained damages to the **Rear portion**. Please see attached scheduled details.



**SPECIAL REMARKS**

We have not authorised repair. Under normal circumstances, estimated **7 working days** are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



**Ang Guea Kiang**  
Automotive Appraiser  
MSAAA

**Disclaimer**

Pursuant to your instruction, we have **NOT AUTHORIZED** repair. The assessment was conducted on a "**Without Prejudice**" basis. If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **CA APPRAISER PTE LTD** for any reliance on this report by any third party.

Our Reference : TP19-088117  
 Your Reference : -  
 Vehicle Number : SJX5315P

S/N	QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
<b>PARTS (LIST ITEMS)</b>					
1	1	BOOTLID <i>1643.75</i>	BUCKLED	2,205.30	2,205.30
2	1	BOOTLID EMBLEM 'PASSAT CC'	NECESSARY	625.00	62.50
3	1	BOOTLID WEATHERSTRIP <i>24640</i>	NECESSARY	292.30	292.30
4	1	BOOTLID LOCK	BENT	374.40	374.40
5	1	REAR BUMPER FASCIA <i>1465</i>	CUT/DEFORMED	1,925.30	1,925.30
6	1SET	REAR BUMPER CLIP	NECESSARY	60.00	60.00
7	1	REAR BUMPER MOULDING CENTER	CRACKED	312.70	312.70
8	1	REAR BUMPER MOULDING LH	CUT	220.50	220.50
9	1	REAR BUMPER MOULDING RH	CRACKED	220.50	220.50
10	1	REAR BUMPER SPONGE	COMPRESSED	150.20	150.20
11	1	REAR BUMPER REINFORCEMENT	BENT	560.30	560.30
12	1	REAR BUMPER CENTER SUPPORT	CRACKED	251.80	251.80
13	1	REAR BUMPER SIDE RETAINER LH	DISTORTED	176.50	176.50
14	1	REAR BUMPER SIDE RETAINER RH	DISTORTED	176.50	176.50
15	1	REAR END PANEL	DENTED	765.90	765.90
16	1	TAILLAMP LH <i>409.50</i>	CRACKED	869.50	869.50
17	1	TAILLAMP RH <i>409.50</i>	CRACKED	869.50	869.50
18	1	REAR EXHAUST SILENCER ASSY <i>1439</i>	<i>1. R</i>	2,208.09	2,208.09 <i>400.50</i>
				<b>12,264.29</b>	<b>11,701.79</b>
<b>Less Discount :</b>				10% <b>1,226.43</b>	10% <b>1,170.18</b>
<b>Parts Total : (10681.21)</b>				<b>11,037.86</b>	<b>10,531.61</b>
<b>SPECIAL NETT ITEMS</b>					
19	1SET	REVERSE SENSOR W/WIRE HARNES	MALFUNCTION	800.00	800.00 <i>600.50</i>
20	1	REAR END PANEL JOINT SEALANT	NECESSARY	80.00	80.00 <i>30.50</i>
<b>Special Nett Total:</b>				<b>880.00</b>	<b>880.00</b>
<b>Total Parts:</b>				<b>11,917.86</b>	<b>11,411.61</b>

*11761.211*

Our Reference : TP19-088117

Your Reference :-

Vehicle Number : SJX5315P

S/N	DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	OUR ASSESSMENT(S\$)	
<b>LABOUR &amp; MISC CHARGES</b>				
1	To remove & dismantle damaged parts to cut and chisel out attachment parts. To knock, straighten out dents where necessary to weld, refix, readjust & reshape same.	1,400.00	1,200.00	700
2	To respray painting on all affected parts, to supply paint material i.e. sand paper, rubbing compound, thinner, paint, lacquer etc.	1,600.00	1,400.00	800
3	To check wirings and lightings.	100.00	80.00	200
4	To remove and replace reverse sensors.	120.00	80.00	
5	To remove-refit rear boot compartment upholstery, carpet, garnish etc, in order to facilitate repair.	150.00	120.00	600
6	To supply and apply rust proofing treatment to affected panel.	200.00	150.00	600
7	To remove and install rear parking sensor and check for proper function.	80.00	80.00	X
8	To re-program/encode control units and interrogating fault memory in diagnostic system.	800.00	600.00	250
<b>Labour Total :</b>		<b>4,450.00</b>	<b>3,710.00</b>	
<b>TOTAL (PARTS &amp; LABOUR) :</b>		<b>16,367.86</b>	<b>15,121.61</b>	

Adjustment / Recommendations

1526161

Note : (For Part By Part Repair)

The workshop has agreed to undertake the repair at our adjusted amount of : **\$15,121.61**

Under normal circumstances, the repair period would be about 7 working days.

1/1/2018 ?

**Enquire Vehicle Registration Details**

**Owner Particulars**

NRIC/Passport /Company Cert No.: S9132402D  
 Owner ID Type: Singapore NRIC  
 Owner Name: MUHAMMAD ADIB BIN MOHAMED EUSOPE  
 Registered Address: APT BLK 130A CANBERRA CRESCENT #05-449 SINGAPORE 751130  
 Mailing Address: -  
 Birth Date: 01 Sep 1991

**Vehicle Particulars**

Vehicle No.: SJX5315P  
 Previous Vehicle No.: -  
 Effective Date of Ownership: 17 Jul 2018  
 Original Regn Date: 22 Jun 2010  
 Registration Date: 22 Jun 2010  
 Year of Manufacture: 2010  
 Vehicle Type: Passenger Motor Car  
 Vehicle Scheme: -  
 Vehicle Attachment 1: No Attachment  
 Vehicle Attachment 2: -  
 Vehicle Attachment 3: -  
 Vehicle Make: VOLKSWAGEN  
 Vehicle Model: PASSAT CC 1.8T AT 3572H7  
 Primary Colour: Brown  
 Secondary Colour: -  
 Passenger Capacity: 3  
 Chassis No.: WVVZZZ3CZAE555185  
 Engine No.: LTA1401417  
 Engine Capacity /Power Rating: 1798 cc / -  
 Maximum Power Output: 118.0 kW (158 bhp)  
 Propellant: Petrol

Max Unladen Weight: 1513 kg  
Maximum Laden Weight: 1960 kg  
Open Market Value: \$30,830.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 21 Jun 2020  
Minimum PARF Benefit: \$15,415.00  
No. of Transfers: 3  
IU Label No.: 1123805806  
COE No.: 2010030103000964D  
COE Expiry Date: 21 Jun 2020  
COE Category: B - Car (1601cc & above)  
COE Registration Category: B - Car (1601cc & above)  
Quota Premium (QP) / Prevailing Quota Premium: \$23,889.00 / -  
Actual QP Paid: \$23,889.00  
QP (Regn Cat): \$23,889.00  
OPC Cash Rebate Eligibility: No  
QP during COE Bidding Exercise: \$23,889.00  
Additional Registration Fee Rate: 100.00 %  
Actual ARF Paid: \$30,830.00  
Vehicle Lifespan Expiry Date: No Lifespan  
CO2 Emission: -  
CO Emission: -  
HC Emission: -  
NOx Emission: -  
PM Emission: -

Message: To renew the COE, the Prevailing Quota Premium payable is that of Category B.



**POLIS DIRAJA MALAYSIA**  
 REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S) Pegawal Penyiasat : R112169  
 Daerah : J/BAHRU SELATAN  
 Kontinjen : JOHOR  
 No Repot : TRAFIK JOHOR BAHRU(S)/022063/19  
 Tarikh : 26/08/2019  
 Waktu : 1829 PM  
 Bahasa Diterima : B. Malaysia

## Butir-butir Penerima Repot

Nama : MOHAMAD IZUDDIN B. ABD WAHAB No Personel : R205061 Pangkat : KONST/P  
 Butir-butir Jurubahasa (Jika Ada)  
 Nama : — No K/P (Baru) : — No Polis/Tentera : —  
 No Paspot : — Bahasa Asal : —  
 Alamat : —

## Butir-butir Pengadu

Nama : MUHAMMAD ADIB BIN MOHAMED EUSOPE  
 No K/P (Baru) : — No Polis/Tentera : — No Paspot : K1147636A  
 No Sijil Beranak : —  
 Jantina : Lelaki Tarikh Lahir : 01/09/1991 Umur : 27 tahun 11 bulan  
 Keturunan : Melayu Warganegara : Singapore  
 Pekerjaan : SENDIRI  
 Alamat Tempat Tinggal : APT BLK 130A CANBERRA CRESENT #05-449 SINGAPORE, 751130  
 Alamat Ibu/Bapa : —  
 Alamat Pejabat : —  
 No Tel (Rumah) : — No Tel (Pejabat) : — No Tel (HP) : 98005154  
 Emei : —

## Pengadu Menyatakan:-

PADA 26/08/2019 JAM LEBIH KURANG 1750HRS SAYA MEMANDU M/KAR NO SJX5315P DARI LARKIN MENUJU KE TAMAN PELANGI. PADA KETIKA ITU SAYA TIBA DI KM 3 JALAN JOHOR BAHRU AIR HITAM. SAYA JALAN TERUS DI LORONG KIRI, PERGERAKAN L/LINTAS BERGERAK PERLAHAN. TIBA-TIBA SEBUAH M/KAR NO JMC4009 DARI ARAH BELAKANG DATANG LALU MELANGGAR BELAKANG M/KAR SAYA. SAYA MENGALMI SAKIT BAHAGIAN LEHER, DAN BAHU BELAANG AKIBAT HENTAKAN. KEROSAKAN M/KAR SAYA ADALAH : (BELAKANG) BUMPER, SENSOR, NO PLATE, DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa(Jika ada):

Tandatangan Penerima Repot:

SALINAN YANG DIHUBUNGAN BENAR  
 (HANYA UNTUK TUNTUTAN SIVIL)

ID Pencetak | Tarikh @ Masa Cetak

: R112169 | 01/09/2019 12:49:32 PM

.....  
 KETUA TRAFIK DAERAH, JOHOR BAHRU, JOHOR  
 TIDAK BOLEK DIGUNAKAN UNTUK TUJUAN PERBICARAAN



## POLIS DIRAJA MALAYSIA

REPOt POLIS

**Balai** : TRAFIK JOHOR BAHRU(S)      **Pegawai Penylasat** : R112169  
**Daerah** : J/BAHRU SELATAN      **No Repot Bersangkut** : TRAFIK JOHOR BAHRU  
**Kontinjen** : JOHOR      (S)022063/19  
**No Repot** : TRAFIK JOHOR BAHRU(S)022065/19  
**Tarikh** : 26/08/2019  
**Waktu** : 1926 PM  
**Bahasa Diterima** : B. Malaysia

### Butir-butir Penerima Repot

**Nama** : MOHAMAD IZUDDIN B. ABD WAHAB      **No Personel** : R205061      **Pangkat** : KONST/P  
**Butir-butir Jurubahasa (Jika Ada)**  
**Nama** : ---      **No K/P (Baru)** : ---      **No Polis/Tentera** : ---  
**No Paspot** : ---      **Bahasa Asal** : ---  
**Alamat** : ---

### Butir-butir Pengadu

**Nama** : TAN YONG HOE  
**No K/P (Baru)** : 780528015703      **No Polis/Tentera** : ---      **No Paspot** : ---  
**No Sijil Beranak** : ---  
**Jantina** : Lelaki      **Tarikh Lahir** : 28/05/1978      **Umur** : 41 tahun 2 bulan  
**Keturunan** : Cina      **Warganegara** : Malaysia  
**Pekerjaan** : SWASTA  
**Alamat Tempat Tinggal** : NO 86A JLN BENTARA LUAR TMN ISKANDAR 80050 JOHOR BAHRU JOHOR MALAYSIA  
**Alamat Ibu/Bapa** : ---  
**Alamat Pejabat** : ---  
**No Tel (Rumah)** : ---      **No Tel (Pejabat)** : ---      **No Tel (HP)** : 0177613889  
**Emel** : alvintyh78@gmail.com

### Pengadu Menyatakan:-

PADA 26/08/2019 JAM LEBIH KURANG 1750HRS SAYA MEMANDU M/KAR NO JHU5964 DARI KEMPAS MENUJU KE TAMAN PELANGI. PADA KETIKA ITU SAYA TIBA DI KM 3 JALAN JOHOR BAHRU AIR HITAM. PERGERAKAN L/LINTAS BERGERAK PERLAHAN. SAYA MEMPERLAHANKAN M/KAR SAYA. TIBA-TIBA SEBUAH M/KAR NO JMC4009 DI HADAPAN SAYA BREK. SAYA TURUT BREK NAMUN M/KAR SAYA MEGELUNGSUR JUGA KE HADAPAN DAN TERLANGGAR JUGA BELAKANG M/KAR TERSEBUT. SAYA TIDAK MNEGALMI APA-APA KECEDERAAN. KEROSAKAN M/KAR SAYA ADALAH : (DEPAN) BUMPER, LAMPU BESAR KANAN, DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa(Jika ada) :

Tandatangan Penerima Repot:

SALINAN YANG DISAHKAN BENAR  
(HANYA UNTUK TUNTUTAN SIVIL)

ID Pencetak | Tarikh @ Masa Cetak : R112169 | 01/09/2019 12:49:57 PM

.....  
 PETUA TRAFIK JOHOR BAHRU JOHOR  
 IDAK BOLEK DIGUNAAN UNTUK TUJUAN PERBERKAPAN



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Volkswagen Touran 1.4A TSI Comfortline,



Accident Free, Very Low Mileage, 4 Years Warranty And 2 Free Servicing Remaining  
Direct Owner [StarAd](#)

**Lake View Credit Pte Ltd** [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted  20 results/page

1 vehicles

Volkswagen Passat

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Volkswagen Passat	Any	Any	2010	Any	Any	Any	Available
	<b>Volkswagen Passat 1.8T</b>	<b>\$26,800</b>	<b>\$13,840 /yr</b>	16-Nov-2010	1,798 cc	-	Luxury	Available
Cny Promo Cheapest In Town All Wear N Tear Replaced Gear Box Mu Replace 1yr Plus Ago None Oil Leak, With Upgraded Of 19inch Rims LTA Approve Exhaust, Coil Overs, Touch Screen Stereo Also Cheaper Then Rental So Call For Apt To View.								
Posted: 22-Jan-2020 Tags: 2010 Volkswagen Passat, 2010 volkswagen passat, Volkswagen Passat, volkswagen passat, Volkswagen, Passat, passat, Used Volkswagen								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volkswagen Passat, Volkswagen Passat Singapore, used Volkswagen Passat Singapore, used Volkswagen Passat, used vehicles Singapore or even buy used Volkswagen Passat Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**



Your Ref: 19/19/19/VP02/293060

Date: 30<sup>th</sup> Jan 2020

Our Ref: CS1/LPC20000945/Ksd3e2

**M/s Lonpac Insurance Bhd**

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJX 5315P**

**INSURED VEHICLE: JMC 4009**

**ACCIDENT DATE: 26/08/2019**

We thank you for your instruction on 14/01/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJX 5315P from M/s CA Appraiser.
- b) Polis Diraja Malaysia of Vehicles SJX 5315P, JHU 5964 and JMC 4009.
- c) Colour damaged vehicle photographs of SJX 5315P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJX 5315P
Make & Model	: Volkswagen Passat CC 1.8T AT 3572H7
Year of Registration	: 2010
Chassis Number	: WVWZZZ3CZAE555185
Engine Capacity	: 1798 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 5315P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID	BUCKLED	2,205.30	1,643.75
1	BOOTLID EMBLEM 'PASSAT CC'	NECESSARY	62.50	62.50
1	BOOTLID WEATHERSTRIP	NECESSARY	292.30	246.10
1	BOOTLID LOCK	BENT	374.40	374.40
1	REAR BUMPER FASCIA	CUT / DEFORMED	1,925.30	1,465.00
1	SET REAR BUMPER CLIP	NECESSARY	60.00	60.00
1	REAR BUMPER MOULDING CENTER	CRACKED	312.70	312.70
1	REAR BUMPER MOULDING LH	CUT	220.50	220.50
1	REAR BUMPER MOULDING RH	CRACKED	220.50	220.50
1	REAR BUMPER SPONGE	COMPRESSED	150.20	150.20
1	REAR BUMPER REINFORCEMENT	BENT	560.30	560.30
1	REAR BUMPER CENTER SUPPORT	CRACKED	251.80	251.80
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	176.50	176.50
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	176.50	176.50
1	REAR END PANEL	DENTED	765.90	765.90
1	TAILLAMP LH	CRACKED	869.50	409.50
1	TAILLAMP RH	CRACKED	869.50	409.50
	LESS 10% DISCOUNT		-949.37	-750.57
			<b>8,544.33</b>	<b>6,755.08</b>
1	REAR EXHAUST SILENCER ASSY (LOCAL REPAIR)	DENTED	2,208.09	400.00
	LESS 10% DISCOUNT		-220.81	-
			<b>1,987.28</b>	<b>400.00</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR W/WIRE HARNESS (SN)	MALFUNCTION	800.00	600.00
1	REAR END PANEL JOINT SEALANT (SN)	NECESSARY	80.00	30.00
			<b>880.00</b>	<b>630.00</b>
<b><u>LABOUR</u></b>				
	TO REMOVE & DISMANTLE DAMAGED PARTS TO CUT AND CHISEL OUT ATTACHEMENT PARTS. TO KNOCK, STRAIGHTEN OUT DENTS WHERE NECESSARY TO WELD, REFIX, READJUST & RESHAPE SAME.		1,400.00	700.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON ALL AFFECTED PARTS, TO SUPPLY PAINT MATERIAL I.E. SAND PAPER, RUBBING COMPOUND, THINNER, PAINT, LACQUER ETC.		1,600.00	800.00
	TO CHECK WIRINGS AND LIGHTINGS.		100.00	20.00
	TO REMOVE AND REPLACE REVERSE SENSORS. }		120.00	80.00
	TO REMOVE - REFIT REAR BOOT COMPARTMENT UPHOLSTERY, CARPET, GARNISH ETC, IN ORDER TO FACILITATE REPAIR.		150.00	60.00
	TO SUPPLY AND APPLY RUST PROOFING TREATMENT TO AFFECTED PANEL.		200.00	60.00
	TO REMOVE AND INSTALL REAR PARKING SENSOR AND CHECK FOR PROPER FUNCTION. }		80.00	-
	TO RE-PROGRAM / ENCODE CONTROL UNITS AND INTERROGATING FAULT MEMORY IN DIAGNOSTIC SYSTEM.		800.00	250.00
			4,450.00	1,970.00
	<b>GRAND TOTAL</b>		<b>15,861.61</b>	<b>9,755.08</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,800.00</b>

Report Ref No. CS1/LPC20000945/Ksd3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.