

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 16-Jan-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: <i>Cecilia</i>	VEHICLE NO	: SKX782U
ADDRESS	:	MODEL	: NISSAN X-TRAIL 2.0
<u>ACCIDENT DETAILS</u>	DATE : 13-Jan-20	<i>JNIJANT 32Z0001187</i>	
	TIME : 16:15HRS		
THIRD PARTY REQUESTOR / CONTACT : DEON			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAILGATE <i>Defed</i>	1	\$ 4,200.00	\$ <u>4,200.00</u>
2	TAILGATE LOGO <i>neu</i>	1	\$ 62.00	\$ 62.00
3	TAILGATE EMBLEM 'X- TRAIL' <i>neu</i>	1	\$ 110.00	\$ 110.00
4	TAILGATE LOCK <i>Defed</i>	1	\$ 570.00	\$ <u>570.00</u>
5	TAILGATE WEATHERSTRIP <i>Defed</i>	1	\$ 140.00	\$ 140.00
6	TAILGATE WINDSCREEN MOULDING <i>neu</i>	1	\$ 90.00	\$ 90.00
7	REAR BUMPER <i>Defed</i>	1	\$ 1,550.00	\$ <u>1,550.00</u>
8	REAR BUMPER LOWER LID <i>neu</i>	1	\$ 450.00	\$ 450.00
9	REAR BUMPER LOWER LID CENTER GARNISH <i>Defed</i>	1	\$ 70.00	\$ 70.00
10	REAR BUMPER SIDE RETAINER <i>neu</i>	2	\$ 39.00	\$ 78.00
11	REAR BUMPER TOWING COVER <i>neu</i>	1	\$ 110.00	\$ 110.00
12	REAR BUMPER REFLECTOR <i>neu</i>	2	\$ 70.00	\$ 140.00
13	REAR BUMPER REINFORCMENT <i>Defed</i>	1	\$ 560.00	\$ <u>560.00</u>
14	REAR BUMPER TOP CHROME <i>neu</i>	1	\$ 320.00	\$ 320.00
15	END PANEL TOP GARNISH <i>Defed</i>	1	\$ 90.00	\$ 90.00
16	END PANEL <i>Defed</i>	1	\$ 450.00	\$ 450.00

Part Prices checked P.S.

893

*7313
6581.70*

TOTAL PRICE \$ 8,990.00
 LESS 10% \$ 899.00
SUB TOTAL PRICE \$ 8,091.00

SPECIAL NETT PRICE

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>neu neu</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>neu</i>	1	\$ 100.00	\$ 100.00
3	REAR BUMPER CLIPS(SET) <i>neu</i>	1	\$ 22.00	\$ 22.00

4	REAR END PANEL INSULATOR SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
5	REAR END PANEL TOP GARNISH CLIPS(SET) <i>New</i>	1	\$ 150.00	\$ 150.00	<i>10</i>
6	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

352

TOTAL \$ 692.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>800</i>	
3	TUFF COAT	\$ 120.00	<i>60</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>X</i>	
6	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 180.00	<i>60</i>	
7	REMOVE AND REFIX REAR WINDSCREEN	\$ 220.00	<i>120</i>	
8	TO REMOVE AND REFIX REVERSE SENSOR	\$ 100.00	<i>50</i>	

TOTAL \$3,480.00

TOTAL PARTS COST : \$ 8,783.00
 TOTAL LABOUR COST : \$ 3,480.00
 TOTAL REPAIR COST : \$ 12,263.00

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

Adrian Lij 1920
H/S 15/01/20.

06 Days.

total: 8853.70

H/S: 7K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: