

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 22 January 2020 9:45 am
To: Carine Yeo TCBC
Cc: SUR
Subject: SLE 8285Z OD (MSIG) DOA - 13/01/2020

Dear Carine,

As instructed by our client, please proceed at repair cost not exceeding **\$ 38,000.00 or whichever lower (all in, including check and any supplementary items, and including excess \$800)** to repair the insured vehicle **SLE 8285Z** .

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Wishing you a Happy and Prosperous Lunar New Year!



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

