

MS First Capital Insurance Ltd
6 Raffles Quay #21-00
Singapore 048580 *Angk*
Tel:62222311 Fax:62223547

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : **SLB3823U**

CHASSIS NO : SALCA2AG7FH541714

ENGINE NO : 015053202234204PT

MAKE / MODEL : LAND ROVER / DISCOVERY SPORT 2.0 SI4 SE 7STR

DATE OF ACCIDENT : 11.01.2020 @ 0725HRS

YOUR INSURED VEHICLE NUMBER : **SHD6897Z**

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
1 REAR BOOT LID / <i>DD</i>	1	\$ 3,200.00	\$ 3,200.00 ✓
2 REAR BOOT LID SPORT EMBLEM / <i>npc</i>	1	\$ 100.00	\$ 100.00
3 REAR BOOT LID DISCOVERY EMBLEM / <i>npc</i>	1	\$ 100.00	\$ 100.00
4 REAR BOOT LID LAND ROVER EMBLEM / <i>npc</i>	1	\$ 180.00	\$ 180.00
5 REAR WINDSCREEN GLASS MOULDING / <i>npc</i>	1	\$ 250.00	\$ 250.00
6 REAR BOOT REFLECTOR LAMP LH X	1	\$ 980.00	\$ 980.00
7 REAR TAILLAMP LH ?	1	\$ 1,300.00	\$ 1,300.00 <i>900</i>
8 REAR BUMPER / <i>BR</i>	1	\$ 2,800.00	\$ 2,800.00 <i>1700</i>
9 REAR BUMPER REINFORCEMENT ?	1	\$ 1,050.00	\$ 1,050.00 <i>900</i>
10 REAR BUMPER RETAINER LH / <i>BR</i>	1	\$ 120.00	\$ 120.00
11 REAR UPPER END PANEL ?	1	\$ 1,300.00	\$ 1,300.00
12 REAR END PANEL ?	1	\$ 1,150.00	\$ 1,150.00
13 REAR FLOOR END PANEL ?	1	\$ 950.00	\$ 950.00
14 REAR FENDER LH / <i>DD</i>	1	\$ 2,550.00	\$ 2,550.00
15 REAR FENDER AIR GRILLE LH ?	1	\$ 150.00	\$ 150.00
16 REAR TAILLAMP PANEL LH ?	1	\$ 480.00	\$ 480.00
17 REAR FENDER UNDER-DUST COVER LH / <i>CRV</i>	1	\$ 680.00	\$ 680.00
18 REAR FENDER WHEEL ARCH- MOULDING LH / <i>cut</i>	1	\$ 550.00	\$ 550.00
19 REAR WHEEL-HOUSE INNER PANEL LH ?	1	\$ 3,450.00	\$ 3,450.00
20 REAR LOWER ARM LH ?	1	\$ 860.00	\$ 860.00
21 REAR DRIVE SHAFT LH X	1	\$ 2,800.00	\$ 2,800.00
22 REAR WHEEL BEARING LH ?	1	\$ 350.00	\$ 350.00
23 REAR KNUCKLE LH ?	1	\$ 1,400.00	\$ 1,400.00
24 REAR LH CONTROL ARM REAR ?	1	\$ 460.00	\$ 460.00
25 FRONT LH CONTROL ARM REAR ?	1	\$ 450.00	\$ 450.00
26 SHOCK ABSORBER LH ?	1	\$ 1,100.00	\$ 1,100.00
27 REAR STABILISER X	1	\$ 980.00	\$ 980.00
28 REAR EXHAUST SILENCER ?	1	\$ 4,100.00	\$ 4,100.00
29 REAR DOOR LH / <i>DD</i>	1	\$ 3,100.00	\$ 3,100.00 <i>2800</i>
	1	\$ 380.00	\$ 380.00
Total		\$	\$ 37,320.00
LESS 10%		\$	\$ 3,732.00
TOTAL PARTS		\$	\$ 33,588.00

SPECIAL NETT ITEM

1 REAR WINDSCREEN SEALANT / <i>npc</i>	1	\$ 100.00	\$ 100.00 <i>40</i>
2 REAR BUMPER CLIPS / <i>npc</i>	1	\$ 250.00	\$ 250.00 <i>30</i>
3 REVERSE SENSORS <i>(npc)</i> / <i>SL1</i>	1	\$ 380.00	\$ 380.00
4 REAR FENDER WHEEL ARCH- MOULDING CLIPS / <i>npc</i>	1	\$ 250.00	\$ 250.00 <i>30</i>
5 REAR FENDER UNDER-DUST COVER CLIPS / <i>npc</i>	1	\$ 250.00	\$ 250.00 <i>30</i>
6 REAR SPORT RIM LH / <i>cut</i>	1	\$ 2,400.00	\$ 2,400.00 <i>1800</i>
7 REAR TYRE LH / <i>BR (70%)</i> \$1000	1	\$ 2,400.00	\$ 2,400.00 <i>1000</i>
8 REAR DOOR WHEEL ARCH MOULDING LH CLIPS / <i>npc</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
9 REAR FENDER GLASS SEALANT / <i>npc</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
		\$	\$ 6,170.00

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.	\$	3,800.00	1250
				150 day X 5 (not include repair)
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$	2,200.00	1090
				150 p M x 4 (not include repair)
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	\$	180.00	50
4	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	\$	180.00	80
5	REMOVE & REFIT REAR WINDSCREEN GLASS	\$	180.00	170
6	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS.	\$	180.00	30
7	TO CARRY OUT DIAGNOSTIC TEST	\$	500.00	X
8	TO REMOVE AND REPLACE EXHAUST SILENCER AND PIPES	\$	580.00	?
9	TRANSFER DOOR MECHANISM	\$	180.00	50
10	REMOVE & REPLACE FENDER 1/4 GLASS	\$	190.00	80
11	REMOVE REAR UNDERCARRIAGE PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING REPLACING AFFECTED UNDERCARRIAGE PARTS AND PERFORM COMPUTERISED ALIGNMENT AND STEERING ALIGNMENT (STEERING ANGLE ZEROING)	\$	1,000.00	300

TOTAL LABOUR S\$:	\$	9,170.00
TOTAL PARTS S\$:	\$	39,758.00
7% GST	\$	3,424.96
GRAND TOTAL S\$:	\$	52,352.96

Prepared By : -

ANNIE TEW

Motor Claims

TEL: 6571 9642 FAX : 6278 5535

EMAIL: ainee@motorway.com.sg

Steve (LKK) WKL P/L
8322 8813 15/1/20, 2.00pm
P/P
Ry Bel SM
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: