



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI17024622/R1qd3e2-1

C/O: SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD
#12-03 CITY HOUSESINGAPORE 068877

Date : 10-02-2020



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 6107A	Veh. Inspected	SJG 5742D
Policy No.	DMPG17100004	Coverage (\$)	0.00
Claim No.	19.27471	Excess (\$)	0.00
Assign From	XIN YI	Assign Date	06/01/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA MAZDA2 AT R	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JM0DE10Y180119662	Colour	GREY
Odometer	155020	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	6 mm
L/H Front Tyre	185/55 R16	DUNLOP	6 mm
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/12/2017	Inspection Date	28/12/2017
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**