

ASS. PEC. BY:

REF: CS/ SPF 20001055/V9f3²²

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Eng Cui Fan

of SPF

Date/Time: 17.1.2020 9.54.A.M

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SG J 7722T

Insured:

Qx 700K

at Workshop m/s

Falcon - Asv

Tel:

67897997

of Blk 9006 Tampines street 93 #01-200

Policy No:

Claim No:

AEMD/105/009/2020/002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15 Jan. 2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.P. Endorsement:

Date/Time: 17.1.2020 9.54.A.M

Person Contacted: Joel

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SG J 7722T - X

Qx 700K - X

Do Not Finalise

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

SP7/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

w/c 20-7-2021 LTA 7428 1 yr 6 m.

20/1/20 45 @ 4300 submit. Used @ 3497.30, 45%.

Cor range: \$4300 - \$4370; Weekend: 02 days; Total: 07 days.

Veh No:

SGJ 77227

Yr Regn:

706

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

M/T Lancer

C.C

1584

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

179749

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMYSSTCS3A6U 011375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5-

mm

R/Bal.

5-

mm

L/Bal.

5-

mm

L/Bal.

5-

mm

D.O.A.

15/1/20

D.O.I.

17/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 JAN 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/1/2021 Marcus

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

220

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

7P

Lump Sum / I.B.I. (\$

4300

TOTAL

Summer Lee (LKK Auto)

From: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>
Sent: Friday, 17 January, 2020 9:32 AM
To: assignments; SUR; Admin-D (LKKAuto
Cc: Hafizul Farhan RAHMAT (SPF); Frankie THAY (SPF)
Subject: Pre-repair survey of SGJ 7722T (vs QX 700K DOA: 15-01-2020)

Importance: High

Good Morning,

Please assist to conduct Pre-repair survey of **SGJ 7722T (vs QX 700K DOA: 15 Jan 2020)** at the following address. Thank you.

Blk 9006 Tampines Street 93
#01-200 S(528840)

Person in-charge: Joel Ng at 67897997

Regards,

Eng Cui Fen (Ms)
1 Logistics Services Executive
Logistics Support and Services Division
Logistics Department
Singapore Police Force
DID: 68428401



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Shiau Chan (LKKAUTO)

From: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>
Sent: Monday, 20 January 2020 11:48 AM
To: Shiau Chan (LKKAUTO); assignments; SUR
Cc: Hafizul Farhan RAHMAT (SPF); Frankie THAY (SPF)
Subject: RE: Pre-repair survey of SGJ 7722T (vs QX 700K DOA: 15-01-2020)

Importance: High

Hi Shiau Chan,

Our ref: AEMD/105/009/2020/002. Thank you.

Regards,

Eng Cui Fen (Ms)
1 Logistics Services Executive
Logistics Support and Services Division
Logistics Department
Singapore Police Force
DID: 68428401



From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 20 January 2020 10:46 AM
To: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Subject: RE: Pre-repair survey of SGJ 7722T (vs QX 700K DOA: 15-01-2020)

Dear Cui Fen,

Kindly provide us the case reference of above mentioned.

"Wishing you a Happy and Prosperous Lunar New Year"

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2020 09:16
Date Of Accident	15/01/2020 08:45
Exact Location Of Accident	CLEMENCEAU AVE SLIP RD > PENANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGJ7722T
Insured/Policyholder	
Name Of Registered Owner	HO SZE KIAN
NRIC No	SXXXX670I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91283925
Alternative Phone No	OTHERS-91283925

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	2019-V0105062-VDP-R001
Cover Note Number	

Driver

Name of Driver	WONG SHEI CHONG
NRIC No	SXXXX640J
Date Of Birth	20/11/1987
Occupation	OUTDOOR
Date Of Driving Pass	26/05/2018
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98597896
Fax Number	
Contact Number	
Email Address	IMDINGLEBERRY@HOTMAIL.COM

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



A-SGJ 77227

B-QX 700K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Report No T/20200115/2031
attach

☐ claim OD / TP at Falcon-Air ☐ claim OD / TP Own W/shop ☐ Reporting Only


DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:



Sketch Plan Pg. 4



SINGAPORE
POLICE FORCE



1720200115/2031

2 of 3

Police Station Of Origin:
Orchard N.P.C.
51 Killyney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No: 1720200115/2031

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGJ7722T		V0105062		

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	WONG SHEI CHONG		ID No.	S8781640J
Related Vehicle	SGJ7722T (Car)		Contact No.	96597896
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B.3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the 15/01/2020 at about 8.45am, I was in the filtering lane waiting to go to the main road and suddenly a Police car hit the back of my vehicle. I got down from vehicle and we made a check. There's a dent at the rear right side of my car. I do not suffer any injuries and later Traffic Police officer came to the scene.

Case in-charge IO Afiq vide: A/20200115/0031

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 670I

Vehicle Details

Vehicle No.: SGJ7722T
Vehicle to be Exported: No
Intended Deregistration Date: 20 Jan 2020
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 1.6 A
Primary Colour: Red
Manufacturing Year: 2006
Engine No.: 4G18HK4987
Chassis No.: JMYSTCS3A6U011375
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$12,352.00
Original Registration Date: 21 Jul 2006
First Registration Date: 21 Jul 2006
Transfer Count: 3
Actual ARF Paid: \$9,441.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Jul 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$24,760.00
COE Rebate Amount: \$7,428.00
Total Rebate Amount: \$7,428.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jan 2020




Used Original
17" for
Jaguar Tyres
& Rims



Throttle
Controller For
Toyota
Alphard 2.5G



Improve
Overall Car
Response &
Power



Used Genesis
Amplifiers For
Audiophile

lancer

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced
Search
[Home](#) » [Used Cars](#) » [Iterly Motor Pte Ltd](#) » Mitsubishi Lancer 1.6A GLX (COE till 10/2021)

Mitsubishi Lancer 1.6A GLX (COE till 10/2021)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$13,500		
Depreciation	\$7,820 /yr	Reg Date	09-Oct-2006 (1yr 8mths 21days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	\$1,028 /yr	Transmission	Auto
Dereg Value	\$8,994 as of today (change)	OMV	\$12,829
COE	\$26,054	ARF	\$14,112
Engine Cap	1,584 cc	Power	79.0 kW (105 bhp)
Curb Weight	1,162 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L Inline 4 Cylinder 16 Valve, Smooth Auto Transmission, Disc Brakes, Airbags, Knockdown Rear Seat. View specs of the Mitsubishi Lancer (2006-2008)

Accessories

Sport Rims, Passed Inspection Exhaust System, Fitted Audio Systems.

Description

2 Owners Only, Smooth Engine, Regular Maintain, Tip Top Condition, Worth Value For Short Term Ride.

Category

COE Car

Status

Available

Resources**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

[Shortlist](#)[Compare](#)[Add note](#)[Report Error](#)[More Actions](#)**Seller Information****Iterly Motor Pte Ltd**

4 vehicles for sale, 13 sold in past 3 mths

61 Ubi Avenue 2 #02-07

Automobile Megamart

Tel: 64893113

[Search cars nearby](#)

Eddy

95168680

Posted on: 16-Jan-2020 | Last Updated on: 16-Jan-2020

[» more Financial info](#)

Upfront Payment

Transfer Fee
[Compare](#)

\$25

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

[Advanced Search](#)

Home » Used Cars » Motor Universe Credit Pte Ltd » Mitsubishi Lancer 1.6A GLX (COE till 06/2021)

Mitsubishi Lancer 1.6A GLX (COE till 06/2021)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

MOTOR UNIVERSE CREDIT PTE LTD

Price	\$11,800		
Depreciation	\$8,280 /yr	Reg Date	21-Jun-2006 (1yr 5mths 3days COE left)
Mileage	150,000 km (11k /yr)	Manufactured	2006
Road Tax	\$1,028 /yr	Transmission	Auto
Dereg Value	\$6,618 as of today (change)	OMV	\$12,442
COE	\$23,227	ARF	\$13,687
Engine Cap	1,584 cc	Power	79.0 kW (105 bhp)
Curb Weight	1,162 kg	No. of Owners	5
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Mitsubishi Lancer (2006-2008)

Description

100% Loan Available, Well Kept Interior And Exterior Condition. Spacious And Comfortable. Reliable And Easy Maintenance. Bank, In House Loan Application Available. Different Loan Schemes To Suit Your Purchase. Call Our Friendly Sales Executive For Viewing And Test Drive Now!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)


[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Motor Universe Credit Pte Ltd

34 vehicles for sale, 47 sold in past 3 mths

210 Turf Club Road Lot A32

Car Mall @ The Grandstand

Tel: 64655595

[Search cars nearby](#)

Johnson

97376599

Andy Cheng

86265699

Benson Hu

97997507

Alvan

84995363

Posted on: 14-Dec-2019 | Last Updated on: 17-Jan-2020

[Compare](#)



FALCON-AIR

SPF ACCIDENT CLAIMS SECTION
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY 298333

Attention : Motor Claim Department

Estimate : ES707564

Date : 16/01/2020
Vehicle Num. : SGJ 7722T
Make/Model : MIT. LANCER
Chassis/Eng# :
Accident Date : 15/01/2020
Claim No. :
Reference :
Policy No. :

not Alcohol
2/1
17/1/20
the photo of the repair
5 L. 2/s + 4300?

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1PC	REAR BUMPER		797.00
2.	1PC	REAR BUMPER TOP BEAM	181	269.00
3.	2PCS	TAILLAMP	404	882.00
4.	2PCS	TAILLAMP PANEL		442.00
5.	4PCS	TAILLAMP CLIP		40.00
6.	1PC	REAR END PANEL	505	595.00
7.	1PC	REAR END PANEL GARNISH		175.00
8.	1PC	BOOT LID	684	993.00
9.	1PC	BOOT LID LOCK		134.00
10.	1PC	BOOT LID WEATHERSTRIP		175.00
11.	1PC	BOOT LID LANCER EMBLEM		45.00
12.	1PC	BOOT LID LOGO		55.00
13.	1PC	BOOT LID GLX EMBLEM		45.00
14.	1PC	REAR NUMBER PLATE GARNISH		156.00
15.	2PCS	REAR BUMPER SIDE RETAINER		136.00
16.	1PC	SPARE TYRE BOARD		258.00
Nett Total S\$:				5,197.00
10.00% Discount S\$:				519.70
				4,677.30

1.	1SET	SPECIAL NETT ITEMS : REAR BUMPER CLIP	50.00
----	------	--	-------

CONTINUE / ...

LKH Auto Consultants hence notify
the Reparer of the following:

- To resurvey before after body painting
- To resurvey (damaged part(s)) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

p-3682
102
p-331380
s.w-33200
L-177000
541380
201
423104



FALCON-AIR

SPF ACCIDENT CLAIMS SECTION
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY 298333

Attention : Motor Claim Department

Estimate : ES707564

Date : 16/01/2020
Vehicle Num. : SGJ 7722T
Make/Model : MIT. LANCER
Chassis/Eng# :
Accident Date : 15/01/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1SET	REAR BUMPER RIVET	50.00	30
3.	1PC	BOOT LID C&C EMBLEM	80.00	50
4.	1SET	REVERSE SENSOR	250.00	200
5.	1PC	BOOT LID SEALANT	100.00	X
Special Nett Total S\$:			530.00	
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING			50.00	30
WATERTEST TO CHECK FOR LEAKAGE			50.00	X
TO APPLY BODY SEALANT ON BODY JOINTS			120.00	50
ANTI-RUST			120.00	60
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS			150.00	80
TRANSFER BOOT LID PARTS			100.00	50
LABOUR/PANEL BEATING			1,000.00	600
SPRAY PAINTING			1,000.00	900
Labour Total S\$:			2,590.00	

E. & O.E.	Total S\$:	7,797.30
-----------	-------------	----------

for FALCON-AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

FALCON-AIR AUTO SERVICES PTE LTD

[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office: 176 Sin Ming Drive #01-06/07/13; #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF20001055/Uqf3s2	
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675 ATTN: ENG CUI FEN			Date : 23-01-2020 Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 700K	Veh. Inspected	SGJ 7722T	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2020/002	Excess (\$)	0.00	
Assign From	ENG CUI FEN	Assign Date	17/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi LANCER (A)	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMYSTCS3A6U011375	Colour	RED	
Odometer	179749	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAES SEE DETAILS.				
5. General Information				
Accident Date	15/01/2020	Inspection Date	17/01/2020	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 7722T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DENTED	797.00	797.00
1	REAR BUMPER TOP BEAM (N)	BENT	269.00	181.00
2	TAILLAMP @ \$441.00 (N)	O/S CRACKED	882.00	404.00
2	TAILLAMP PANEL @ \$221.00 (N)	TO REPAIR SEE LABOUR	442.00	-
4	TAILLAMP CLIP @ \$10.00 (N)	NOT NECESSARY	40.00	-
1	REAR END PANEL (N)	BADLY DENTED	595.00	505.00
1	REAR END PANEL GARNISH (N)	TWISTED	175.00	175.00
1	BOOT LID (N)	BENT / BUCKLED	993.00	684.00
1	BOOT LID LOCK (N)	TWISTED	134.00	134.00
1	BOOT LID WEATHERSTRIP (N)	TWISTED	175.00	175.00
1	BOOT LID LANCER EMBLEM (N)	NECESSARY	45.00	45.00
1	BOOT LID LOGO (N)	NECESSARY	55.00	55.00
1	BOOT LID EMBLEM (N)	NECESSARY	45.00	45.00
1	REAR NUMBER PLATE GARNISH (N)	WARPED / CRACKED	156.00	156.00
2	REAR BUMPER SIDE RETAINER @ \$68.00 (N)	O/S BENT	136.00	68.00
1	SPARE TYRE BOARD (N)	TORN	258.00	258.00
	LESS 10% DISCOUNT		-519.70	-368.20
			4,677.30	3,313.80
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER RIVET (SN)	NECESSARY	50.00	30.00
1	BOOT LID C&C EMBLEM (SN)	NECESSARY	80.00	50.00
1	SET REVERSE SENSOR (SN)	CRACKED	250.00	200.00
1	BOOT LID SEALANT (SN)	NOT NECESSARY	100.00	-
			530.00	330.00
LABOUR				
	TO CHECK LIGHT SYSTEM AND WIRING.		50.00	30.00
	WATER TEST TO CHECK FOR LEAKAGE.	NOT NECESSARY	50.00	-
	TO APPLY BODY SEALANT ON BODY JOINTS.		120.00	50.00

Report Ref No. CS/SPF20001055/Uqf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ANTI-RUST.		120.00	60.00
	TO REMOVE / REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS.		150.00	80.00
	TRANSFER BOOT LID PARTS.		100.00	50.00
	LABOUR / PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL.		1,000.00	600.00
	SPRAY PAINTING.		1,000.00	900.00
			2,590.00	1,770.00
	GRAND TOTAL		7,797.30	5,413.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/SPF20001055/Uqf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,300.00 - \$4,370.00

RECOMMENDED REPAIR DAYS : 5

WEEKENDS : 2

TOTAL DAYS : 7

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.