

CHOO MOTOR SPRAY PAINTER  
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY  
SPORE 417883

Not Allowed  
make  
1/5 @ 4800  
4 days.

VEHICLE No:JPM 5127

1PC	TAILGATE	1255.00
1PC	TAILGATE KIA LOGO	
1PC	TAILGATE INNER LOCK	
1PC	TAILGATE WEATHERSTRIP	
1PC	TAILGATE GLASS MOULDING	
1PC	REAR BODY PANEL N/S	1815
1PC	REAR BUMPER	
2PCS	REAR BUMPER SIDE RETAINERS @ \$55.00	
1SET	REAR BUMPER CLIPS	
2PCS	TAILLAMPS @ \$480.00	425 x 2 = 850
1PC	TAILGATE DAMPER N/S	
1PC	TAILGATE 'RS' STICKER	
1PC	TAILGATE 'PREGIO' STICKER	
1PC	TAILGATE REFLECTOR N/S	

Body 20	\$1,480.00 ✓
neu	\$68.00 ✓
11	\$250.00 X
11	\$288.00 X
neu	\$181.00 ✓
Body 20	\$1,850.00 ✓
12	\$799.00 X
MSTM	\$110.00 1PC
neu	\$50.00 ✓
CNE	\$960.00 ✓
SIL	\$288.00 X
11	\$50.00 X
11	\$60.00 X
11	\$450.00 X
	\$6,884.00

TO CHECK WIRING  
TO DISMANTLE & REFIX REAR WINDSCREEN  
TO DISMANTLE & REFIX REAR BODY PANEL GLASS N/S  
TO TRANSFER TAILGATE MECHANISM  
TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

	\$80.00 20
	\$150.00 80
	\$150.00 100
	\$100.00 60
	\$100.00 60
	\$1,280.00 1000
	\$1,280.00 850
TOTAL	\$10,024.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

p- 4274  
102  
3846.60  
6016.6  
4813