

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AIG INSURANCE

Vehicle number SKW118T
Make / Model MERCEDES GLC250
Chassis number WDC2533462F503529
Accident date 15/1/20
Reference 2001-27

Acknowledged by Repairer

Qty Particulars Unit Price - SGD \$ Signature: Date:

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER / P	2014.80
1	REAR BUMPER LOWER GARNISH / CHY	930.00
1	REAR BUMPER LOWER CHROME GARNISH / CHY.	555.60
1	REAR BUMPER TOW COVER / SCH	99.20
1	REAR BUMPER REFLECTOR / Svc H / CRA	148.00
1	REAR BUMPER REINFORCEMENT ? / BT.	958.80
2	REAR BUMPER RETAINER ? / BR	350.40
1	REAR BUMPER INNER GUIDE ? / CRA	268.80
1	REAR BUMPER BRACKET ? / CRA	220.80
1	EXHAUST SILENCER ? / DD	2268.00
1	EXHAUST HEATSHIELD ? / Svc	408.00
2	EXHAUST MOUNTING ? / Svc	200.80
1	EXHAUST COVER ? / SCH. LH	516.20
2	TAILLAMP LH / CRA	2020.80
2	TAILLAMP CHROME GARNISH ? / X	420.00
1	END PANEL ? / X R.	2244.00
1	END PANEL TOP GARNISH / Svc	442.80
1	BOOTLID / Svc	3623.65
1	BOOTLID EMBLEM - LOGO / Svc	150.00
1	BOOTLID EMBLEM - GLC250 / Svc	123.60
1	BOOTLID EMBLEM - 4MATIC / Svc	123.60
		18087.85
Less 10%		1808.78
		16279.07
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP	50.00 30
1 SET	END PANEL TOP GARNISH CLIP	60.00 / Svc
1	REAR NUMBER PLATE	80.00 30
1	REAR NUMBER PLATE GARNISH	80.00 30
2	REAR REVERSE SENSOR	1200.00 ?
1	REVERSE CAMERA	2496.00 / Svc.
Subtotal		3966.00
Balance C/F		20245.07
LABOUR AND MISCELLANEOUS CHARGES		
Balance B/F		20245.07
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
3	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 80
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 100
5	PANEL BEATING ON AFFECTED AREAS	500.00 1400.00 300
6	SPRAY PAINTING ON AFFECTED AREAS	500.00 1200.00 250
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40
Subtotal		3310.00
Grand total		23555.07

Repair day - 4 days
Lump Sum Repet.
After paint photo
Sun Pm (LKK)
TP withua + Prizhu
20/01/2020