

ASS. REC. BY:

REF: CS/CT1 200012191 R19 f32

Special Instruction:

Survivor: Rasu

ASSIGNMENT (Office)

From (Person): Tan Kah Long of CT1 Date/Time: 20.1.2020 17.42PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 3232L Insured: SM 2 8215C

at Workshop m/s Kah motor Tel: 90 721769

of 255 Alexandra Road

Policy No: DM PCS 30418719000 Claim No: SMM 200 200384 Cor

Sum Insured: Excess:

Make of Veh: D.O.A. 16.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 20.1.2020 9.37AM Person Contacted: San Hai

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 3232L - X
	SM 2 8215C - X
28/1/2020 11.58am	Confirmed with Ng Sin Hai final fig to 5405.32, 5 days. (Red to 8992.70, 62%).

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV _____

To Inspect Vehicle No: SHK 3232L

at Workshop m/s KATH MOTOR

of 285, ALEXANDRA RD

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

DAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: SGK 3232L Yr Regn: 2016 / Aug
Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make:	Honda JAZZ 1.5 (A)	C.C	1498
Colour	MARON	A/C:	Insured / Std / NI / NA
Sp. Reading	030931	T/Radio:	Insured / Std / NI / NA
Eng/No:			

C/No: JHMK5850 HX200402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Worder~~ / Jammed / Leaked / Burnt or

Brake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ~~S~~Rim / STD A/Rim or

Tyre Size: F: 195/55R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	16/01/2020	D.O.I.	17/02/2020

*Survey held at KAH MOTOR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

1) 28/2 typist

Date/Time: File: Return to?

Report Form 4:

1. ~~34100~~ 34100 / 0.12 = 284166.67

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

☐ Interview (5)

Tech. Inc. Co.

$$\|f\|_{\text{Max}} = \max_{1 \leq i \leq n} |f(x_i)|$$

Survey Fee:

Transportation.

$$S + RS \rightarrow S_2$$

b. Finishes

3. Conclusions

1974

MECP

5405.32

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2020		20 Jan 2020 17:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	ELENA YAP SUAN BEE, ID: S1708675H
Vehicle Reg. No.:	SGK3232L
Claim Type:	TP / SNM20D200384C02
Vehicle Reg. No. (Insured):	SML8215C
	Policy/Cover Note No.: DMPCSN30418719000
	Policy No. (Claimant):
	Excess: S\$500.00
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2020]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 20 January 2020 5:40 PM
To: Ng Sin Hai; 'assignments'
Subject: RE: OUR REF: SNM20D200384/SML8215C/TKL - 3rd party direct settlement SGK3232L & your insured SML8215C/DOA:16/01/2020/Est \$

WITHOUT PREJUDICE

Dear Sin Hai,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]

Sent: Monday, January 20, 2020 5:20 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Subject: RE: OUR REF: SNM20D200384/SML8215C/TKL - 3rd party direct settlement SGK3232L & your insured SML8215C/DOA:16/01/2020/Est \$

Dear Kah Leong,

Any one of your choice is fine with me.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent: Monday, 20 January 2020 11:58 AM

To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Subject: RE: OUR REF: SNM20D200384/SML8215C/TKL - 3rd party direct settlement SGK3232L & your insured SML8215C/DOA:16/01/2020/Est \$

Without Prejudice

Dear Sin Hai,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, January 20, 2020 10:26 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; shng@kahmotor.onmicrosoft.com

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200384/SML8215C/TKL - 3rd party direct settlement SGK3232L & your insured SML8215C/DOA:16/01/2020/Est \$

Dear Kah Leong,

Please conduct PRS for SGK3232L.

Note : officer in charge – Kah Leong 63896193.

*** *Kindly quote our reference number when replying.*

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Friday, January 17, 2020 1:50 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: 3rd party direct settlement SGK3232L & your insured SML8215C/DOA:16/01/2020/Est \$

Dear All,

Please refer to the attached pdf, we are assisting our insured vehicle SGK3232L to file a 3rd party claim against your insured vehicle SML8215C and to request for direct settlement.

Kindly assist and expedite to check the claim liability soonest.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 February 2020 11:58 AM
To: Ng Sin Hai; Rasul (LKKAUTO); SUR
Subject: RE: Submission Pre-Invoice for vehicle SGK3232L

Dear Sin Hai,

WITHOUT PREJUDICE

Confirm final fig \$5,405.32 before GST and 5 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Thursday, 27 February 2020 11:03 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SGK3232L

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$5,405.32 (before GST)

No of working days : 05 days. (LOR)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2020 13:30
Date Of Accident	16/01/2020 17:30
Exact Location Of Accident	PASIR RIS DRIVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK3232L
Insured/Policyholder	
Name Of Registered Owner	ELENA YAP SUAN BEE
NRIC No	SXXXX675H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81239338
Alternative Phone No	OFFICE-81239338

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver


Name of Driver	ELENA YAP SUAN BEE
NRIC No	SXXXX675H
Date Of Birth	17/11/1965
Occupation	INDOOR
Date Of Driving Pass	10/09/1985
Driving Experience	34 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81239338
Fax Number	
Contact Number	OFFICE-81239338
Email Address	NOEMAIL

Vehicle Number: _____

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan

Vehicle Number: _____

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SGK3232L

Chassis No : JHMGK5850HX200402

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : ELENA YAP SUAN BEE

Ins Policy No. :

Date of Accident : 16/1/2020

Document No. : SQT20000296

Date : 17. Jan 2020

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : L15B31190250

Date | Time : 17. Jan 2020 1:51:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>me</i>	2	60.00		120.00 ✓	8.40	128.40
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>? x su</i>	1	320.00		320.00 X	22.40	342.40
33500-T5A-J02	TAILLIGHT ASSY.R. <i>X n</i>	1	244.60	5	232.37	16.27	248.64
33550-T5A-J02	TAILLIGHT ASSYL. <i>X n</i>	1	244.60	5	232.37	16.27	248.64
75701-T5A-000	EMBLEMH <i>me ? x n</i>	1	10.70	5	10.16 X	0.71	10.87
90301-ST0-003	NUTPUSH 3MM <i>me X n</i>	2	2.10	5	3.99 X	0.28	4.27
74890-T5B-911	GARNISH ASSYRR.LICENSE <i>X su</i>	1	219.10	5	208.14	14.57	222.71
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>me</i>	1	11.70	5	11.11 ✓	0.78	11.89
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>me</i>	2	7.10	5	13.49 ✓	0.94	14.43
73226-SZW-000	DAMPERSTD 5X5 <i>me</i>	1	8.70	5	8.26 ✓	0.58	8.84
04715-T5B-000ZZ	FACERR.BUMPER <i>de</i>	1	515.50	5	489.72 ✓	34.28	524.00
71593-T5A-000	SPACERR.RR.BUMPER <i>me</i>	1	11.50	5	10.92 ✓	0.76	11.68
71598-T5A-000	SPACERL.RR.BUMPER <i>me</i>	1	11.50	5	10.92 ✓	0.76	11.68
91505-TM8-003	CLIP,BUMPER <i>me</i>	8	2.30	5	17.48 ✓	1.22	18.70
71502-T5A-000	GARNISHR.RR.BUMPER <i>? x su</i>	1	14.60	5	13.87 X	0.97	14.84
71507-T5A-000	GARNISHL.RR.BUMPER <i>? x su</i>	1	14.60	5	13.87 X	0.97	14.84
75722-T5L-T01	EMBLEMRR. <i>? me</i>	1	11.90	5	11.30 ✓	0.79	12.09
66100-TAR-T10ZZ	PANEL COMPRR. <i>repair</i>	1	328.60	5	312.17	21.85	334.02
38387-TZ5-A01	ANTENNA ASSYL.F. <i>X su</i>	1	60.80	5	57.76	4.04	61.80

Printed on 17/1/2020 2:45:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SGK3232L

Chassis No : JHMGK5850HX200402

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : ELENA YAP SUAN BEE

Ins Policy No. :

Date of Accident : 16/1/2020

Document No. : SQT20000296

Date : 17. Jan 2020

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : L15B31190250

Date | Time : 17. Jan 2020 1:51:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74940-TZ5-A01	BUZZER ASSYSMART <i>Xsu</i>	1	62.00	5	58.90	4.12	63.02
68100-T5B-Z50ZZ	TAILGATE COMP <i>bt</i>	1	749.60	5	712.12	49.85	761.97
74440-T5A-003	WEATHERSTRIPTAILGATE <i>?</i>	1	92.30	5	87.68	6.14	93.82
74800-T5S-K61	LOCK ASSY, TAILGATE <i>?</i>	1	86.20	5	81.89	5.73	87.62
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>?</i>	1	60.80	5	57.76	4.04	61.80
84550-T5S-M10	BOX ASSYCARGO FLOOR <i>?</i>	1	116.90	5	111.05	7.77	118.82
84521-T5A-901ZA	LID ASSYSPARE TIRE <i>?</i>	1	194.70	5	184.96	12.95	197.91
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER <i>?</i>	1	58.70	5	55.76	3.90	59.66
Sum Item					3448.02	241.34	3,689.36
BOSUN	SUNDRIES <i>nec</i>	1	100.00 <i>30</i>		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	450.00 <i>Xnn</i>		450.00	31.50	481.50
BOJSE	SEALANT FOR TAILGATE	1	80.00 <i>60 nec</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 <i>Xnn</i>		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 <i>80</i>		180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00 <i>120</i>		180.00	12.60	192.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00 <i>60</i>		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00 <i>300</i>		560.00	39.20	599.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00 <i>300? Xnn</i>		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 <i>300</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>300</i>		560.00	39.20	599.20
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>1350</i>		3000.00	210.00	3210.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	4000.00 <i>1400</i>		4000.00	280.00	4280.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00 <i>Xnn</i>		560.00	39.20	599.20
Sum Labor					10950.00	766.50	11,716.50

Survey By

Printed on 17/1/2020 2:45:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT20000296	Page	3
	3 ANSON ROAD #16-00	Date	: 17. Jan 2020		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: NG SIN HAI		
Registration No	: SGK3232L	Engine No	: L15B31190250		
Chassis No	: JHMGK5850HX200402	Date Time	: 17. Jan 2020 1:51:24 PM		
Model	: JAZZ 1.5VTIR CVT 17YM	Surveyor Name	:		
Owner's Name	: ELENA YAP SUAN BEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 16/1/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	17/02/2020 @ 1730						
Excess							
Status							
Signature							
Total Amount					14,398.02	1,007.84	15,405.86
Total (Inclusive of GST)							15,405.86

Rasul
Hp 90010068
6 days
Remy before paint
email: rasul@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/1/2020 2:45:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0051770 / CHINA TAIPING
Chassis No: JHMGK5850HX200402
License No: SGK3232L
Mileage: 27715
Engine No: L15B31190250

Document No: SVO20011076
Printed By: SHNG
Order Date: 18. February 2020
Order Time: 12:00:44 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00 ✓	8.40	128.40
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.70	5	11.11 ✓	0.78	11.89
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	7.10	5	13.49 ✓	0.94	14.43
73226-SZW-000	DAMPER STD 5X5	1	8.70	5	8.26 ✓	0.58	8.84
04715-T5B-000ZZ	FACERR.BUMPER	1	515.50	5	489.72 ✓	34.28	524.00
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	5	10.92 ✓	0.76	11.68
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	5	10.92 ✓	0.76	11.68
91505-TM8-003	CLIP.BUMPER	8	2.30	5	17.48 ✓	1.22	18.70
75722-T5L-T01	EMBLEMRR.	1	11.90	5	11.30 ✓	0.79	12.09
68100-T5B-Z50ZZ	TAILGATE COMP	1	749.60	5	712.12 ✓	49.85	761.97
	SUM PARTS:				1,405.32	98.36	1,503.68
BOSUN	1466	1	30.00 ✓		30.00	2.10	32.10
	SUNDRIES						
BOJSE	1466	1	60.00 ✓		60.00	4.20	64.20
	SEALANT FOR TAILGATE						
BML02I	1466	1	80.00 ✓		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)						
BA02R	1466	1	120.00 ✓		120.00	8.40	128.40
	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)						
BODAMKIT	1466	1	60.00 ✓		60.00	4.20	64.20
	WINDSCREEN DAM KIT.						
BG02D	1466	1	300.00 ✓		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN, (N)						
BMI03D	1466	1	300.00 ✓		300.00	21.00	321.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKTG02R	1466	1	300.00 ✓		300.00	21.00	321.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BP06R	1610	1	1,350.00 ✓		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)						
BKRP02M	0669	1	1,400.00 ✓		1,400.00	98.00	1,498.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0051770 / CHINA TAIPING
Chassis No: JHMGK5850HX200402
License No: SGK3232L
Mileage: 27715
Engine No: L15B31190250

Document No: SVO20011076
Printed By: SHNG
Order Date: 18. February 2020
Order Time: 12:00:44 PM
Service Advisor: NG SIN HAI

ALIGN RR FLOOR PAN & RENEW
DAMAGE PARTS.

SUM LABOUR:	4,000.00	280.00	4,280.00
TOTAL SGD	5,405.32	378.36	5,783.68

Total Payable (SGD) 5,783.68

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2020		20 Jan 2020 17:42 Edit Adj Rpt	S\$5,405.32 Edit Estimates	S\$5,405.32 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	ELENA YAP SUAN BEE , ID: S1708675H		
Vehicle Reg. No.:	SGK3232L	Date of Loss:	16/01/2020 17:00 - :59 [41 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D200384C02	Policy/Cover Note No.:	DMPCSN30418719000
Vehicle Reg. No. (Insured):	SML8215C	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGK3232L (SNM20D200384C02)**
[SML8215C]

TP
ELENA YAP SUAN BEE
Jan 16 2020 5:00PM

[-]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:34	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:38	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:38	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	17/01/20 13:38	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	17/01/20 13:38	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	17/01/20 13:38	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	28/02/20 11:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	28/02/20 11:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	28/02/20 11:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
23	28/02/20 11:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
24	28/02/20 11:43	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
25	28/02/20 11:43	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
26	28/02/20 11:43	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/01/20 17:42	Pre-Repair Survey	Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:37	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	17/01/20 13:37	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View

View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:34	Video - Accident	Load MP4	

Assessment Reports

1 per page☒

No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:38	Accident Statement	Load HTM	

Photos/Images

3 per page☒

No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	17/01/20 13:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	17/01/20 13:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	17/01/20 13:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page☒

No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	17/01/20 13:37	Sketch Plan	Load TIF	
2	17/01/20 13:37	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST <input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001218/R1QF3S2

Date: 02/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30418719000	
Claimant Vehicle No :	SGK3232L	Insured Vehicle No :	SML8215C	
Date of Loss:	16/01/2020	Nature of Claim:	TP	Claim No: SNM20D200384C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK3232L		
Make & Model:	HONDA JAZZ, 1.5 (A)	Engine No:	L15B31190250
Reg. Date:	10/08/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850HX200402
Colour:	Maroon	Odometer:	30931 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,548.02	1,435.32	2,112.70	59.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,850.00	3,970.00	6,880.00	63.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,398.02	5,405.32	8,992.70	62.46
+ GST 7.00/7.00% (S\$)	1,007.86	378.37	629.49	62.46
Nett Amount (S\$)	15,405.88	5,783.69	9,622.19	62.46

INSPECTION

Date of Assignment:	20/01/2020		
Date Inspected:	17/02/2020	Inspected At:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2020)
Parts:	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK3232L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
2	4		*ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
3	1		*TAILLIGHT ASSY,R.	Not Necessary	232.37 FS	*- FS
4	1		*TAILLIGHT ASSYL.	Not Necessary	232.37 FS	*- FS
5	1		*EMBLEMH	Not Necessary	10.16 FS	*- FS
6	2		*NUTPUSH 3MM	Not Necessary	3.99 FS	*- FS
7	1		*GARNISH ASSYRR.LICENCE	Serviceable	208.14 FS	*- FS
8	1		*RUBBER C WINDSHIELD DAMPER	Necessary	11.11 FS	*11.11 FS
9	1		*RUBBER WINDSHIELD DAMPER	Necessary	13.49 FS	*13.49 FS
10	1		2pcs *DAMPERSTD 5X5	Necessary	8.26 FS	*8.26 FS
11	1		*FACERR.BUMPER	Deformed	489.72 FS	*489.72 FS
12	1		*SPACERR.RR.BUMPER	Necessary	10.92 FS	*10.92 FS
13	1		*SPACERL.RR.BUMPER	Necessary	10.92 FS	*10.92 FS
14	1		8pcs *CLIP, BUMPER	Necessary	17.48 FS	*17.48 FS
15	1		*GARNISHR.RR.BUMPER	Serviceable	13.87 FS	*- FS
16	1		*GARNISHL.RR.BUMPER	Serviceable	13.87 FS	*- FS
17	1		*EMBLEMRR.	Necessary	11.30 FS	*11.30 FS
18	1		*PANEL COMPRR.	Repair	312.17 FS	*- FS
19	1		*ANTENNA ASSYL.F.	Serviceable	57.76 FS	*- FS
20	1		*BUZZER ASSYSMART	Serviceable	58.90 FS	*- FS
21	1		*TAILGATE COMP	Bent	712.12 FS	*712.12 FS
22	1		*WEATHERSTRIP TAILGATE	Serviceable	87.68 FS	*- FS
23	1		*LOCK ASSY, TAILGATE	Serviceable	81.89 FS	*- FS
24	1		*LINING ASSYRR.PANEL	Serviceable	57.76 FS	*- FS
25	1		*BOX ASSYCARGO FLOOR	Serviceable	111.05 FS	*- FS
26	1		*LID ASSYSPARE TIRE	Serviceable	184.96 FS	*- FS
27	1		*LINING ASSYTALGATE LOWER	Serviceable	55.76 FS	*- FS
28	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	3,548.02	1,435.32
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY UNDERSIDE COATING.	New	450.00	0.00
2	SEALANT FOR TAILGATE.	New	80.00	60.00
3	SEALANT FOR REAR END PANEL.	New	80.00	0.00
4	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.	New	180.00	80.00
5	REMOVE & INSTALL REVERSE SENSOR.	New	180.00	120.00
6	WINDSCREEN DAM KIT.	New	80.00	60.00
7	REMOVE & INSTALL RR. WINDSCREEN.	New	560.00	300.00
8	RESET VEHICLE SMART ENTRY SYSTEM.	New	560.00	0.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS.	New	560.00	300.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.	New	560.00	300.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	3,000.00	1,350.00
12	CUT OFF & RENEW RR PANEL. STRAIGHTEN.	New	4,000.00	1,400.00
13	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.	New	560.00	0.00
Gross Labour Cost (\$\$)			10,850.00	3,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >