

# LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

CENTRAL NARCOTICS BUREAU  
CORPORATE SERVICES DIVISION  
BLK B  
POLICE CANTONMENT COMPLEX  
393 NEW BRIDGE ROAD

REF No. CS/CNB19016992/Keq2-1

REF Date 24/06/2021

Code CNB

## DISBURSEMENT FEE

Vehicle No. PC 7477G

Insured

Accident Date 4/9/2019

Inspection Date 30/9/2019

<b>LKK Cost of Claim paid to claimant on behalf of CNB</b>		
Repair Cost of SLR 7380U	\$	3,543.83
GST paid to claimant on behalf of CNB	\$	248.07
Loss of Use (\$140.00 x 7day)	\$	980.00
<b>Total Fee</b>	<b>\$</b>	<b>4,771.90</b>

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

YUYU