

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20001250	0/Bpa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG			Date: 28-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XE 7557D	Veh. Inspected	SKT 8257M	
	Policy No.	GA523990	Coverage (\$)	0.00	
	Claim No.	S0M02DPC	Excess (\$)	0.00	
	Assign From	RICHARD ANG	Assign Date	20/01/2020	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA3 1.5L	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JM6BM42A8G0311092	Colour	BLACK	
	Odometer	63199	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	POOR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/01/2020	Inspection Date	21/01/2020	
	Survey held at	TEAM AUTOPRO PTE LTD			
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				