

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party insurance is a "Without Prejudice" basis. No liability is accepted or allowed. Any liability is subject to final approval from insurance company.

Acknowledged by Repairer

Signature:

Date:

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-123, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Repair Estimate

Date: 14/1/2020

Vehicle Num: SJX4888J

Make/Model: VW JETTA

Chassis No: WVVZZZ1KZAN117682

S/N	PARTS	QTY	PRICE	TOTAL
1	Front RH fender X Repair	1	\$ 380.00	\$ 380.00
2	Front bumper cover	1	\$ 700.00	\$ 700.00
3	Center cooling grille X NN	1	\$ 200.00	\$ 200.00
4	Front LH bumper guide X NN	1	\$ 25.00	\$ 25.00
5	Front RH bumper guide X NN	1	\$ 25.00	\$ 25.00
6	Front LH lower bumper guide X NN	1	\$ 20.00	\$ 20.00
7	Front RH lower bumper guide X NN	1	\$ 20.00	\$ 20.00
8	Front foam insert ✓ DE	1	\$ 30.00	\$ 30.00
9	Front impact beam ✓ BT	1	\$ 330.00	\$ 330.00
10	Radiator grille X NN	1	\$ 300.00	\$ 300.00
11	Radiator grille chrome frame / CMA	1	\$ 490.00	\$ 490.00
12	Front LH chrome strip X NN	1	\$ 220.00	\$ 220.00
13	Front RH chrome strip X NN	1	\$ 220.00	\$ 220.00
14	Front LH lower cover strip X NN	1	\$ 40.00	\$ 40.00
15	Front RH lower cover strip X NN	1	\$ 40.00	\$ 40.00
16	Rear bumper / PR	1	\$ 680.00	\$ 680.00
17	Rear spoiler / CMA	1	\$ 390.00	\$ 390.00
18	Towing eye cap X NN	1	\$ 45.00	\$ 45.00
19	Rear impact beam ✓ BT	1	\$ 380.00	\$ 380.00
20	Rear bumper attachment strip X NN	1	\$ 60.00	\$ 60.00
21	LH rear bumper guide / PR	1	\$ 45.00	\$ 45.00
22	RH rear bumper guide X NN	1	\$ 45.00	\$ 45.00
TOTAL PARTS				\$ 4,685.00
TOTAL AMOUNT				\$ 4,685.00
MISCELLANEOUS ITEM				
1	Licence plate with casing BT	2	\$ 35.00	\$ 70.00
LABOUR				
1	Removal, refitting, panel beating of affected panels		\$ 900.00	\$ 900.00
2	Surface preparation and spray paint of affected panels		\$ 900.00	\$ 900.00
3	Sensor calibration, diagnostics and clearing of fault codes after repair		\$ 120.00	\$ 120.00
TOTAL				\$ 6,675.00
GST 7%				\$ 467.25
GRAND TOTAL				\$ 7,142.25

~~2305~~ 3045

-10%: ~~2074.5~~
2740.5

40

800

40

4520.5

~~3854.5~~

20%: ~~3000~~ 3600

6 Days.