

2/20/2020

ASS. REC. BY:

REF: CS / FCI 20001309 / Qud3 / N2
Special Instruction:

Surveyor: SUN Pin
CWS

ASSIGNMENT (Office)

From (Person): Rachel/Wu Limei of FCI Date/Time: 5:42pm @ 21/01/2020

Estimated Cost: _____ Bill to: _____

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFS 4184E Insured: SHD 3308C

at Workshop m/s Triple-T Automobile Tel: 6385 1171

of Bites Defu lane 10 # 01-574

P. Lic No: _____ Claim No: 020000486MF&H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/01/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp H.O.D. Endorsement: _____

Date/Time: 9:30am @ 21/1/2020 Person Contacted: Irene Vehicle IN/OUT (OUT)

Date/Time	Action/Instruction	Inspected	Notes
	SFS 4184E - CC3/A14/2008107 / Agn	<input checked="" type="checkbox"/>	Insp: Gosteed 15 kaki Bukit road 4 # 01-51 DOA: 20/01/2012
	SHD 3308C - CC3/A14/10022895 / Da 27 292		DOA: 7/11/2010

REF: FCI

AS. GEN BY Sun Pin.

ASSIGNMENT

From: _____ Date: 03/02/2020

Veh No: SFS 4184 E Yr Regn: 29/10/2011

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SFS 4184 E

Make: Audi S5 sportback. C.C: 2945

at Workshop m/s Go Steed
of Iskaki Bukit Road 4 # 01-51

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 74284 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: -

Policy No. _____

C/No: WAUZZZ8T9BA106330.

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: After 10am

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 255 / 35 R19

R: 255 / 35 R19

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: _____

Front

Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. 17/01/2020

D.O.I. 03/02/2022

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Go Steed.

CA / REV / REP. / 24 HRS ^{up}

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV = 59,000

PV = 47,749

NV = 11,251

4/3 Sent Preli by email

Confirm with

Finalize \$4,000 @ 4 days (L/S) (Red \$6652-00, 62%)

Date/Time, File Pass to?

: Prel. Report

Days Of Repair: 4

2x15 = 30

1) _____
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

170 + 30

2) 4/3/20 Typist

Add Fee: Site Insp (\$)

Transportation

50

Interview (\$)

Photos

50

Tech. Invs (\$)

Other

88

Wheel end (\$)

Report Format:

Lump Sum L.E.I.C: \$4000/=

TOTAL

388

RECEIVED 4 MAR 2020



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D20000486MFSH

Date: 04 March 2020

Our Ref: CS/FCI20001309/Qyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SGS4184E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/02/2020 at TRIPLE-T AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,652.00</u> .
Revised Estimate Amount	: S\$ <u>5,384.80</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
At the rear portion.



Comments / Present Status:

Damages Consistent.

Yours faithfully

OI SUN PIN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-01-2020	Our Ref No. D20000486MFSH
Accident Date	17-01-2020	Claim Type. Third Party
Insured Vehicle	SHD3308C	Third Party Vehicle. SFS4184E
Survey Location	BLK 5 DEFU LANE 10 #01-574	
Contact Person.	LOO SI LE	
Contact No.	63851171/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRIPLE-T AUTOMOBILE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



ANNOUNCING Carway

as sgCarMart Premium Dealer for the 3rd Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

2017 Lexus ES250 Executive Sunroof



1 Owner! Full Agent Maintained Under Warranty. Trust Motoring - StarAd

AutoInn
An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category ▼

Sort by Date Posted ▾ 20 results/page ▾

5 vehicles

Audi S5

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi S5	Any	Any	2011	Any	Any	Any	Available
	Audi S5 Cabriolet 3.0A TFSI Quattro	\$59,888	\$22,410 /yr	13-Jan-2011	2,995 cc	90,000 km	Sports	Available
Audi S5 Cabriolet With Bidded Plate Number SLQ616S, More Than \$20k Worth Of Repair Done And Accessories With Invoices As Prove. Capristo Exhaust (LTA Approved) 19" Sports Rims, 2 x Electric Seats/Memory, MMI High Colour Screen, Parking Assist, B&O Sound System...								
Posted: 17-Jan-2020 Tags: 2011 Audi S5, 2011 audi s5, Audi S5, audi s5, Audi, S5, s5, Used Audi								
	Audi S5 Sportback 3.0A TFSI Quattro	\$55,800	\$20,870 /yr	13-May-2011	2,995 cc	120,000 km	Sports	Available
New Clutch, New Rims, New Tyres, Newly Serviced. \$10k Wear And Tear Done Up This Year 2019. Full No-expenses Spared History With Optima Werke Prior To 2019. Car Is Tip Top Condition With Zero Creaking Noises Anywhere. Owner Leaving Sg Soon So Change Of Plan...								
Posted: 06-Jan-2020 Tags: 2011 Audi S5, 2011 audi s5, Audi S5, audi s5, Audi, S5, s5, Used Audi								
	Audi S5 Sportback 3.0A TFSI Quattro	\$59,800	\$20,970 /yr	30-May-2011	2,995 cc	141,844 km	Sports	Available
Cheapest S5 At 14k Depre! High Body Value Of 8k. Flexible Financing From Mthly \$900 Only! R55 Grille, Miltek Full Exhaust System! Accident-Free, Extremely Well Maintained Unit, View To Believe! High Trade In Available With Flexible In House Loan And Bank Loan Hu...								
Posted: 14-Dec-2019 Tags: 2011 Audi S5, 2011 audi s5, Audi S5, audi s5, Audi, S5, s5, Used Audi								
	Audi S5 Sportback 3.0A TFSI Quattro	\$59,000	\$19,120 /yr	30-Jun-2011	2,995 cc	91,000 km	Sports	Available
A Car Not To Be Missed! A Powerful 3.0 V6 Engine Producing 328bhp To The Wheels That Is Also Suitable For Daily Drives. A Large Bootspace And 4 Doors To Bring Your Friends And Family Around When U Need To. At The Flick Of A Button, Change From Comfort To...								
Posted: 16-Jan-2020 Tags: 2011 Audi S5, 2011 audi s5, Audi S5, audi s5, Audi, S5, s5, Used Audi								
	<p>Is your COE expiring? Let us help you renew it!</p> <p>Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.</p>							
	Audi S5 Cabriolet 3.0A TFSI Quattro	\$71,800	\$20,760 /yr	15-Sep-2011	2,995 cc	42,000 km	Sports	Available
Rare S5 3l Cabriolet With Super Low Mileage Of Just 42,000km Only, Expat Own With Regular Service With Record, Guarantee 100% Accident Free And No Modification, 100% Original Stunning Showroom Cond, Best Unit For COE Renewal Consideration, Sporty Black Wi...								
Posted: 03-Feb-2020 Tags: 2011 Audi S5, 2011 audi s5, Audi S5, audi s5, Audi, S5, s5, Used Audi								

Save this search criteria, to get email alerts whenever a match is found.

Make: Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	087B
Vehicle Details	
Vehicle No.:	SFS4184E
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Feb 2020
Vehicle Make:	AUDI
Vehicle Model:	S5 SPORTBACK 3.0 TFSI QU
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	CAK021338
Chassis No.:	WAUZZZ8T9BA106330
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$65,325.00
Original Registration Date:	29 Oct 2011
First Registration Date:	29 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$65,325.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2021
PARF Rebate Amount:	\$35,928.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$68,501.00
COE Rebate Amount:	\$11,821.00
Total Rebate Amount:	\$47,749.00

The information contained herein is correct as at 06 Feb 2020

OK

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 62385 1171

Vehicle No: SFS4184E

Model No. Audi S5

Chassis no. *

Accident Date : 17/01/2020

Owner : Chng Kian Woon Gerry

Date of Estimate : 03/02/2020

Estimate for Accident Vehicle No. SFS4184E

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Rear bumper / PD	1	\$1,685.00	\$1,685.00
2 Rear bumper lower lid / BR.	1	\$752.00	\$752.00
3 Rear bumper reinforcement / DO <i>photo</i>	1	\$687.00	\$687.00
4 Rear bumper side retainer / BR.	2	\$88.00	\$176.00
5 Rear chassis extension / BT	1 2	\$352.00	\$704.00
6 Boot lid - repair X R	1	\$1,587.00	\$0.00
7 Boot lid logo X nn	1	\$65.00	\$65.00
8 Rear end panel X R	1	\$562.00	\$562.00
9 Rear end panel top garnish X SVC	1	\$188.00	\$188.00
10 Rear parking sensor / short.	2 4	\$225.00	\$900.00 450
11 Rear exhaust tip chrome / SCH.	2	\$135.00	\$270.00
12 Rear exhaust pipe X SVC	1	\$1,958.00	\$1,958.00
Sub-Total Amount =			\$7,947.00
Less parts-discount = 0%			\$0.00
Sub-Total =			\$7,947.00
<u>Special Nett Items</u>	Qty	Unit Price	Total Amount
1 Rear bumper clips / Nec.	set	\$55.00	\$55.00 <i>35</i>
2 Rear end panel top garnish clips X nn	set	\$20.00	\$20.00
Sub-Total =			\$75.00
Total cost for parts =			\$8,022.00

Labour charges

1 Panel beating for replace and repair affected parts	\$1,100.00	400
2 Spray painting (Special paint)	\$1,200.00	450
3 Apply putty and anti-corrosion to affected parts.	\$80.00	40.
4 Wiring / bulb checking	\$50.00	30
5 R/R exhaust pipe	\$120.00	60
6 R/R reverse sensor	\$80.00	30
	<hr/>	
	\$2,630.00	
	<hr/>	

[Handwritten signature]
3/3/2022

Repair day - 4 days.

Lump Sum Repair
After paint photo.

Sun Pin (Lkk)
03/02/2022
TP without prejudice.

Total parts	=	\$8,022.00
Total labour	=	\$2,630.00
Total Amount	=	\$10,652.00
		<hr/>
		12239

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI20001309/Qyd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-03-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3308C	Veh. Inspected	SFS 4184E
Policy No.		Coverage (\$)	0.00
Claim No.	D20000486MFSH	Excess (\$)	0.00
Assign From	RACHELWU LIMEI	Assign Date	21/01/2020
2. Vehicle Particulars & Condition			
Make & Model	AUDI S5 SPORTBACK	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WAUZZZ8T9BA106330	Colour	SILVER
Odometer	74284	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/35 R19	GOODYEAR	5 mm
L/H Front Tyre	255/35 R19	GOODYEAR	5 mm
R/H Rear Tyre	255/35 R19	GOODYEAR	5 mm
L/H Rear Tyre	255/35 R19	GOODYEAR	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/01/2020	Inspection Date	03/02/2020
Survey held at	15 KAKI BUKIT ROAD 4 #01-51		
Repairer	TRIPLE-T AUTOMOBILE		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 4184E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,685.00	1,685.00
1	REAR BUMPER LOWER LID	BROKEN	752.00	752.00
1	REAR BUMPER REINFORCEMENT	DENTED	687.00	687.00
2	REAR BUMPER SIDE RETAINER @\$88.00	BROKEN	176.00	176.00
2	REAR CHASSIS EXTENSION @\$352.00	BENT (1 PC ONLY)	704.00	352.00
1	BOOT LID	TO REPAIR SEE LABOUR	1,587.00	-
1	BOOT LID LOGO	NOT NECESSARY	65.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	562.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	188.00	-
4	REAR PARKING SENSOR @\$225.00	SHORTED (2 PCS ONLY)	900.00	450.00
2	REAR EXHAUST TIP CHROME @\$135.00	SCRATCHED	270.00	270.00
1	REAR EXHAUST PIPE LESS 10% DISCOUNT	SERVICEABLE	1,958.00	-
			9,534.00	3,934.80
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	55.00	35.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
			75.00	35.00
LABOUR				
PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR END PANEL.			1,100.00	400.00
SPRAY PAINTING (SPECIAL PAINT).			1,200.00	450.00
APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS.			80.00	40.00
WIRING/BULB CHECKING.			50.00	30.00
R/R EXHAUST PIPE.			120.00	60.00
R/R REVERSE SENSOR.			80.00	30.00
			2,630.00	1,010.00

Report Ref No. CS/FCI20001309/Qyd3n2



GRAND TOTAL		12,239.00	4,979.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/FCI20001309/Qyd3n2

MARKET VALUE: \$59,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$47,749.00=NETT VALUE: \$11,251.00

OI SUN PIN
Asst. Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.