

22/03/2002

ASS. REC. BY:

REF: CS/MSG-20001311/kyfs

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Crystal Lu

of

MSG

Date/Time: 22.1.2020 10.57a.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHF 724T

Insured:

SGY 5427E

at Workshop m/s Trans-cab

Tel:

6287 6666

of NO 2 AMK Street 63

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 19.1.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.1.2020

11.39a.m.

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 724T - CS/INC 60147741 kgd3n2 D.O.A - 17/08/2019
	SGY 5427E - CS/LPC 12014121/ EVN D.O.A - 14/07/2012

ASS. REC. BY:

REF: MSG-1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$40,101/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1/10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 724T

Yr Regn:

12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

408654

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL 13 AUG 28 116P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Skilun

Front

Rear

R/Bal.

D

mm

R/Bal.

7

mm

L/Bal.

D

mm

L/Bal.

7

mm

D.O.A.

19/1/20

D.O.I.

22/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/2

Sent Preli by Merimen

20/3

US \$12300/- (Red \$98396-82, 88%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

23/1/20 Typist

Days Of Repair:

11

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

\$12300/-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 28 Feb 2020

Preliminary Advice

Insured Vehicle No	: SGY5427E	Accident Date	: 19/01/2020
TP Vehicle No	: SHF724T	Assignment Date	: 22/01/2020
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 11.00
Date of Inspection	: 22/01/2020		
Inspection At	: TRANS-CAB SERVICES PTE LTD (HQ) 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	110,696.82
Revised Amount	:S\$	25,711.90
Check Items (Estimated)	:S\$	14,100.98
Total	:S\$	39,812.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Wednesday, 22 January 2020 10:57 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: 22012020095027-0001.pdf

TP SHF724T DOA: 19/01/2020 SGY5427E (MSIG) Est: \$110K Car in.

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

-----Original Message-----

From: Winnie Chua <pingping_chua@sg.msig-asia.com>

Sent: Wednesday, 22 January 2020 9:58 AM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>

Cc: Candy Kong <candy.kong@transcab.com.sg>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>; Helene Phua <helene_phua@sg.msig-asia.com>

Subject: FW: TP SHF724T DOA: 19/01/2020 SGY5427E (MSIG) Est: \$110K Car in, please outsource.

Dear Crystal,

Car in as stated in letter, please outsource case.

Thank you.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey) Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Winnie Chua

Sent: Wednesday, 22 January 2020 9:56 AM

To: Christina Wong <Christina_Wong@sg.msig-asia.com>; Iryani Amin <iryani_amin@sg.msig-asia.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: TP SHF724T DOA: 19/01/2020 SGY5427E (MSIG) (Outsource case)

Liab: unclear

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey) Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg


CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Unclear -

CW/Yani

TRANS 得運私人有限公司
-cab TRANS-CAB SERVICES PTE LTD



Co. Reg. No: 200303878K

Facsimile Message

Date	22.01.2020		
To	MSIG Insurance (S) Pte Ltd		
Fax	6225 7402		
Your Ref	SGY5427E	Our Ref	SHF724T
From	Candy - Accident Department		
Fax	6257 1330		
Total Page/s	19 (including the cover)		

Kindly arrange for survey today. The taxi is in our premises.

Please note that our address of our Accident Repair Workshop is at No 2, Ang Mo Kio St 63.

You may contact me at my direct line 6213 0998 to confirm or email me at candy.kong@transcab.com.sg

TAXI IS IN WORKSHOP

PLEASE DO NOT ASSIGN TO Automobile Inspection Services Pte Ltd

Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 09:21
Date Of Accident	19/01/2020 23:40
Exact Location Of Accident	RAFFLES BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF724T
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	KWOK CHONG YUM
NRIC No	SXXXX272H
Date Of Birth	09/07/1949
Occupation	OUTDOOR
Date Of Driving Pass	17/03/1975
Driving Experience	44 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91386727
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 316 JURONG EAST STREET 32 #08-267
Postcode	600316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact*	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20200120/2007

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGY5427E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SI TIANG PENG

NRIC/Passport Number

SXXXX772G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

SUNTEC CITY

TANJONG PAGAR EXPRESSWAY

RAFFLES BLVD

A - SHF 724T

B - SGY 5427E

LANE 2

LANE 1

HOTEL PARKROYAL

MARINA SQUARE CARPARK


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DIS 2e attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature 
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200120/2007

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

1 of 3

Report No. T/20200120/2007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2020 02:39		Vide Report No.:		Station Diary No.: 13	
Informant's Particulars					
Name of Informant: KWOK CHONG YUM			Address: APT BLK 316 JURONG EAST STREET 32 #08-267 SINGAPORE 600316		
ID Type / ID No.: NRIC NO / S0005272H			Contact No.: Home/Office: Mobile: 91386727		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 70	Date of Birth: 09/07/1949	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 19/01/2020 23:40	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 RAFFLES BOULEVARD TEMASEK BOULEVARD At the junction between Raffles Boulevard and Temasek Boulevard				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGY5427E	Car	MITSUBISHI	GRANDIS	Red	Slightly Damaged	1
SHF724T	TAXI	RENAULT	LATITUDE	Red	Totally Damaged	2

Details of Pedestrians Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200120/2007

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

2 of 3

Report No. T/20200120/2007

CONTINUATION OF REPORT

Driver			
Name	SI TIANG PENG	ID No.	S0308772G
Related Vehicle	SGY5427E (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KWOK CHONG YUM	ID No.	S0005272H
Related Vehicle	SHF724T (TAXI)	Contact No.	91386727
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 19/01/2020 at about 2340hrs, I was driving my taxi bearing registration plate number SHF 724 T down Raffles Boulevard when suddenly a car bearing registration plate number SGY 5427 E drove out from Temasek Boulevard junction crossing the double white line to enter Marina Square Shopping Mall carpark. Unfortunately as I could not react on time and it was too sudden, I hit on to the right side of his vehicle which damaged his rear right door as well as the rear fenders. My taxi was seriously damaged and the engine started leaking. Both the airbags in the front were deployed in my taxi. No one was injured during the accident.

I am lodging a police report for my company to take necessary actions.



**SINGAPORE
POLICE FORCE**



T/20200120/2007

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

3 of 3

Report No. T/20200120/2007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 1 SHAMEERUDIN BIN TAJUDDIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/01/2020 02:39

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

SN 085

Authentication Stamp

NP168

Signature:

Singapore Police Force

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHF724T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jan 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002400
Chassis No.:	VF1ABL15AUC281169
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Dec 2014
First Registration Date:	31 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$19,010.00
Total Rebate Amount:	\$27,758.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jan 2020

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

Not Authorized
1/18mp @ 12,300 Max
Book Value ??

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JAN 2020

SHF 724T

VF1ABL15AUC281169

RENAULT

LATITUDE

19.1.2020

MSIG

31/12/2014

PART		LIST	
1	BUMPER COVER FRT	\$ <i>BT/CM</i> 747.20	✓
1	BUMPER SPOILER FRT	\$ <i>MT</i> 344.70	✓
1	BUMPER ABSORBER FRT	\$ <i>CM</i> 394.68	✓
1	BUMPER RETAINER FRT LH	\$ <i>D.Y</i> 101.40	✓
1	BUMPER SUPPORT FRT	\$ <i>SL</i> 10.70	X
1	BUMPER RETAINER FRT RH	\$ <i>D.Y</i> 101.40	✓
1	BUMPER SUPPORT FRT	\$ <i>SL</i> 10.70	X
1	BUMPER UNDERTRAY FRT	\$ <i>CM</i> 292.50	✓
1	BUMPER GRILLE LOWER FRT	\$ <i>MT</i> 147.00	✓
1	BUMPER FOG LAMP GRILLE RH	\$ <i>SL</i> 207.21	X
1	BUMPER FOG LAMP GRILLE LH	\$ <i>SL</i> 207.21	X
1	BUMPER BEAM FRT	\$ <i>R</i> 663.70	✓
2	BUMPER BEAM PAD FRT	\$ <i>SL</i> 24.50	X
1	HEADLAMP RH	\$ <i>Bo</i> 743.60	✓
1	HEADLAMP PANEL FRT RH	\$ <i>R</i> 128.30	✓
1	HEADLAMP LH	\$ <i>MT Bo</i> 743.60	✓
1	HEADLAMP PANEL FRT LH	\$ <i>R</i> 127.70	✓
1	HEADLAMP HARNESS	\$ <i>SL</i> 556.10	X
2	HEADLAMP ADJUST MOTOR	\$ <i>SL</i> 313.90	X
1	HORN	\$ <i>CM</i> 449.90	✓
1	HORN BRACKET	\$ <i>R</i> 21.90	✓
1	FENDER PANEL FRT RH	\$ <i>BU</i> 437.10	✓
1	WHEELARCH FRT RH	\$ <i>SL</i> 191.40	X
1	FENDER BRACKET FRT RH	\$ <i>R</i> 106.40	X
1	FENDER BRACKET LOWER RH	\$ <i>R</i> 11.80	X
1	FENDER INSULATOR RH	\$ <i>SL</i> 66.30	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

1	CHASSIS PANEL FRT RH	\$	<i>R</i>	592.90	X
1	CHASSIS PANEL SUPPORT FRT RH	\$	<i>R</i>	431.70	X
1	FENDER PANEL INNER FRT RH L70Y	\$	<i>R</i>	838.40	X
1	FENDER PANEL SUPPORT FRT RH L70Y	\$	<i>R</i>	432.00	X
1	WHEEL HOUSING PANEL FRT RH	\$	<i>R</i>	2,698.60	X
1	FENDER PANEL FRT LH	\$	<i>Bu</i>	414.40	✓
1	WHEELARCH FRT LH	\$	<i>Su</i>	112.30	X
1	FENDER BRACKET LOWER LH	\$	<i>Su</i>	11.80	X
1	FENDER INSULATOR LH	\$	<i>Su</i>	65.50	X
1	FENDER BRACKET FRT LH	\$	<i>R</i>	59.00	X
1	TOW COVER FRT	\$	<i>Su</i>	60.90	X
1	FRONT BRACE PANEL	\$	<i>Bu</i>	177.22	✓
1	RADIATOR GRILLE	\$	<i>CM</i>	969.90	✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Ru</i>	225.36	✓
1	RADIATOR GRILLE FRAME	\$	<i>Bu</i>	686.00	✓
1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	<i>Bu</i>	41.60	✓
1	BONNET	\$	<i>Bu</i>	1,312.70	✓
1	BONNET INSULATOR	\$	<i>CM</i>	294.30	✓
1	BONNET STRUT RH	\$	<i>Su</i>	53.30	X
1	BONNET HINGE RH	\$	<i>Diy</i>	237.40	✓
1	BONNET STRUT LH	\$	<i>Su</i>	53.30	X
1	BONNET HINGE LH	\$	<i>R</i>	236.50	X
1	BONNET LOCK	\$	<i>Bu</i>	152.80	✓
1	BONNET CABLE	\$	<i>Su</i>	55.20	X
1	BONNET CABLE COVER	\$	<i>Su</i>	80.60	X
1	BONNET SEAL OUTER	\$	<i>Su</i>	83.20	X
1	BONNET SEAL INNER	\$	<i>Su</i>	70.10	X
2	BONNET BUFFER	\$	<i>Su</i>	26.80	X
1	LOWER ARM LH L70Y	\$	<i>Su</i>	192.70	X
1	KNUCKLE ARM LH L70Y	\$	<i>Su</i>	481.50	X
1	ABSORBER FRT LH L70Y	\$	<i>Su</i>	274.10	X
1	DRIVESHAFT LH	\$	<i>R</i>	1,355.70	X
1	STABILIZER BAR FRT	\$	<i>Su</i>	427.90	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

1	KNUCKLE HUB+BEARING LH/RH L70Y	\$	272.30	X
1	LOWER ARM RH L70Y	\$	192.70	X
1	KNUCKLE ARM RH L70Y	\$	481.50	X
1	ABSORBER FRT RH L70Y	\$	274.10	X
1	DRIVESHAFT RH	\$	1,355.70	X
1	STEERING PINION RACK L70Y	\$	3,765.30	X
1	AUTO COMPUTER	\$	1,287.30	X
1	INJECTION COMPUTER	\$	2,706.30	X
1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70	X
1	WIPER RESERVOIR MOTOR	\$	82.60	X
1	WIPER RESERVOIR	\$	179.60	X
1	WIPER RESERVOIR NECK	\$	29.30	X
1	SUBFRAME OUTER FRT	\$	1,094.20	X
1	SUBFRAME BRACKET OUTER LH	\$	49.00	X
1	SUBFRAME BRACKET OUTER RH	\$	49.00	X
1	A/C CONDENSER	\$	1,537.80	X
1	A/C PIPE CONDENSER TO COMPRESSOR	\$	187.20	X
1	A/C PIPE CONDENSER TO EXPANSION VALVE	\$	380.20	X
1	A/C PIPE COMPRESSOR	\$	222.70	X
1	A/C PIPE	\$	486.50	X
1	A/C CONDENSER GARNISH LH UPPER	\$	57.30	X
1	A/C CONDENSER GARNISH RH UPPER	\$	56.70	X
1	A/C CONDENSER GARNISH LH	\$	67.90	X
1	A/C CONDENSER GARNISH RH	\$	67.70	X
1	A/C COMPRESSOR	\$	2,142.30	X
1	AIR COOLER	\$	598.90	X
1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	X
1	AIR INTERCOOLER HOSE (Short)	\$	375.14	X
1	TRANSMISSION COOLER	\$	1,219.30	X
1	TRANSMISSION COOLER PAD	\$	9.50	X
1	RADIATOR	\$	871.20	X
2	RADIATOR STUD UPPER	\$	11.10	X
2	RADIATOR BUSH UPPER	\$	11.10	X
2	RADIATOR MTG LOWER	\$	30.10	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

1 RADIATOR FAN COWLING	\$	cm	417.00	
1 RADIATOR FAN MOTOR LH	\$		826.70	✓
1 RADIATOR FAN MOTOR RH	\$		821.20	✓
1 RADIATOR TANK	\$		174.80	✓
1 RADIATOR HOSE UPPER	\$		97.50	✓
1 RADIATOR HOSE LOWER	\$		254.10	✓
1 RADIATOR TANK HOSE	\$		56.20	✓
1 FUSE BOX	\$	ln	987.39	X
1 ENGINE MOUNTING UPPER	\$		592.02	✓
1 ENGINE MOUNTING LOWER	\$		149.20	✓
1 A/C HEATER VALVE	\$	ln	484.50	X
1 TURBO DUCT	\$	ln	1,027.80	X
1 BASE BATTERY TRAY	\$	ln	363.40	X
1 ENGINE MOUNTING RH	\$	ln	153.50	X
1 ALTERNATOR	\$	ln	1,442.30	X
1 ENGINE HARNESS	\$	ln	1,501.60	X
1 BATTERY COVER	\$	ln	363.40	X
1 BATTERY	\$	ln	350.00	X
1 AIR CLEANER LOWER	\$	ln	271.26	X
1 AIR CLEANER HOSE	\$	ln	175.85	X
1 AIR CLEANER BOX	\$	ln	464.20	X
1 SUBFRAME INNER FRT	\$	ln	746.00	X
1 SUBFRAME BRACKET INNER LH	\$	ln	101.00	
1 SUBFRAME BRACKET INNER RH	\$	ln	101.00	
1 SUBFRAME SUPPORT INNER	\$	ln	69.50	
1 DOOR PANEL FRT LH	\$	ln	2,844.66	
1 DOOR HARNESS LH	\$	ln	2,640.00	
1 DOOR MIRROR ASSY LH	\$	ln	727.90	
1 DOOR PANEL FRT RH	\$	ln	2,844.66	
1 DOOR HARNESS RH	\$	ln	2,640.00	
1 DOOR MIRROR ASSY RH	\$	ln	1,483.40	
1 DOOR HINGE UPPER RH	\$	ln	261.28	
1 DOOR HINGE LOWER	\$	ln	300.55	
1 DOOR CHECK FRT LH/RH	\$	ln	194.77	

Suck

X

Trans-cab Auto Services Pte Ltd**AAD2001-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

1 DOOR FINISHER FRT RH	\$	<i>Sm</i>	515.06	X
1 ROCKER PANEL INNER GARNISH RH	\$	<i>Sm</i>	466.51	X
1 ROCKER PANEL INNER RH	\$	<i>n</i>	1,024.79	X
1 ROCKER PANEL OUTER RH	\$	<i>n</i>	1,184.99	X
1 ROCKER PANEL CENTER RH	\$	<i>n</i>	990.25	X
1 SEATBELT LH L70Y	\$	<i>Ts</i>	1,488.70	—
1 SEATBELT RH L70Y	\$	<i>Tm</i>	1,553.10	—
1 SEATBELT BUCKLE LH L70Y	\$	<i>Sm</i>	498.70	X
1 SEATBELT BUCKLE RH L70Y	\$	<i>Sm</i>	498.70	X
1 PASSENGER AIRBAG L70Y	\$	<i>Burn</i>	2,093.60	—
1 STEERING AIRBAG L70Y	\$	<i>h</i>	1,592.90	—
1 AIRBAG COMPUTER L70Y	\$	<i>me</i>	1,213.90	—
1 AIRBAG SENSOR L70Y	\$	<i>me</i>	502.90	—
1 AIRBAG SENSOR L70Y	\$	<i>me</i>	172.90	—
1 ROTARY SWITCH L70Y	\$	<i>me</i>	812.90	—
1 DASHBOARD	\$	<i>Ts</i>	3,102.00	—
1 GLOVE BOX	\$	<i>Sm</i>	526.90	} X
1 GLOVE BOX FLAP	\$	<i>Sm</i>	648.10	
1 FACE CONSOLE	\$	<i>Sm</i>	949.60	
1 DIESEL FILTER	\$	<i>Sm</i>	839.78	
1 COVER HYDR DISTRIBUTOR	\$	<i>Sm</i>	493.35	
1 ENGINE OIL SUMP	\$	<i>Sm</i>	97.70	}
1 SUPPORT ENGINE UPPER	\$	<i>Sm</i>	610.37	
1 ENGINE TOP COVER 2.0	\$	<i>cm</i>	139.80	—

TOTAL	\$	92,087.78
10%	\$	9,208.78
	\$	82,879.00

Special Nett

1 BUMPER CLIP FRT	\$	<i>me</i>	66.00	—
1 BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	X
1 BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	X
1 BUMPER GRILLE LOWER CLIP	\$	<i>me</i>	69.00	—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}	X	
1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50			
1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00			
2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00			
2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00			
1 WHEELARCH CLIP FRT RH	\$	na	30.50			
1 FRONT RIGHT TYRE	\$	Sh	300.00			
1 WHEELARCH CLIP FRT LH	\$	na	30.50	}		
1 FRONT RIGHT TYRE RIM	\$	Sh	380.00			
1SET Front licence plate with holder	\$	mit	80.00	K55N		
1SET RADIATOR GRILLE SCREW	\$	na	16.00	X		
1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00			
1 WINDSCREEN SEALANT	\$	na	109.20	}	X	
1 FRONT WINDSCREEN MOULDING	\$	na	120.00			
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00			
6 BONNET INSULATOR CLIP L70Y	\$	na	3.80			
2 BONNET CABLE CLIP L70Y	\$	na	4.20			
2 BONNET CABLE COVER SCREW L70Y	\$	na	5.00			
1 FRONT LH DOOR STICKER 'Trans-Cab'	\$	na	80.00			
1 FRONT LH DOOR STICKER 'Classic'	\$	na	80.00			
1 FRONT LEFT TYRE	\$	Sh	300.00			
1 FRONT LEFT TYRE RIM	\$	Sh	380.00			
1SET HEADLAMP SCREW	\$	na	4.70			
1 FRONT RH DOOR STICKER 'Trans-Cab'	\$	na	80.00			
1 FRONT RH DOOR STICKER 'Classic'	\$	na	80.00			
1SET BUMPER BEAM SCREW	\$	Sh	24.50			
2 BONNET LOCK NUT	\$	Sh	13.22			
1SET FENDER SCREW	\$	Sh	20.00			
1SET FENDER NUT	\$	Sh	5.90			
1SET DASHBOARD SCREW	\$	Sh	5.50			
1SET BONNET HINGE BOLT	\$	Sh	2.80			
TOTAL		\$	2,607.82			
TOTAL PARTS		\$	85,486.82			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151****LABOUR**

To transfer of front windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn	170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		9,000.00	8001
To transfer of front fender fittings, attachment and perform water seepage test.	\$		350.00	X
To rust-proofing of the affected areas.	\$		170.00	1201
Putty and spray painting of the affected portion.	\$		9,000.00	13201
To check ABS and brake efficiency, final checking and testing.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$		220.00	601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	h	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD2001-151**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00	<i>Y001</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 350.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	<i>5</i> 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>5</i> 380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>5</i> 440.00	X
To remove and renew engine and gear box mounting.	\$	<i>5</i> 380.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>501</i>
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00	<i>2501</i>

Trans-cab Auto Services Pte Ltd**AAD2001-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724TTo replace, refix and top up coolant for radiator \$ 170.00 *50/*Towing Fees \$ 150.00 *50/***TOTAL \$ 25,210.00****Over All Total \$ 110,696.82****LUMP SUM (REPAIR DAY)**~~30 DAYS~~*11 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: