



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
ZHANG XUETAO  5 CANBERRA DRIVE #12-09 SINGAPORE 768103  <b>Contact No</b>	<b>Cust No/Name</b>	KCV12523/ZHANG XUETAO
	<b>Reg No/Reg Date</b>	SMQ8636U / 06/12/201
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	MMBSTA13AKH003605
	<b>Engine No</b>	3A92UJC2338
	<b>Make/Model</b>	MIT/19MY ATTRAGE 1.2 CVT
	<b>Colour/Trim</b>	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV12523	CRDVCH	30/12/2019/ 15:38	BLC	442 / CocoLu	49507			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT DOOR LH								550.00
E PNT98000 SPRAY PAINT FOR FRT DOOR LH								420.00
E PNT88000 TRANSFER FRT DOOR TRIMS AND GLASS								200.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION								40.00
M SUNDRY Sundry								20.00
M PANEL ASSY,RR DOOR,LH					1.00	839.00	00.00	839.00
M TAPE,FR DOOR SASH,LH					1.00	29.00	00.00	29.00

Estimate

Confirm & accepted by

	<b>Nett</b>	<b>2,328.00</b>
<b>7% GST on</b>	<b>2328.00</b>	<b>162.96</b>
	<b>Total Payable</b>	<b>2,490.96</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.