

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:57

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016100 Date: 17/03/2021 Order: SKH9813P Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKH9813P (V 18537) Regn Date: 31/01/2013 Mileage: 109257 WIP No.: 27083
Model: A4 1.8T FSI MU 8K203H LIMITED Chassis: WAUZZZ8K6DA057923 Engine: CJE 017590 Dept: U
You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO DISMANTLE AND RENEW RHS FRONT FENDER AND RHS HEADLIGHT.TO REPAIR FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND BONNET	1100.00	1.00	1,100.00
X	A8K0821106J	FENDER (LAST)	1.00	931.50	745.20
X	AN 0161857	POP-RIVET	4.00	3.20	10.24
X	A8K0821136J	SUPPORT AP	1.00	111.50	89.20
X	A8K0853824C	STONEGUARD	1.00	68.30	54.64
X	A8K0805608B	MOUNTING AP	1.00	111.50	89.20
X	A8T0941454D	BRACKET AP	1.00	99.10	79.28
X	A8K0941044D	HEADLAMP	1.00	1027.00	821.60

Parts 1,889.36
Labour 0.00
Sublet 1,850.00
Menus 0.00
Lubricant 0.00

Sub-Total 2,939.36

7% GST 205.76

Grand Total 3,145.12



Received by

For & on behalf of
Premium Automobiles Pte Ltd