

ASS. REC. BY:

REF: C8/EG120001476/ESd30r Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): meimer Jacelyn Foo of EGI Date/Time: 24/11/2020 @ 12.02pm

Estimated Cost: Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDM65Y Insured: GBJ 6246S

at Workshop m/s Trans Eurocars Tel: 6331 0682

of 27A Tanjong Penjun

Policy No: Claim No: CDMCA20000130

Sum Insured: Excess:

Make of Veh: D.O.A. 18/01/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time: 12:13pm @ 24/11/2020 Person Contacted: Jobi Vehicle IN/OUT

Date/Time	Action/Instruction
	Palmarid (✓)
	SDM65Y-X
	GBJ 6246S-X
30/01/20	@ 14:16 pm revised PA to Jacelyn via meimer.

ASS. REC. BY:

Steve

REF:

EG1

ASSIGNMENT

From:

Date:

29/01/2020

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDM 65Y

at Workshop m/s

Trans Euokars

of

27A Tanjung Penjun

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:


11:30am (waiting)

(Policy Condition)

Jobi

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDM 65Y

Yr Regn:

15/6/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini Cooper

c.c

1499

Colour

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

30995

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WM WXM1520401637940

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/45R17

R:

V

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/1/20

D.O.I.

29/1/20

Survey held at

Trans Euokars, Tanjung Penjura

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/2/20

MV-99K

Final \$6809.61, 5 days (Jessica)

(C\$ 3,127.78 Red - 32%)

18/2/2020

RECEIVED 18 FEB 2020

Date/Time, File Pass to?

18/01/20

1)

Typ: 4

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

290

Transportation:

S + RS, SI

Photos

Others

11

TOTAL

261

Report Format:

Lump Sum / L.B.B. C

\$6,809.61 P/P

Nivitha (LKK Auto)

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: Friday, 24 January 2020 12:02 PM
To: Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: eva.kok@eurokars.com.sg; Phoebe Xie; jobithomas@eurokars.com.sg
Subject: RE: ERGO REF: CDMCG20000130 (GBJ6246S) / OUR REF: SDM65Y THIRD PARTY CLAIM
Attachments: 1181_001.pdf

Data Classification: Confidential, C3

**** NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

Thank you!

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9199
jacelyn.foo@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: jobithomas@eurokars.com.sg [mailto:jobithomas@eurokars.com.sg]
Sent: Friday, January 24, 2020 12:01 PM
To: Jacelyn Foo
Cc: eva.kok@eurokars.com.sg; Phoebe Xie
Subject: RE: ERGO REF: CDMCG20000130 (GBJ6246S) / OUR REF: SDM65Y THIRD PARTY CLAIM

Dear Jacelyn Foo,

Kindly assign to LKK.

Best Regards.



Jobi Thomas

Senior Insurance Claims Executive
27A Tanjong Penjuru, Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690
E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: 24 January 2020 11:33 AM
To: Jobi Thomas <jobithomas@eurokars.com.sg>
Cc: Eva Kok <eva.kok@eurokars.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>
Subject: RE: ERGO REF: CDMCG20000130 (GBJ6246S) / OUR REF: SDM65Y THIRD PARTY CLAIM

Data Classification: Confidential, C3

Dear Jobi,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	AA	Appraisal Associate

Thanks!

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.



www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: jobithomas@eurokars.com.sg [<mailto:jobithomas@eurokars.com.sg>]

Sent: Friday, January 24, 2020 7:55 AM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: eva.kok@eurokars.com.sg

Subject: YOUR REF: GBJ6246S / OUR REF: SDM65Y THIRD PARTY CLAIM

YOUR REF: GBJ6246S / OUR REF: SDM65Y THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle ASAP at 27A Tanjong Penjuru.

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Best Regards.



Jobi Thomas

Senior Insurance Claims Executive

27A Tanjong Penjuru, Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690

E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	041D
Vehicle Details	
Vehicle No.:	SDM65Y
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2020
Vehicle Make:	MINI
Vehicle Model:	COOPER HATCHBACK 3DR LED DSC
Primary Colour:	Green
Manufacturing Year:	2017
Engine No.:	39919952B38A15A
Chassis No.:	WMWXM520402G37040
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$24,466.00
Original Registration Date:	15 Jun 2017
First Registration Date:	15 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$16,253.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2027
PARF Rebate Amount:	\$12,189.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$39,839.00
Total Rebate Amount:	\$52,028.00

The information contained herein is correct as at 29 Jan 2020

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Jan 2020

Preliminary Advice

Insured Vehicle No	: GBJ6246S	Accident Date	: 18/01/2020
TP Vehicle No	: SDM65Y	Assignment Date	: 24/01/2020
Make	: MINI COOPER	Est. Duration of Repair	: 5.00
Date of Inspection	: 29/01/2020		
Inspection At	: TRANS EUROKARS PTE LTD - TANJONG PENJURU (HQ) 27A TANJONG PENJURU SINGAPORE 609042		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,937.39
Revised Amount	:S\$	6,706.26
Check Items (Estimated)	:S\$	276.71
Total	:S\$	6,982.97
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 12:16
Date Of Accident	18/01/2020 14:10
Exact Location Of Accident	ALONG FLYOVER OF BT TIMAH RD TOWARDS SUNGEI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM65Y
Insured/Policyholder	
Name Of Registered Owner	NOR'AINI BINTE AHMAD
NRIC No	S7204041D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94523312
Alternative Phone No	OFFICE-94523312

Vehicle Particulars

Manufacturer	MINI
Model	COOPER
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101404689-01
Cover Note Number	DRVO PREMIUM

Driver

Name of Driver	ABDUL RASHID BIN BUDIN
NRIC No	S1472304H
Date Of Birth	26/03/1961
Occupation	INDOOR
Date Of Driving Pass	22/11/1990
Driving Experience	29 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84289208
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	2C #02-11 HONG SAN WALK
Postcode	689049
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ6246S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KOTLA ASHOK REDDY
NRIC/Passport Number	036055545
Contact Number	82340020
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Vehicle No: SDM 55 Y

Report Date: 20/1/2020 Start Time: 12:12 PM

Report No: MT _____ D.O.A: 18/1/20

Make Model: Mini Cooper

Reporting Type: TP End Time: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.

20/1/2020 12:12


Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time:

20/1/2020 12:12

Reporting Centre Personnel's Signature
Name: Ganesh
NRIC/ Fin No: S993561

SKETCH PLAN




Along Flyover of Bukit Timah Road Towards Sungei Road


Vehicle A: SDM65Y	Vehicle B: GBJ6246S		
-------------------	---------------------	--	--

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.


20/1/2020 12:12
Policyholder's Signature
Date & Time:


20/1/2020 12:12
Driver's Signature (If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Ganesh
NRIC/ Fin No: S993561

Annex D

NOTICE OF REPORTING

This is to confirm that Abdul Rashid Bin Budin, NRIC: S1472304H, has reported to the Police a non-injury traffic accident which occurred along Bukit Timah Road, Fly Over towards Sungei Road.

On 18/01/2020 about 1410hrs involving the following vehicles:

Complainant's vehicle: SDM65Y

While my car SDM65Y was stationery along Bukit Timah Road towards Sungei Road, I felt a large impact at the rear. I was on the 2nd lane and I was stationery for about a minute as the traffic was very heavy. I do not know how the driver (GBJ6246S) manage to hit my vehicle (SDM65Y). No one was injured, no Police or ambulance attended to us.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt(3) T150394 Tay Kah Jun
Date: 20/01/2020 Time: 1116hrs



eS/D Ref: No: 35

Police Post/Unit: Bukit Timah NPC



Original - to be issued to informant
Duplicate - to be submitted to Traffic Police



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



ERGO INSURANCE PTE. LTD.		NAME : Ms Nor'Aini Binte Ahmad		WIP : 33624	
5 TEMASEK BOULEVARD		ADDRESS :		EXCESS :	
#04-01 SUNTEC TOWER FIVE				DATE: 23-Jan-20	
SINGAPORE 038985					
ATTN. : MOTOR CLAIMS		TEL : MR. ABDUL RASHID BI BUDIN @ 84289208			
FAX :					
VEH NO :	SDM65Y	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6331 0682
CHASSIS NO :	WMWXM520402G37040	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER	DATE REG.:	15-Jun-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES	
		QTY				
1	REAR BUMPER <i>x R</i>	1	M51.12.7.380.009		\$ 947.12	X
2	REAR BUMPER SPOILER <i>x MM</i>	1	M51.12.7.380.015		\$ 274.43	X
3	REAR BUMPER SPOILER CHROME <i>? / BR</i>	1	M51.12.7.365.737		\$ 103.35	/
4	TAILGATE CHROME <i>x MM</i>	1	M51.13.7.362.121		\$ 253.76	X
5	TAILGATE SPOILER SUPPORT <i>/ MC</i>	1	M51.62.7.337.600		\$ 32.70	/
6	REAR WINDSCREEN STRIP <i>/ MC</i>	1	M51.13.7.320.540		\$ 131.04	/
7	REAR WINDSCREEN MOUNT LH <i>/ MC</i>	1	M51.13.7.302.545		\$ 55.38	/
8	REAR WINDSCREEN MOUNT RH <i>/ MC</i>	1	M51.13.7.375.104		\$ 55.38	/
9	TAILGATE SPOILER BLIND RIVET <i>/ MC</i>	3	B51.24.8.226.003		\$ 15.81	/
10	REAR EMBLEM "MINI" <i>x MM</i>	1	M51.14.7.026.186		\$ 79.11	X
11	COOPER LETTERING <i>/ MC</i>	1	M51.14.2.755.617		\$ 71.24	/
12	REAR FOG LIGHT <i>? x MM</i>	1	M63.24.6.946.904		\$ 173.36	X
13	REAR BUMPER SPOILER SENSOR GASKET <i>/ MC</i>	4	B66.20.9.283.203		\$ 26.52	/
14	TAILGATE <i>/ ON</i>	1	M41.00.7.320.545		\$ 1,368.19	/
TOTAL PARTS					\$ 3,587.39	
					\$ -	
TOTAL PARTS COST					\$ 3,587.39	

Labour Description

1	TO REPLACE TAILGATE AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>840</i>			<i>1260</i>	\$ 1,900.00	
2	TO RESPRAY TAILGATE AND REAR BUMPER. <i>810</i>			<i>1600</i>	\$ 1,800.00	
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			<i>150</i>	\$ 250.00	
4	TO TRANSFER THE TAILGATE MECHANISM.			<i>420</i>	\$ 500.00	
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			NETT	\$ 560.00	/
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			NETT	\$ 120.00	/

7	TO TRANSFER THE REVERSE SENSORS.	420 ✓	\$	500.00
8	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	\$	70.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 ✓	\$	250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250 ✓	\$	350.00
11	SUNDRIES.	NETT 70 ✓	\$	50.00


Xnn

TOTAL LABOUR	\$	-	\$	6,350.00
TOTAL PARTS	\$	-	\$	3,587.39
TOTAL	\$	-	\$	9,937.39
LESS EXCESS	\$	-	\$	-
TOTAL AFTER EXCESS	\$	-	\$	-
GST 7%	\$	-	\$	-
GRAND TOTAL	\$	-	\$	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.


 Steve (LKK)
 83228813
 Steve.chm@lkk auto.com

wtl PL
 29/1/20, 11:30am
 5 days
 P/P
 PL PL sy

John Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



ERGO INSURANCE PTE. LTD.		NAME : Ms Nor'Aini Binte Ahmad		WIP : 33624	
5 TEMASEK BOULEVARD		ADDRESS :		EXCESS :	
#04-01 SUNTEC TOWER FIVE				DATE: 23-Jan-20	
SINGAPORE 038985					
ATTN. : MOTOR CLAIMS		TEL : MR. ABDUL RASHID BI BUDIN @ 84289208			
FAX :					
VEH NO :	SDM65Y	DATE IN :		CONTACT PERSON :	JOB THOMAS 6331 0682
CHASSIS NO :	WMWXM520402G37040	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER	DATE REG.:	15-Jun-17	POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	M51.12.7.380.009	\$ -	\$ 947.12
2	REAR BUMPER SPOILER	1	M51.12.7.380.015	\$ -	\$ 274.43
3	REAR BUMPER SPOILER CHROME	1	M51.12.7.365.737	\$ 103.35	\$ 103.35
4	TAILGATE CHROME	1	M51.13.7.362.121	\$ -	\$ 253.76
5	TAILGATE SPOILER SUPPORT	1	M51.62.7.337.600	\$ 32.70	\$ 32.70
6	REAR WINDSCREEN STRIP	1	M51.13.7.320.540	\$ 131.04	\$ 131.04
7	REAR WINDSCREEN MOUNT LH	1	M51.13.7.302.545	\$ 55.38	\$ 55.38
8	REAR WINDSCREEN MOUNT RH	1	M51.13.7.375.104	\$ 55.38	\$ 55.38
9	TAILGATE SPOILER BLIND RIVET	3	B51.24.8.226.003	\$ 15.81	\$ 15.81
10	REAR EMBLEM "MINI"	1	M51.14.7.026.186	\$ -	\$ 79.11
11	COOPER LETTERING	1	M51.14.2.755.617	\$ 71.24	\$ 71.24
12	REAR FOG LIGHT	1	M63.24.6.946.904	\$ -	\$ 173.36
13	REAR BUMPER SPOILER SENSOR GASKET	4	B66.20.9.283.203	\$ 26.52	\$ 26.52
14	TAILGATE	1	M41.00.7.320.545	\$ 1,368.19	\$ 1,368.19
TOTAL PARTS				\$ 1,859.61	\$ 3,587.39
					\$ -
TOTAL PARTS COST				\$ 1,859.61	\$ 3,587.39
Labour Description					
1	TO REPLACE TAILGATE AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,260.00	\$ 1,900.00
2	TO RESPRAY TAILGATE AND REAR BUMPER.			\$ 1,600.00	\$ 1,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 150.00	\$ 250.00
4	TO TRANSFER THE TAILGATE MECHANISM.			\$ 420.00	\$ 500.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			\$ 560.00	\$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			\$ 120.00	\$ 120.00

7 *	TO TRANSFER THE REVERSE SENSORS.	\$ 420.00	\$ 500.00
8	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	\$ -	\$ 70.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 250.00	\$ 350.00
11	SUNDRIES.	\$ 20.00	\$ 50.00
	TOTAL LABOUR	\$ 4,950.00	\$ 6,350.00
	TOTAL PARTS	\$ 1,859.61	\$ 3,587.39
	TOTAL	\$ 6,809.61	\$ 9,937.39
	LESS EXCESS	\$ -	\$ -
	TOTAL AFTER EXCESS	\$ 6,809.61	
	GST 7%	\$ 476.67	\$ -
	GRAND TOTAL	\$ 7,286.28	\$ -

NUMBER OF DAYS: 5 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



















...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2020 14:03 Edit Reg		24 Jan 2020 00:00 Edit Adj Rpt	S\$6,809.61 Edit Estimates	S\$6,809.61 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: NOR'AINI BINTE AHMED , ID: S7204041D									
Vehicle Reg. No.: SDM65Y		Date of Loss: 18/01/2020 14:00 - :59 [31 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBJ6246S		Policy No. (Claimant):							
		Excess:							
Repairer: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609042 West Coast - Tel: 6331 0680									
Handling Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 05/02/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDM65Y
 [GBJ6246S]
 TP
 NOR'AINI BINTE AHMED
 Jan 18 2020 2:00PM
 [-]
 Trans Eurokars Pte Ltd - Tanjong Penjuru

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/20 14:16	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
2	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/01/20 18:21	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
5	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/01/20 18:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
8	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/01/20 18:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	17/02/20 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20001476/ESD3E2

Date: 19/02/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SDM65Y

Insured Vehicle No : GBJ6246S

Date of Loss: 18/01/2020

Nature of Claim: TP

Claim No: CDMCG20000130

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDM65Y**

Make & Model: MINI COOPER, 1.5 HATCHBACK 3DR LED DSC (A)

Engine No: 39919952B38A15A

Reg. Date: 15/06/2017 (Man. Year: 2017)

Chassis No: WMWXM520402G37040

Colour: Green

Odometer: 30995 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,707.39	1,879.61	1,827.78	49.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,230.00	4,930.00	1,300.00	20.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,937.39	6,809.61	3,127.78	31.47
+ GST 7.00/7.00% (S\$)	695.62	476.67	218.95	31.48
Nett Amount (S\$)	10,633.01	7,286.28	3,346.73	31.47

INSPECTION

Date of Assignment: 24/01/2020

Date Inspected: 29/01/2020 Inspected At:

Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2020)
Parts:	144	MINI COOPER 1.5 HATCHBACK 3DR LED DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDM65Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	947.12 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	274.43 FS	*- FS
3	1		*REAR BUMPER SPOILER CHROME	Broken	103.35 FS	*103.35 FS
4	1		*TAILGATE CHROME	Not Necessary	253.76 FS	*- FS
5	1		*TAILGATE SPOILER SUPPORT	Necessary	32.70 FS	*32.70 FS
6	1		*REAR WINDSCREEN STRIP	Necessary	131.04 FS	*131.04 FS
7	1		*REAR WINDSCREEN MOUNT LH	Necessary	55.38 FS	*55.38 FS
8	1		*REAR WINDSCREEN MOUNT RH	Necessary	55.38 FS	*55.38 FS
9	3		*TAILGATE SPOILER BLIND RIVET	Necessary	15.81 FS	*15.81 FS
10	1		*REAR EMBLEM MINI	Not Necessary	79.11 FS	*- FS
11	1		*COOPER LETTERING	Necessary	71.24 FS	*71.24 FS
12	1		*REAR FOG LIGHT	Not Necessary	173.36 FS	*- FS
13	4		*REAR BUMPER SPOILER SENSOR GASKET	Necessary	26.52 FS	*26.52 FS
14	1		*TAILGATE	Dented	1,368.19 FS	*1,368.19 FS
15	1		*NUMBER PLATE WITH CASING	Not Necessary	70.00 FS	*- FS
16	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,707.39	1,879.61
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE TAILGATE AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,900.00	1,260.00
2	TO RESPRAY TAILGATE AND REAR BUMPER	New	1,800.00	1,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
4	TO TRANSFER THE TAILGATE MECHANISM	New	500.00	420.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS	New	560.00	560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS	New	120.00	120.00
7	TO TRANSFER THE REVERSE SENSORS	New	500.00	420.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	250.00
Gross Labour Cost (S\$)			6,230.00	4,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >