

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 March 2020 3:34 PM
To: 'Hafizul Farhan RAHMAT (SPF)'; Reports (LKKAuto)
Cc: Cui Fen ENG (SPF); Frankie THAY (SPF); SUR
Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Hafizul,

Items listed below had been checked and discovered no damage.

Front door inner trim board RH (item is serviceable, not necessary to replace)



Front door power window channel RH (item is serviceable, not necessary to replace)



Front door power window channel weatherstrip RH (item is serviceable, not necessary to replace)



Front door power window motor RH and
Front door power window regulator RH
(item is serviceable, not necessary to replace)



Front door weatherstrip RH (item is serviceable, not necessary to replace)



Front top arm RH (item is serviceable, not necessary to replace)



Steering rack & pinion (item is serviceable, not necessary to replace)



Front tyre RH (item is serviceable, not necessary to replace)



For Front door rubber guide stopper RH and Front door seal rivet no photos

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>

Sent: Tuesday, 3 March 2020 9:42 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Reports (LKKAuto) <report@lkkauto.com>

Cc: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>

Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Veron,

As spoken with your surveyor, Guo Xian, can you put in writing that the items listed below had been checked and discovered no damage.

(example)

Front door inner trim board RH (item is serviceable, not necessary to replace)



Best Regards,

Hafizul Farhan Bin Rabmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Tel: 6842 8429
Police Logistics Department | [Singapore Police Force](#)



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 28 February 2020 5:21 PM
To: Reports (LKKAUTO) <report@lkkauto.com>; Hafizul Farhan RAHMAT (SPF) <[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>
Cc: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Hafizul,

Refer items photos.



Front door inner trim board RH



Front door power window channel RH




Front door power window channel weatherstrip RH



Front door power window motor RH and
Front door power window regulator RH



Front door weatherstrip RH



Front top arm RH



Steering rack & pinion



Front tyre RH

For Front door rubber guide stopper RH and Front door seal rivet no photos

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 21 February 2020 5:24 PM

To: Reports (LKKAuto) <report@lkkauto.com>; 'Hafizul Farhan RAHMAT (SPF)'

<[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>

Cc: 'Cui Fen ENG (SPF)' <ENG_Cui_Fen@spf.gov.sg>; 'Frankie THAY (SPF)' <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>

Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Hafizul,

According to surveyor's the below items no damaged during PRS and also TP survey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Reports (LKKAuto) <report@lkkauto.com>

Sent: Wednesday, 19 February 2020 9:56 AM

To: 'Hafizul Farhan RAHMAT (SPF)' <Hafizul_Farhan_RAHMAT@spf.gov.sg>

Cc: 'Cui Fen ENG (SPF)' <ENG_Cui_Fen@spf.gov.sg>; 'Frankie THAY (SPF)' <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>

Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Hafizul,

Thank you for the email.

Dear Veron,

Kindly assist. Our ref.: [CS3/SPF19003101/Gvd3e2-1](#)

Best Regards,

ELAINE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

From: Hafizul Farhan RAHMAT (SPF) [mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg]

Sent: Wednesday, 19 February 2020 9:48 AM

To: Elaine (LKK Auto)

Cc: Cui Fen ENG (SPF); Frankie THAY (SPF); 'SUR'

Subject: RE: Survey Report & Invoice of Vehicle SDR 828L

Dear Elaine,

Thank you for the re-survey report.

However we need a detailed explanation of why any of the items stated below should not be replaced.

FRONT DOOR INNER TRIM BOARD RH
FRONT DOOR MECHANISM LOCK RH
FRONT DOOR WINDOW CHANNEL RH
FRONT DOOR POWER WINDOW CHANNEL RH
FRONT DOOR POWER WINDOW CHANNEL WEATHERSTRIP RH
FRONT DOOR POWER WINDOW MOTOR RH
FRONT DOOR POWER WINDOW REGULATOR RH
FRONT DOOR RUBBER GUIDE STOPPER RH
FRONT DOOR WEATHERSTRIP RH
FRONT TOP ARM RH
STEERING RACK & PINION

FRONT TYRE RH(SN)
FRONT DOOR SEAL RIVET (SN)

Thank you.

Best Regards,

Hafizul Farhan Bin Rabmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Tel: 6842 8429
Police Logistics Department | [Singapore Police Force](#)



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Elaine (LKK Auto) <report@lkkauto.com>
Sent: Tuesday, 18 February 2020 4:06 PM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Cc: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; 'SUR' <sur@lkkauto.com>
Subject: Survey Report & Invoice of Vehicle SDR 828L

Dear Sir / Madam,

Enclose Survey Report of SDR 828L.

Thank you.

Best Regards,

ELAINE | Reports
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,