

REF: CS/CTI/20001573/TLVd3 ⁿ²

Special Extension:

Investor: Tanfik

ASSIGNMENT (Office)

From (Person): Ben. Tang of CTI Date/Time: 29/1/2020 @ 12.01pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SMA 8198B Insured: SMK 572D

at Workshop m/s Cycle & Carriage Industries Tel: 83320062

of 188 Pandan Loop

Policy No: _____ Claim No: SNM20D200512/SMK572D/BEN

Sum insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/01/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS ^(wp)

H.O.D. Endorsement: _____

Date/Time: 12.05pm @ 29/1/2020 Person Contacted: Vincent Vehicle IN (OUT)

Date/Time	Action/Instruction	Estimate	✓
	<u>SMA 8198B - X</u>		
	<u>SMK 572D - X</u>		
<u>31/3/20</u>	<u>@ 5.03pm Vincent said vehicle no repair.</u>		
<u>1/4/20</u>	<u>Submit preli report</u>		

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 29 January 2020 12:01 PM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM20D200512/SMK572D/BEN & YOUR REF: SMA8198B -PRS & DIRECT SETTLEMENT

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMA8198B.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Sent: Wednesday, January 29, 2020 11:51 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200512/SMK572D/BEN & YOUR REF: SMA8198B -PRS & DIRECT SETTLEMENT

Morning Ben

LKK FOR SURVEY

Kindly revert liability

TKS

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401

From: Ben Tang [<mailto:Ben.Tang@sg.entaiping.com>]
Sent: Wednesday, 29 January 2020 11:30 AM
To: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Cc: Claims Dept of CTI <claimsdept@sg.entaiping.com>
Subject: RE: OUR REF: SNM20D200512/SMK572D/BEN & YOUR REF: SMA8198B -PRS & DIRECT SETTLEMENT

This email was sent from outside of your organisation

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 29 January 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: Claims Dept of CTI

Sent: Wednesday, January 29, 2020 11:24 AM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; vincent.seah@cyclecarriage.com.sg

Subject: OUR REF: SNM20D200512/SMK572D/BEN & YOUR REF: SMA8198B -PRS & DIRECT SETTLEMENT

Dear Ben,

Please conduct PRS-SMA8198B soonest possible.

Officer In Charge- Ben Tang-DID : 6389 6175.

Dear Vincent,

*** kindly quote our reference number when replying.***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: Vincent Seah <vincent.seah@cyclecarriage.com.sg>

Sent: Tuesday, January 28, 2020 6:26 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: SMA8198B/SMK572D= DIRECT SETTLEMENT

TO : CHINA TAIPING

Accident Claim Dept.

RE: Accident involving motor vehicle nos. SMA8198B & SMK572D along CHOA CHU KANG BLK 234 OPEN CARPARK , Accident date: 23.01.2020

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SMA8198B), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SMK572D) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at vincent.seah@cyclecarriage.com.sg

Regards

Vincent Seah
Cycle & Carriage Industries Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel: 8332 0062 (H/P)
Fax: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 26 March 2020 3:18 PM
To: Vincent Seah
Subject: RE: SMA 8198B-DOA: 23/1/2020

Dear Vincent,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Sent: Thursday, 5 March 2020 9:57 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SMA 8198B-DOA: 23/1/2020

Morning Vernon

Case not clear by China Taiping. No repair done

Tks

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 27 February 2020 4:23 PM
To: Vincent Seah <vincent.seah@cyclecarriage.com.sg>
Subject: SMA 8198B-DOA: 23/1/2020

This email was sent from outside of your organisation

Dear Vincent,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2020 15:04
Date Of Accident	23/01/2020 20:50
Exact Location Of Accident	CHOA CHU KANG CENTRAL BLK 234 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA8198B
Insured/Policyholder	
Name Of Registered Owner	CHUA TIAN TENG
NRIC No	SXXXX812G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96165338
Alternative Phone No	OFFICE-96165338

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29120860QMY
Cover Note Number	

Driver

Name of Driver	CHUA BEE LING PAULINE
NRIC No	SXXXX324F
Date Of Birth	07/01/1981
Occupation	INDOOR
Date Of Driving Pass	28/01/1992
Driving Experience	27 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96608198
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	4 HILLVIEW CRESCENT
Postcode	669429
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY CAR WAS PARKED WAITING A LOT OF CHOA CHU KANG CENTRAL BLK 234 OPEN CARPARK. CAR B (SMK572D) WAS REVERSING INTO OPP. LOT WHILE DOING SO HIS CAR HIT INTO MY CAR RIGHT REAR PORTION. I DID HAD AN OPERATION ON 7 JAN 2020.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK572D
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A: SMA 8188B

B: 5ML-5720



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

waiting a lot

My vehicle was parked ~~in~~ of close du key central Bille 234 open car park. Vehicle 5ML-5720 was ~~was~~ reversing into opp lot, while doing so his vehicle hit into my vehicle SMA 8188B right rear portion.

I did had an operation on 07/01/2020.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Vincent Scallan
 Vincent Scallan & Carriage Hubertson (Pty) Ltd
 010 111 1101
 Body Care & Repair Center Fax: 082 2077
 Body Care & Repair Center Fax: 082 2077
 Email: vincent.scallan@vscallan.com

Policyholder's Signature

Date & Time 28/01/2020
12:35PM

Driver's Signature

(if driver is not the policyholder)
Date & Time 28/01/2020
12:35PM

Reporting Centre Person's

Name:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time 28/01/2020
12:35PM

Driver's Signature

(if driver is not the policyholder)

Date & Time 28/01/2020
12:35PM

Reporting Centre Personnel

Name:

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4401 / 8332 0062 Fax: 6771 1272
Email: vincent.seah@cyclicarriage.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-85001111X

ESTIMATE FOR SMA8198B

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 41017
Reg No/Reg Date SMA8198B / 18/04/2018
Date In/Mileage / 0
Chassis No WDD2050402R367787
Engine No 27491031259899
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian Bl/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/01/2020/ 18:07	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : A291208600MY // 23.01.2020 DRIVE IN/EXCESS : 28.01.2020 // TP CAR NO: SMK5720-CHINA TAIPING DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	✓ 380.00
A BPILAB REMOVE & REPLACE ON REAR BUMPER, RHR FENDER				1920 2400.00
A BPIRES RESPRAY ON REAR BUMPER, RHR FENDER				1200 1800.00
M REAR BUMPER	1.00	1643.61	00.00	Rv 1643.61
M RIVET	4.00	4.59	00.00	an * 18.36

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Signature
7/2/20 @ 11:30
Taufik 97495469
wp
sur@lkkauto.com
taufik@lkkauto.com
4 days
Review after repair

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary works must be resurveyed and is subject to final approval from insurance Company
Acknowledged by Repairer
Signature:

Confirmed & accepted by

Nett 6,241.97
7% GST on 6241.97 436.94
Total Payable 6,678.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8385
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001573/T1VD3N2
Date: 01/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30346019000
 Claimant Vehicle No: SMA8198B Insured Vehicle No: SMK572D
 Date of Loss: 23/01/2020 Nature of Claim: TP Claim No: SNM20D200512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA8198B**
 Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491031259899
 Reg. Date: 18/04/2018 (Man. Year: 2017) Chassis No: WDD2050402R367787
 Colour: Black Odometer: 24441 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,661.97	0.00	1,661.97	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	3,500.00	1,080.00	23.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,241.97	3,500.00	2,741.97	43.93
+ GST 7.00/7.00% (S\$)	436.94	245.00	191.94	43.93
Nett Amount (S\$)	6,678.91	3,745.00	2,933.91	43.93

INSPECTION

Date of Assignment: 10/02/2020
 Date Inspected: 07/02/2020 Inspected At: 188 PANDAN LOOP
 SINGAPORE 128378
 REPAIRER: CYCLE & CARRIAGE INDUSTRIES
 (1986) PL
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2020)**Parts:** M1-COUPE MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMA8198B)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,643.61 FS	*- FS
2	4		*RIVET	Not Necessary	18.36 FS	*- FS
Total Parts (S\$)					1,661.97	0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE & REPLACE ON REAR BUMPER,RHR FENDER	New	2,400.00	1,920.00
3	RESPRAY ON REAR BUMPER,RHR FENDER	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			4,580.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >