

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2020 Sendback Est	30 Jan 2020 13:17 S\$10,902.63	30 Jan 2020 13:34 Edit Adj Rpt	S\$9,868.43 Edit Estimates	S\$9,868.43 View Rpt		Pending for Survey Report Cancel Case
	28 May 2020 09:46 Sendback Est	28 May 2020 09:54 S\$396.05	28 May 2020 09:54 Assign			Combine Suppl.	New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **SABRINA CHUA WAN KIANG**, ID: S1767543E, Tel: +6597310708, Email: NOEMAIL

Vehicle Reg. No.:	SJU64L	Date of Loss:	27/01/2020 16:00 - :59 [84 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 20/20/20/VP05/022967	Policy/Cover Note No.:	Z20VP05025636 (Comprehensive)
		Excess:	S\$500.00

Repairer: **Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110

Handling Insurer: **Lonpac Insurance Bhd (HQ)** - Tel: +65 62507388 ... [Handled by **Gerald Poh** - 6250 7388 ext 240]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... [Final Rpt due 10/02/2020]

Driver/Custodian: SABRINA CHUA WAN KIANG (53 / Female) , NRIC: S1767543E, Tel: +6597310708 Email: NOEMAIL

Adj Asg. Remarks: SURVEY & REVERT

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- LONPAC_HQ (04/02/2020): **Alert - Adj Mandate Approved (S\$10662.62) - SJU64L - Claim Handler: Gerald Poh**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJU64L (20/20/20/VP05/022967)
OD
Jan 27 2020 4:00PM
[SABRINA CHUA WAN KIANG]
Lai Huat (Meng Kee) Motor Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>		View <input type="button" value="View in Browser"/>		
Assessment Reports		1 per page <input type="button" value=""/>		
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	30/01/20 13:17	Repairer Estimates		Load HTM
2	28/05/20 09:54	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 09:29	Adjuster Immediate Advice		Load HTM
2	03/02/20 09:53	Adjuster Immediate Advice		Load HTM
Photos/Images		3 per page <input type="button" value=""/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 09:35	General View		Load JPG <input checked="" type="checkbox"/>
2	31/01/20 09:35	General View		Load JPG <input checked="" type="checkbox"/>
3	31/01/20 09:35	General View		Load JPG <input checked="" type="checkbox"/>
4	31/01/20 09:35	General View		Load JPG <input checked="" type="checkbox"/>
5	31/01/20 09:35	General View		Load JPG <input checked="" type="checkbox"/>
6	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
7	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
8	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
9	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
10	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
11	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
12	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
13	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
14	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
15	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
16	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
17	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
18	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
19	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
20	31/01/20 09:36	General View		Load JPG <input checked="" type="checkbox"/>
21	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
22	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
23	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
24	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
25	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
29	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
30	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
31	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
32	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
33	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	03/09/20 15:02	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
Documentation				
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	1 per page	<input checked="" type="checkbox"/>
1	30/01/20 13:16	E-filed GIA report	Load PDF	
2	30/01/20 13:16	Driver's NRIC & Driving Licence	Load PDF	
3	30/01/20 13:16	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 09:33	ESTIMATE	Load PDF	
2	03/02/20 09:39	ESTMATE	Load PDF	
3	08/09/20 09:09	PARTS INVOICE	Load PDF	
4	08/09/20 09:09	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/01/20 16:16	Accident Statement	Load HTM	
Photos/Images				
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	3 per page	<input checked="" type="checkbox"/>
1	29/01/20 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	29/01/20 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	29/01/20 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	29/01/20 16:15	CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>
Documentation				
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	1 per page	<input checked="" type="checkbox"/>
1	29/01/20 15:20	Sketch Plan	Load TIF	
2	29/01/20 15:20	Identification Card	Load TIF	
3	29/01/20 15:20	Driving License	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20001635/KYD3S2**Date:** 08/09/2020**REFERENCE**

Insured/Claimant: SABRINA CHUA WAN KIANG Policy No: Z20VP05025636
Date of Loss: 27/01/2020 Nature of Claim: OD Claim No: 20/20/20/VP05/022967

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU64L**
Make & Model: BMW 640I, 3.0 Convertible M Sport (A) Engine No: 09358354N55B30A
Reg. Date: 21/01/2013 (Man. Year: 2012) Chassis No: WBALW72080DK15603
Colour: Metallic Black Odometer: 72324 km
Engine Capacity: 2979 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 ZR19 Rear Tyre Size: 275/35 ZR19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,392.63	8,348.43	1,044.20	11.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	1,020.00	-160.00	-18.60
Paintwork Labour	650.00	500.00	150.00	23.08
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,902.63	9,868.43	1,034.20	9.49
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	10,402.63	9,368.43	1,034.20	9.94
+ GST 7.00/7.00% (S\$)	728.18	655.79	72.39	9.94
Nett Amount (S\$)	11,130.81	10,024.22	1,106.59	9.94

INSPECTION

Date of Assignment: 30/01/2020 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 30/01/2020 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$9,868.42

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2020)
Parts: 143	BMW 640I 3.0 Convertible M Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU64L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Cracked	1,180.00 F	*1,180.00 F
2	1		*Front headlamp LH	Mtg Cracked	3,350.00 F	*3,350.00 F
3	1		*Front headlamp panel LH	Damaged	100.00 F	*100.00 F
4	1		*Front fender LH	Cracked	730.00 F	*730.00 F
5	1		*Front fender inner shield LH	Distorted	100.00 F	*100.00 F
6	3		*Front fender inner shield rivets LH	Necessary	10.50 F	*10.50 F
7	1		*Front shock absorber LH	Necessary	1,400.00 F	*950.00 F
8	1		*Front control arm LH	Distorted	330.00 F	*330.00 F
9	1		*Front lower arm LH	Damaged	310.00 F	*310.00 F
10	1		*Front knuckle arm LH	Serviceable	450.00 F	*- F
11	1		*Front stabilizer bar link LH	Bent	72.00 F	*72.00 F
12	1		*Engine side cover LH	Serviceable	135.00 F	*- F
13	1		*FRONT BUMPER LOWER CORNER COVER LH	Cracked	-	*35.00 F
14	1		*FRONT FENDER INNER SHIELD LH (REAR PORTION)	Cracked	-	*92.00 F

F=Franchise part.

Sub Total (S\$)	8,167.50	7,259.50
+ Margin on L,N Items 15.00/15.00% (S\$)	1,225.13	1,088.93
Total Parts (S\$)	9,392.63	8,348.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	To spray paint	New	650.00	500.00
Labour Items				
2	Towing fee (4-wheel)	New	150.00	150.00
3	To check wheel alignment (computerised)	New	80.00	60.00
4	To check/clear fault codes	New	80.00	80.00
5	To straighten front body, to dismantle + renew of parts	New	550.00	480.00
6	LABOUR TO PROGRAM EDCSVL DAMPER SATELITE, FRONT LEFT.	New	-	250.00
			Gross Labour Cost (\$\$)	1,510.00
				1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >